E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Inspector: Matthew Vanicek		E&A - P2008.19			Stage			
		Kiltera Villas @ Waterford NER111205						
Drainet Name								
Project Name:								
For Week Ending:		6/13/2020						
Project Location:		144th and Ida Streets- Omaha, NE (Douglas County)						
Grading:	100%	,						
Sanitary Sewer:	100%							
Storm Sewer:	100%							
Paving: Seeding:	100%		_					
Utilities:	100%							
Overall Development:	97%							
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Inspection Time				
	2.000				Week			
Sunday: Monday	0.00"							
Tuesday	0.00"							
Wednesday	0.08"							
Thursday	0.00"	5/14/2020	72/55 Cloudy	9:30 AM				
Friday	0.00" 0.26"							
Saturday	0.26				Week			
Sunday:	0.05"				week .			
Monday	0.00"							
Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.03"							
Friday	0.08"							
Saturday	0.00"				Weels			
Sunday:	0.83"				Week			
Monday	0.12"	5/25/2020	67/61 Cloudy	8:15 AM				
Tuesday	0.86"	5/26/2020	67/60 Scattered Showers	3:15 PM				
Wednesday	0.01"							
Thursday	0.00"							
Friday Saturday	0.00" 0.00"							
Saturday	0.00				Week			
Sunday:	0.03"							
Monday	0.01"							
Tuesday Wednesday	0.00" 0.01"							
Thursday	0.01"							
Friday	0.00"							
Saturday	0.00"							
Our days	0.00"				Week !			
Sunday: Monday	0.00" 0.00"							
Tuesday	0.79"							
Wednesday	0.03"	6/10/2020	75/56 Sunny	8:35 AM				
Thursday	0.00"							
Friday	0.00" 0.00"							
Saturday	μ.υυ			1				
	None							
Complaints:								
			1					
Construction Sequencing:			L					

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013).

#### Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

Is dust associated with the construction activity adequately controlled on the site?

Create Corrective Action?

N/A

### Comments:

The site was inactive during the last inspection. One vacant lot remains.

# Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1. No maintenance is required at this time.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
Lot 10	Silt Fence	Lot 10	9/25/2018	Active	No		
Current Condition:	Good Condition - Landmark Homes repaired the silt fence at the back of the lot and installed silt fence along the						
	front of the lot prior to the inspection on 5/20/19. E&A repaired the silt fence during the inspection on 2/27/20.						
Lot 23	Individual Lot	Lot 23		Removed			
Current Condition:	Removed - Landmark Homes sodded the lot prior to the inspection on 5/20/19.						
		N41d11m34s					
STR	Streets	W96d12m23s	8/28/2008	Active	No		
Current Condition:	Good Condition- Landmark Homes cleaned the streets prior to the inspection on 11/27/18.						
SWPPP Sign	SWPPP Sign	1 sign	10/27/2008	Active	No		
Current Condition:	Good Condition-						
	Installed on 10-27-08 on 156th and Potter						

Hette Van Inspector Signature:

Reviewed By:

But Su