

E & A Consulting Group, Inc.  
 10909 Mill Valley Road, Suite 100  
 Omaha, NE 68154  
 tel 402.895.4700  
 fax 402.895.3599  
 www.eacg.com



**E & A CONSULTING GROUP, INC.**  
*Engineering Answers*

Zachary A. Jilek, CPESC, CISEC  
 Environmental Services Dept. Manager

**E&A - P2008.194.000**

Inspector: Matthew Vanicek		Stage
Project Name:	<b>Kiltera Villas @ Waterford NER111205</b>	3
For Week Ending:	<b>8/8/2020</b>	
Project Location:	<b>144th and Ida Streets- Omaha, NE (Douglas County)</b>	<b>68007</b>

Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	97%			

RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Inspection Time	
					<b>Week 1</b>
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.02"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.09"				
					<b>Week 2</b>
Sunday:	0.00"				
Monday	0.42"				
Tuesday	0.15"				
Wednesday	0.00"	7/22/2020	83/63 Overcast	9:00 AM	
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					<b>Week 3</b>
Sunday:	0.16"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.10"				
Friday	0.00"				
Saturday	0.12"				
					<b>Week 4</b>
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.20"				
Thursday	0.05"				
Friday	0.00"				
Saturday	0.00"				
					<b>Week 5</b>
Sunday:	N/A	N/A			
Monday	N/A	N/A			
Tuesday	N/A	N/A			
Wednesday	N/A	N/A			
Thursday	N/A	N/A			
Friday	N/A	N/A			
Saturday	N/A	N/A			

Complaints:	None			
Construction Sequencing:				

**Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?**

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

**Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :**

Entire Site, grading was completed prior to taking this project over on 8/28/2008. Entire Site; McArdle completed regarding of the lots 12-18 along 155th Street as of 6/2011.

**What temporary or permanent stabilization measures listed in this section are being implemented?**

Existing vegetation / Sod (8-2008), seed on S.B.'B' (removed basin) (4/09), Lots 11-18 was re-seeded (6/2011) Lots 12, 13, 14 were sodded (10/5/2013).

**Checklist Questions:**

**Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?**

Yes

**Create Corrective Action?**

N/A

**Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.**

Yes

**Create Corrective Action?**

N/A

**Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?**

Yes

**Create Corrective Action?**

N/A

**Are construction entrances and adjacent streets being maintained adequately?**

Yes

**Create Corrective Action?**

N/A

**Is dust associated with the construction activity adequately controlled on the site?**

Yes

**Create Corrective Action?**

N/A

**Comments:**

**Comments:**


The site was inactive during the last inspection. One vacant lot remains. **E&A has submitted the NOT as of 8/11/20.**

**Findings / Corrective Actions (Date):**

**Findings / Corrective Actions (Date):**

1. No maintenance is required at this time.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
Lot 10	Silt Fence	Lot 10	9/25/2018	Active	No
<b>Current Condition:</b>	Good Condition - Landmark Homes repaired the silt fence at the back of the lot and installed silt fence along the front of the lot prior to the inspection on 5/20/19. E&A repaired the silt fence during the inspection on 2/27/20.				
Lot 23	Individual Lot	Lot 23		Removed	
<b>Current Condition:</b>	Removed - Landmark Homes sodded the lot prior to the inspection on 5/20/19.				
STR	Streets	N41d11m34s W96d12m23s	8/28/2008	Active	No
<b>Current Condition:</b>	Good Condition- Landmark Homes cleaned the streets prior to the inspection on 11/27/18.				
SWPPP Sign	SWPPP Sign	1 sign	10/27/2008	Active	No
<b>Current Condition:</b>	Good Condition- Installed on 10-27-08 on 156th and Potter				

Inspector Signature: 

Reviewed By: 