	P20	08.194.000				
Inspector: Phillip Dechant			Stage			
Project Name:	Ki	Kiltera Villas @ Waterford				
•		9/13/2008				
For Week Ending:		9/13/2008				
Grading:	100%	6				
Sanitary Sewer:	100%	-				
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	40%					
	,					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected				
			Week			
Sunday:	0.00"					
Monday	0.40"					
Tuesday	0.00"	09/09/08				
Wednesday	0.00"	1 1				
Thursday	1.29"					
Friday	0.27"	09/12/08				
Saturday	0.01"					
Complaints:	None	one				
Construction Sequencing:						
Which portion(s) (i.e. drainage basins) of in the last 14 days?	the site have had a temp	orary or permanent cessation of grading, e	arthwork, or ground disturban			
Entire Site, grading was completed	prior to taking this pro	oject over on 8/28/2008.				
Which portion(s) (i.e. drainage basins) of	the site do not have grac	ling, earthwork, or ground disturbance sch	eduled in the next 14 days? :			
Entire Site, grading was completed	prior to taking this pro	oject over on 8/28/2008.				
What temporary or permanent stabilizatio	n measures listed in this	section are being implemented?	1			
Existing vegetation / Sod (8-2008)						
Comments:						
Comments:						
Site Idle with existing homes						
Findings / Corrective Actions (Da	te):					
Findings / Corrective Actions (Da	te):					
1) See BMP section for required ma	intenance					

			Projected Install			
Unique Name	Туре	Location	Date	Status	Maintance	
	Construction	N41d11m25s				
CE 1	Entrance	W96d12m40s		Removed	No	
Current Condition:	Construction Ent	Construction Entrance paved prior to first inspection on 8/28/08.				
	Sediment	N41D11M27				
S.B. B	Basin	w96D12M23S	8/28/2008	Active	Yes	
Current Condition:	Good condition:	15% filled				
	Inspector to pain	t doopout marks on ris	or at payt inspection	Due to rains, now	completion data of	
	ASAP	t cleanout marks on ris N41d11m34s	ser at next inspection.		completion date of	
S.F.			ser at next inspection.	Due to rains, new o	completion date of No	
S.F. Current Condition:	ASAP Silt Fence	N41d11m34s				
Current Condition: ST 1	ASAP Silt Fence Silt fence remove Sediment Trap	N41d11m34s W96d12m23s ed prior to inspection c N41d11m34s W96d12m23s				
Current Condition:	ASAP Silt Fence Silt fence remove	N41d11m34s W96d12m23s ed prior to inspection o N41d11m34s W96d12m23s rfall and pond	on 8-28-08	Removed	No	
Current Condition: ST 1	ASAP Silt Fence Silt fence remove Sediment Trap	N41d11m34s W96d12m23s ed prior to inspection c N41d11m34s W96d12m23s	on 8-28-08	Removed	No	
Current Condition: ST 1 Current Condition:	ASAP Silt Fence Silt fence remove Sediment Trap Permanent water Streets	N41d11m34s W96d12m23s ed prior to inspection of N41d11m34s W96d12m23s rfall and pond N41d11m34s	n 8-28-08 8/26/2008 8/28/2008	Removed Removed	No	

Current Condition:	Not installed		
	Sign needs to be installe	ed	
	Inspector to order and in	nstall ASAP	
Inspector Signature:	FREIST	Reviewed By:	Zachany K. Jild