E&A - P2004.045.000								
Inspector: Mike Jacobson	Stage							
Project Name:	Me	ridian Park	3					
For Week Ending:	•							
. c. 110011 <u></u>								
Grading:	100%							
Sanitary Sewer:	87%							
Storm Sewer:	87%							
Paving:	85%							
Seeding: Utilities:	100%							
Overall Development:	20%							
		<u> </u>	1					
RAIN FALL AMOUNTS	Amount in inches	Date inspected						
O	0.00	1	Week 1					
Sunday: Monday	0.00"							
Tuesday	0.00"							
Wednesday	0.06"							
Thursday	0.08"							
Friday	0.04"							
Saturday	0.00"							
	lo orii		Week 2					
Sunday:	0.01"							
Monday	0.03" 0.00"	01/22/08						
Tuesday Wednesday	0.00	01/22/08						
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
			Week 3					
Sunday:	0.00"							
Monday	0.01"							
Tuesday	0.01"							
Wednesday	0.00"							
Thursday Friday	0.00"							
Saturday	0.00"							
Jaturday	0.00		Week 4/5					
Sunday:	0.03"							
Monday	0.00"							
Tuesday	0.17							
Wednesday	0.10"							
Thursday	0.00"							
Friday	0.00"	02/08/08						
Saturday	0.00"							
	None							
Complaints:	110110							
Construction Sequencing			Construction and an arrangement					
disturbance in the last 14 days		orary or permanent cessa	tion of grading, earthwork, or ground					
-	eted and site seeded Summer	/Fall 2005						
Limito Ono, grading comple	noa ana ono oceaea caminen	1 dil 2000.						
	basins) of the site do not have grad	ding, earthwork, or ground	d disturbance scheduled in the next					
14 days? :								
Enitre Site, grading comple	eted and site seeded Summer	/Fall 2005.						
What temporary or permanent	stabilization measures listed in this	s section are being implem	nented?					
What temporary or permanent stabilization measures listed in this section are being implemented?  Site seeded Fall 2005 & 5/2007, stabilized entrances installed Summer 2005, Re-Seed 5/2007 by Geis								
One secucu rall 2000 & 3/.	2001, Stabilized Elitratices Ilis	taneu Summer 2005, F	NO-OCCU DIZUUT DY GCIS					
Comments:								

## Comments:

Home construction remains active on site at this time. School construction is active in sediment basin G area. Majority of site has good vegetative cover.

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):

1) No required maintenance in the BMP section.

			Projected			Description of	
Unique Name	Туре	Location	Install Date	Status	Maintenance	Maintenance/Activity:	
·							
a		N41d00m00s				Repairs	
CE A	Construction Entrance	W96d00m00s	<u> </u>	Removed		Needed/Planned:	
Current Condition:	Entrance Paved		T	Γ	1	ļ	
		N41d00m00s					
SB E	Sediment Basin	W96d00m00s	07/01/05	Active	No	ļ	
Current Condition:		Good Condition- 9% Filled -Cleaned/ Erosion Maintenance 5/2007 by Dave Hausman					
	-Cleaned/ Erosion Maintena						
00.5	On diverged Bankin	N41d00m00s	07/04/05	A - (*	NI-		
SB F	Sediment Basin	W96d00m00s	07/01/05	Active	No	•	
Current Condition:	Good Condition- 16% filled.						
	Cleaned 9/2006.	NI44-10000-	T	Γ	1	ļ	
SB G	On diverged Bankin	N41d00m00s	00/00/05	A - (*	NI-		
	Sediment Basin	W96d00m00s	08/26/05	Active	No	<u> </u>	
Current Condition:	Good Condition- 12% Filled						
	-Cleaned 5/2007 by Dave H			T	1	•	
a	o =	N41d00m00s					
SF A	Silt Fence	W96d00m00s	07/19/05	Removed		•	
Current Condition:	Removed		1	Т	1	<u> </u>	
		N41d00m00s					
SF B	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed - Not needed due						
		N41d00m00s					
SF C	Silt Fence	W96d00m00s	07/01/05	Active	No		
Current Condition:	Good Condition						
	-Maintenanced 11/1/07 by Tim Geis.						
		N41d00m00s					
ST A	Silt Trap	W96d00m00s		Removed		_	
Current Condition:	Trap Closed June 2006.						
		N41d14m44s					
STR	Streets	W96d12m59s	8/10/2007	Active	No		
Current Condition:	Good Condition - No major :	signs of track off.					
Inonastaria Cianat	Natural Jawlan		Reviewed By:	Zadrany k.	1 July		
Inspector's Signature:	home Lange		Reviewed By:		J	Ţ	