E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manager E&A CONSULTING GROUP, INC. ENGINEERING • PLANNING • FIELD SERVICES

Inspector: Mike Jacobson, C	ISEC				Stage	
inspector: mike bacobson, o		Meridia	n Dork		2	
Project Name:		NER1	10696			
For Week Ending:		5/12/	2012			
Project Location:	168th	168th & Giles Street- Omaha, NE (Sarpy County)				
	10011	a ones offeet on		oounty)	68136	
Grading:		100%				
Sanitary Sewer:		90%				
Storm Sewer:		90%				
Paving:		90%				
Seeding:		100%				
Utilities:		65%				
Overall Development:		20%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	ł			
					Week	
Sunday:	0.11"					
Monday	0.00"					
Tuesday	0.84"					
Wednesday	0.16"	05/02/12				
Thursday	0.12"	<mark>05/03/12</mark>				
Friday	0.02"	05/04/12				
Saturday	0.00"					
					Week	
Sunday:	0.80"	<mark>05/06/12</mark>				
Monday	0.00"					
Tuesday	0.00"	05/08/12				
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				Meet	
Sunday	N/A	N/A			Week	
Sunday: Monday	N/A	N/A				
Tuesday	N/A	N/A				
Wednesday	N/A	N/A				
Thursday	N/A	N/A				
Friday	N/A	N/A				
Saturday	N/A	N/A				
	I -					
	None					
Complaints:						
Construction Sequencing:						
Which portion(s) (i.e. drainage basin	s) of the site have had a temporal	ry or permanent cessati	ion of grading, earth	work, or ground dis	turbance in the last 14 days?	
Entire Site, grading completed	and site seeded Summer/Fa	dl 2005.				
Entire Site, grading was comple	eted in Replat Three area Lo	ts 1-54 prior to insp	ection on 10/5/11	by Double D.		
Which portion's) (i.e. drainage basin	s) of the site do not have grading.	, earthwork, or ground o	disturbance schedul	led in the next 14 day	ys?	
Entire Site, grading completed	and site seeded Summer/Fa	ıll 2005.				
	eted in Replat Three area Lo	ots 1-54 prior to insp	ection on 10/5/11	by Double D.		
Entire Site, grading was compl				-	<u> </u>	
Entire Site, grading was comple		<u></u>	ented?			
	ization measures listed in this see	ction are being implement				
What temporary or permanent stabil			Re-Seed 5/2007 P	v Geis Sedimen	t Basin E area seeded	
What temporary or permanent stabil Site seeded Fall 2005 & 5/2003	7, stabilized entrances install	led Summer 2005, F				
What temporary or permanent stabil Site seeded Fall 2005 & 5/200 (9/2008); Areas around where I	7, stabilized entrances install handicap ramps were installe	led Summer 2005, F ed was re-seeded (4	l/2009); Sedimen			
What temporary or permanent stabil Site seeded Fall 2005 & 5/2003	7, stabilized entrances install handicap ramps were installe	led Summer 2005, F ed was re-seeded (4	l/2009); Sedimen			
What temporary or permanent stabil Site seeded Fall 2005 & 5/200 (9/2008); Areas around where I	7, stabilized entrances install handicap ramps were installe	led Summer 2005, F ed was re-seeded (4	l/2009); Sedimen			

A few homes are under construction along Meridian Street.

## Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date): 1) Some maintenance is required in the BMP section.

Projected Unique Name Location Install Date Status Maintenance Туре N41d00m00s W96d00m00s Construction Entrance Removed **Current Condition:** Entrance Paved Along 164th CW Concrete Washout Pit Street Removed **Current Condition:** Concrete washout was removed prior to inspection on 7/12/11 by Jeff w/ Hearthstone Production. Along 165th 7/12/2011 CW 1 Concrete Washout Pit Active Street No **Current Condition:** Good Condition-Washout pit was replaced and the construction debris was cleaned up prior to inspection on 10/19/11 by Jeff w/ Hearthstone Production. Meridian Park Replat three Lots Silt Fence POD A Removed This POD is being removed from the report and the silt fence was moved to BMP SF 1, SF 2 and SF 3 **Current Condition:** as of inspection on 5/8/12 POD B Silt Fence Lots 63-73 Removed **Current Condition:** Silt fence is no longer needed due to the all lots being sodded in this pod prior to inspection on 6/3/10 by Chris w/ Hearthstone Production. POD C Lots 97-122 Silt Fence Removed **Current Condition:** Silt fence is no longer needed due to the all lots being sodded in this pod prior to inspection on 10/5/11 by Jeff w/ Hearthstone Production. POD D Lots 123-162 Silt Fence Removed **Current Condition:** Silt fence is no longer needed due to the all lots being sodded in this pod prior to inspection on 10/5/11 by Jeff w/ Hearthstone Production. POD E Silt Fence Lots 163-199 Removed **Current Condition:** Silt fence installed on the back of lot 175 was removed prior to inspection on 9/29/10 by Chris w/ Hearthstone Production due to the lot being sodded. All the homes in this pod have been completed. 4/16/2011 POD F Silt Fence Lots 209-217 Active Yes **Current Condition:** Good Condition- Silt fence installed on the back lots or the back of the lots 209-212 and lot 217. Lot 216 needs silt fence installed on the back of the lot. Lot 210 needs a silt fence check installed on the front of the lot. Silt fence needs to be added in the Southeast corner of the lot. Hearthstone was informed to complete maintenance by 4/22/12. Maintenance was completed prior to nspection on 5/2/12 by CS for Hearthstone. Lots 11-14 along 5/2/2012 POD E Silt Fence Meridian Street Active Yes Current Condition: Good Condition-Additional silt fence needs to be installed on the front of lots 12 and 13. The Home company was informed to complete maintenance by 5/9/12. Maintenance was completed prior to inspection on 5/8/12 by The Home company. N41d00m00s Sediment Basin W96d00m00s Removed SB E **Current Condition:** Basin was removed due to lot development prior to inspection on 6/12/08 by Double D Excavating. N41d00m00s SB F Sediment Basin W96d00m00s Removed **Current Condition:** As of inspection on 5/12/11 the basin has been filled in by Double D Excavating. N41d00m00s SB G Sediment Basin 08/26/05 W96d00m00s Active No Current Condition: Good Condition- 15% Filled Partially Cleaned out and baffle repaired prior to inspection on 10/12/10 by Bob Roth. N41d00m00s SF A Silt Fence W96d00m00s 07/19/05 Removed

Current Condition:	Removed						
		N41d00m00s					
SF B Current Condition:	Silt Fence Removed - Not needed d	W96d00m00s	etative cover in a	Removed			
ourient condition.		N41d00m00s					
SF C	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed - Not needed o	due to established vege	etative cover in a	area.			
		Meridian Park					
SF 1 Current Condition:	Silt Fence	Replat Lot 1	5/4/2010	Active	Yes		
Current Condition:	Fair Condition- Silt fence Maintenance was completed						
	Maintenance was completed prior to inspection on 5/2/12 by CS for Hearthstone. Lot was seeded prior to inspection on 5/2/12 by CS for Hearthstone.						
	Additional silt fence needs to be added on the Southside of the lot to help prevent run off. Commercial Seeding was informed to complete maintenance by 5/14/12.						
		Meridian Park					
		Replat Lots 26,					
SF 2	Silt Fence	27	5/4/2010	Active	Yes		
Current Condition:	Fair Condition- Silt fence						
	Maintenance was completed prior to inspection on 5/2/12 by CS for Hearthstone.						
	Lot was seeded prior to inspection on 5/2/12 by CS for Hearthstone.						
	One area of silt fence on						
	26 are undermined and full and it needs to be cleaned out and backfilled and compacted.						
	Commercial Seeding was	s informed to complete	maintenance by	y 5/14/12.			
		Meridian Park Replat Lots 46,					
SF 3	Silt Fence	47	5/4/2010	Active	Yes		
Current Condition:	Fair Condition- Silt fence	is installed on the Eas	t side of the lots				
	Maintenance was completed prior to inspection on 5/2/12 by CS for Hearthstone.						
	Lot was seeded prior to inspection on 5/2/12 by CS for Hearthstone.						
	One area of silt fence on lot 47 is undermined and full and it needs to be cleaned out and backfilled						
	and compacted.						
	Commercial Seeding was	s informed to complete	maintenance by	y 5/14/12.			
<b>27</b> A	011 T	N41d00m00s					
ST A Current Condition:	Silt Trap Trap Closed June 2006.	W96d00m00s		Removed			
Current Condition:	Trap Closed Julie 2000.	N41d00m00s					
ST B	Sediment Trap	W96d00m00s		- ·			
Current Condition:	Sediment trap was remove			Removed			
		ved prior to inspection	on 10/5/11 due		he area by Double D.		
		ved prior to inspection	on 10/5/11 due		he area by Double D.		
		N41d00m00s	on 10/5/11 due	to re-grading of t	ne area by Double D.		
ST C	Sediment Trap	N41d00m00s W96d00m00s		to re-grading of to Removed			
ST C Current Condition:	Sediment Trap	N41d00m00s W96d00m00s		to re-grading of to Removed			
		N41d00m00s W96d00m00s ved prior to inspection		to re-grading of to Removed			
Current Condition:	Sediment trap was remov	N41d00m00s W96d00m00s ved prior to inspection N41d00m00s		to re-grading of t Removed to re-grading of t			
		N41d00m00s W96d00m00s ved prior to inspection N41d00m00s W96d00m00s	on 10/5/11 due	Removed Removed to re-grading of t	he area by Double D.		
Current Condition: ST D	Sediment trap was remov	N41d00m00s W96d00m00s ved prior to inspection N41d00m00s W96d00m00s	on 10/5/11 due	Removed Removed to re-grading of t	he area by Double D.		
Current Condition: ST D	Sediment trap was remov	N41d00m00s W96d00m00s ved prior to inspection N41d00m00s W96d00m00s ved prior to inspection North of Replat	on 10/5/11 due	Removed Removed to re-grading of t	he area by Double D.		
Current Condition: ST D Current Condition:	Sediment trap was remov Sediment Trap Sediment trap was remov	N41d00m00s W96d00m00s ved prior to inspection N41d00m00s W96d00m00s ved prior to inspection North of Replat three Lots 1 and	on 10/5/11 due - on 10/5/11 due -	to re-grading of t Removed to re-grading of t Removed to re-grading of t	he area by Double D.		
Current Condition: ST D Current Condition: ST 1	Sediment trap was remov Sediment Trap Sediment trap was remov Sediment Trap	N41d00m00s W96d00m00s ved prior to inspection N41d00m00s W96d00m00s ved prior to inspection North of Replat three Lots 1 and 2	on 10/5/11 due	Removed Removed to re-grading of t	he area by Double D.		
Current Condition: ST D Current Condition:	Sediment trap was remov Sediment Trap Sediment trap was remov	N41d00m00s   W96d00m00s   ved prior to inspection   N41d00m00s   W96d00m00s   ved prior to inspection   North of Replat three Lots 1 and 2   ad	on 10/5/11 due on 10/5/11 due 10/5/2011	Removed to re-grading of t to re-grading of t Removed to re-grading of t Active	he area by Double D.		
Current Condition: ST D Current Condition: ST 1	Sediment trap was remov Sediment Trap Sediment trap was remov Sediment Trap Good Condition- 5% Fille	N41d00m00s   W96d00m00s   ved prior to inspection   N41d00m00s   W96d00m00s   ved prior to inspection   North of Replat three Lots 1 and 2   ad	on 10/5/11 due on 10/5/11 due 10/5/2011	Removed to re-grading of t to re-grading of t Removed to re-grading of t Active	he area by Double D.		
Current Condition: ST D Current Condition: ST 1 Current Condition:	Sediment trap was remov Sediment Trap Sediment trap was remov Sediment Trap Good Condition- 5% Fille Sediment trap is installed	N41d00m00s W96d00m00s ved prior to inspection N41d00m00s w96d00m00s ved prior to inspection North of Replat three Lots 1 and 2 d prior to inspection on Southeast corner of Replat three	on 10/5/11 due on 10/5/11 due 10/5/2011 10/5/11 by Doul	to re-grading of t Removed to re-grading of t Removed to re-grading of t Active	he area by Double D. he area by Double D. No		
Current Condition: ST D Current Condition: ST 1 Current Condition:	Sediment trap was removed Sediment Trap Sediment trap was removed Sediment Trap Good Condition- 5% Fille Sediment trap is installed Sediment Trap	N41d00m00s W96d00m00s ved prior to inspection N41d00m00s W96d00m00s ved prior to inspection North of Replat three Lots 1 and 2 ed prior to inspection on Southeast corner of Replat three lot 1	on 10/5/11 due on 10/5/11 due 10/5/2011	Removed to re-grading of t to re-grading of t Removed to re-grading of t Active	he area by Double D.		
Current Condition: ST D Current Condition: ST 1 Current Condition:	Sediment trap was remov Sediment Trap Sediment trap was remov Sediment trap was remov Sediment Trap Good Condition- 5% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille	N41d00m00s   W96d00m00s   ved prior to inspection   N41d00m00s   W96d00m00s   ved prior to inspection   North of Replat three Lots 1 and 2   domon to inspection on Southeast corner of Replat three lot 1	on 10/5/11 due : on 10/5/11 due : 10/5/2011 10/5/11 by Doul	to re-grading of t Removed to re-grading of t Removed to re-grading of t Active	he area by Double D. he area by Double D. No		
Current Condition: ST D Current Condition: ST 1 Current Condition:	Sediment trap was removed Sediment Trap Sediment trap was removed Sediment Trap Good Condition- 5% Fille Sediment trap is installed Sediment Trap	N41d00m00s   W96d00m00s   ved prior to inspection   N41d00m00s   W96d00m00s   ved prior to inspection   North of Replat three Lots 1 and 2   d prior to inspection on Southeast corner of Replat three lot 1   ed d prior to inspection on	on 10/5/11 due : on 10/5/11 due : 10/5/2011 10/5/11 by Doul	to re-grading of t Removed to re-grading of t Removed to re-grading of t Active	he area by Double D. he area by Double D. No		
Current Condition: ST D Current Condition: ST 1 Current Condition:	Sediment trap was remov Sediment Trap Sediment trap was remov Sediment trap was remov Sediment Trap Good Condition- 5% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille	N41d00m00s   W96d00m00s   ved prior to inspection   N41d00m00s   W96d00m00s   ved prior to inspection   North of Replat three Lots 1 and 2   d   southeast corner of Replat three lot 1   ad   prior to inspection on Southeast corner of Replat three lot 1   ad   prior to inspection on Northeast corner	on 10/5/11 due : on 10/5/11 due : 10/5/2011 10/5/11 by Doul	to re-grading of t Removed to re-grading of t Removed to re-grading of t Active	he area by Double D. he area by Double D. No		
Current Condition: ST D Current Condition: ST 1 Current Condition: ST 2 Current Condition:	Sediment trap was removed Sediment Trap Sediment trap was removed Sediment Trap Good Condition- 5% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment trap is installed	N41d00m00s   W96d00m00s   ved prior to inspection   N41d00m00s   W96d00m00s   ved prior to inspection   North of Replat three Lots 1 and 2   domon to inspection on Southeast corner of Replat three lot 1   ed d prior to inspection on Northeast corner of Replat three	on 10/5/11 due on 10/5/11 due 10/5/2011 10/5/11 by Doul 10/5/2011	to re-grading of t Removed to re-grading of ti Removed to re-grading of ti Active ble D. Active	he area by Double D. he area by Double D. he area by Double D. No		
Current Condition: ST D Current Condition: ST 1 Current Condition:	Sediment trap was remov Sediment Trap Sediment trap was remov Sediment trap was remov Sediment Trap Good Condition- 5% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille	N41d00m00s   W96d00m00s   ved prior to inspection   N41d00m00s   W96d00m00s   ved prior to inspection   North of Replat three Lots 1 and 2   d prior to inspection on Southeast corner of Replat three lot 1   ed d prior to inspection on   Northeast corner of Replat three lot 26	on 10/5/11 due : on 10/5/11 due : 10/5/2011 10/5/11 by Doul	to re-grading of t Removed to re-grading of t Removed to re-grading of t Active	he area by Double D. he area by Double D. No		
Current Condition: ST D Current Condition: ST 1 Current Condition: ST 2 Current Condition:	Sediment trap was removed Sediment Trap Sediment trap was removed Sediment trap was removed Sediment Trap Good Condition- 5% Fille Sediment trap is installed Sediment Trap Good Condition- 6% Fille Sediment trap is installed Sediment Trap	N41d00m00s   W96d00m00s   ved prior to inspection   N41d00m00s   w96d00m00s   ved prior to inspection   North of Replat three Lots 1 and 2   d prior to inspection on Southeast corner of Replat three lot 1   ed d prior to inspection on Northeast corner of Replat three lot 26	on 10/5/11 due on 10/5/11 due 10/5/2011 10/5/2011 10/5/2011 10/5/11 by Dou	to re-grading of t Removed to re-grading of t Removed to re-grading of t Active ble D. Active ble D. Active	he area by Double D. he area by Double D. he area by Double D. No		

		North of Replat three Lots 27 and					
ST 4	Sediment Trap	28	10/5/2011	Active	No		
Current Condition:	Good Condition- 7% Filled						
	Sediment trap is installed prior to inspection on 10/5/11 by Double D.						
		Southeast corner					
		of Replat three					
ST 5	Sediment Trap	lot 27	10/5/2011	Active	No		
Current Condition:	Good Condition- 6% Filled						
	Sediment trap is installed prior to inspection on 10/5/11 by Double D.						
		Northeast corner of Replat three					
ST 6	Sediment Trap	lot 46	10/5/2011	Active	No		
Current Condition:	Good Condition- 5% Filled						
	Sediment trap is installed prior to inspection on 10/5/11 by Double D.						
		N41d14m44s					
STR	Streets	W96d12m59s	8/10/2007	Active	Yes		
Current Condition:	Fair Condition-						
	Streets was cleaned up prior to inspection on 5/2/12 by CS.						
	Due to the recent rains there is some minor signs of run off along Cary Street and Virginia Street and it needs to be cleaned up.						
	Lesson and a faile data fations						
	Inspector failed to inform anyone to cleaned streets. On 5/7/12 inspector informed Commercial Seeding to cleaned streets ASAP for Hearthstone.						
				A 11			
SWPPP Sign	SWPPP Sign	Two signs on site	3/28/2008	Active	No		
Current Condition:	Good Condition On 3/28/08 a SWPPP sign was installed at 164th & Giles and 168th & Meridian St. entrance.						
Inspector Signature:	I Jawlow			Reviewed By:	Zachany K. Jilik		