E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



## Engineering Answers

| nspector: Patrick Sechser                 | =3A                                    | P2004.045.00        | -                       |                     |                        |  |
|---|--|---------------------|-------------------------|---------------------|------------------------|--|
|   |  |                     |                         |                     | Stage                  |  |
|   |  | Moridian            | Park                    |                     | 3                      |  |
|   |  | Meridian Park       |                         |                     |                        |  |
| Project Name:                             |  | NER1106             |                         |                     |                        |  |
| or Week Ending:                           |  | 12/13/20            | 14                      |                     |                        |  |
| Project Location:                         | 168th & Gile                           | es Street- Omaha    | a, NE (Sarpy Coun       | tv)                 | 68136                  |  |
|   |  |                     |                         | ,,                  |                        |  |
| Grading:                                  | 1009                                   | 6                   |                         |                     |                        |  |
| anitary Sewer:                            | 100%                                   |                     |                         |                     |                        |  |
| otorm Sewer:                              | 100%                                   | -                   |                         |                     |                        |  |
| Paving:                                   | 1009                                   |                     |                         |                     |                        |  |
| Seeding:                                  | 1009                                   |                     |                         |                     |                        |  |
| Itilities:                                | 70%                                    |                     |                         |                     |                        |  |
| overall Development:                      | 52%                                    | 6                   |                         |                     |                        |  |
|   |  | 1                   | 1                       |                     |                        |  |
| AIN FALL AMOUNTS                          | Amount in tenths                       | Date inspected      |                         |                     |                        |  |
|   | 0.00                                   |                     |                         |                     | Wee                    |  |
| Sunday:                                   | 0.00"                                  |                     | -                       |                     |                        |  |
| londay<br>Wasday                          | 0.00"                                  |                     |                         |                     |                        |  |
| uesday<br>Vednesday                       | 0.00"                                  |                     |                         |                     |                        |  |
| hursday                                   | 0.00"                                  | 1                   |                         |                     |                        |  |
| riday                                     | 0.00"                                  |                     |                         |                     |                        |  |
| Saturday                                  | 0.00"                                  |                     | 1                       |                     |                        |  |
|   |  |                     |                         |                     | Wee                    |  |
| unday:                                    | 0.00"                                  |                     |                         |                     |                        |  |
| londay                                    | 0.00"                                  |                     |                         |                     |                        |  |
| uesday                                    | 0.00"                                  |                     |                         |                     |                        |  |
| Vednesday                                 | 0.00"                                  |                     |                         |                     |                        |  |
| hursday                                   | 0.00"                                  |                     |                         |                     |                        |  |
| riday                                     | 0.00"                                  |                     |                         |                     |                        |  |
| Saturday                                  | 0.00"                                  |                     |                         |                     |                        |  |
|   | 0.00                                   |                     |                         |                     | Wee                    |  |
| Sunday:<br>Nonday                         | 0.00"                                  |                     |                         |                     |                        |  |
| luesday                                   | 0.00"                                  |                     |                         |                     |                        |  |
| Vednesday                                 | 0.00                                   |                     |                         |                     |                        |  |
| hursday                                   | 0.00"                                  |                     |                         |                     |                        |  |
| riday                                     | 0.00"                                  |                     |                         |                     |                        |  |
| Saturday                                  | 0.00"                                  |                     |                         |                     |                        |  |
| ,   |  |                     |                         |                     | Wee                    |  |
| Sunday:                                   | 0.00"                                  |                     |                         |                     |                        |  |
| londay                                    | 0.00"                                  | 12/01/14            | 23/14 Sunny             |                     |                        |  |
| uesday                                    | 0.00"                                  |                     |                         |                     |                        |  |
| Vednesday                                 | 0.00"                                  |                     |                         |                     |                        |  |
| hursday                                   | 0.00"                                  |                     |                         |                     |                        |  |
| riday                                     | 0.00"                                  |                     |                         |                     |                        |  |
| aturday                                   | 0.00"                                  |                     |                         |                     |                        |  |
| Sunday:                                   | 0.00"                                  |                     |                         |                     | Wee                    |  |
| londay:                                   | 0.00"                                  | 1                   | +                       |                     |                        |  |
| londay                                    | 0.00<br>0.03"                          | 1                   |                         |                     |                        |  |
| Vednesday                                 | 0.00"                                  |                     |                         |                     |                        |  |
| hursday                                   | 0.00"                                  | 1                   | -                       |                     |                        |  |
| riday                                     | 0.00"                                  |                     |                         |                     |                        |  |
| Saturday                                  | 0.00"                                  |                     |                         |                     |                        |  |
|   | · ·                                    |                     |                         | . I                 |                        |  |
| Complaints:                               | None                                   |                     |                         |                     |                        |  |
|   |  |                     |                         |                     |                        |  |
| Construction Sequencing:                  | I                                      | 1                   |                         | []                  |                        |  |
| hich portion(s) (i.e. drainage basins) of | of the site have had a temporary or pe | rmanent cessation o | f grading, earthwork, c | r ground disturbanc | e in the last 14 days? |  |
| /   |  |                     |                         |                     |                        |  |
| ntire Site, grading completed and         | d site seeded Summer/Fall 2008         | 5.                  |                         |                     |                        |  |

| Which portion's) (i.e. drainage basins) of the  | site do not have grading, earthwo   | rk, or ground disturba | ance scheduled in th | e next 14 days? |   |
|---|-------------------------------------|------------------------|----------------------|-----------------|---|
| Entire Site, grading completed and site   | e seeded Summer/Fall 2005.          |                        |                      |                 |   |
| Entire Site, grading was completed in   | Replat Three area Lots 1-54         | prior to inspection    | on 10/5/11 by Do     | ouble D.        |   |
|   |                                     |                        |                      |                 |   |
| What temporary or permanent stabilization m   | neasures listed in this section are | being implemented?     |                      |                 |   |
| Site seeded Fall 2005 & 5/2007, stabil<br>(9/2008); Areas around where handica<br>Replat three lots 1-54 was seeded (10 | p ramps were installed was          | re-seeded (4/2009)     | ); Sediment basir    |                 |   |
|   |                                     |                        |                      |                 |   |
| Comments:   | •                                   | •                      | •                    | •               | • |
|   |                                     |                        |                      |                 |   |

**Comments:** Home construction is active in various areas of the development as of the last inspections.

## Note: Commerial Development is occurring to the west of the school and is part of Ehrart Griffins SWPPP. Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1.) Some maintenance is required in the BMP section.

|                    |  | 1                                  | Projected          |                     |                    |  |  |
|--------------------|--|------------------------------------|--------------------|---------------------|--------------------|--|--|
| Unique Name        | Туре   | Location                           | Install Date       | Status              | Maintenance        |  |  |
| Unique Name        | Type   | Location                           | instan Date        | Otatus              | Maintenance        |  |  |
|                    |  | N41d00m00s                         |                    |                     |                    |  |  |
| CE A               | Construction Entrance  | W96d00m00s                         |                    | Removed             |                    |  |  |
| Current Condition: | Entrance Paved   |                                    |                    |                     |                    |  |  |
|                    |  | Along 164th                        |                    |                     |                    |  |  |
| CW                 | Concrete Washout Pit   | Street                             |                    | Removed             |                    |  |  |
| Current Condition: | Concrete washout was rem   |                                    | ction on 7/12/11 b |                     | stone Production.  |  |  |
|                    |  |                                    |                    |                     |                    |  |  |
|                    |  | Along 165th                        |                    |                     |                    |  |  |
| CW 1               | Concrete Washout Pit   | Street                             |                    | Removed             |                    |  |  |
| Current Condition: | Concrete washout was rem   | oved prior to inspe                | ction on 10/8/12 t | by CS.              |                    |  |  |
|                    |  |                                    |                    |                     |                    |  |  |
| CW 2               | Concrete Washout Pit   | Lot 35 Replat 3                    |                    | Removed             |                    |  |  |
| Current Condition: | Removed-   | Lot 00 Replat 0                    |                    | Removed             |                    |  |  |
|                    | Concrete washout pit was r   | emoved for pending                 | g excavation activ | vities prior to the | inspection on      |  |  |
|                    | 4/4/2014 by Celebrity Home   | es.                                | -                  | ·                   |                    |  |  |
|                    |  |                                    |                    |                     |                    |  |  |
| CW 3               | Concrete Washout Pit   | Lot 22                             | 4/4/2014           | Active              | No                 |  |  |
| Current Condition: | Good condition-Celebrity H   | omes cleaned out t                 | he washout pit pi  | rior to the inspec  | tion on 9/11/2014. |  |  |
|                    |  |                                    |                    |                     |                    |  |  |
| Lot 182            | Silt Fence   | Lot 182 along<br>Greenfield Street | 12/8/2014          | Pending             | Yes                |  |  |
| Current Condition: | Pending-   | Creenneid Offeet                   | 12/0/2014          | rending             | 105                |  |  |
|                    |  |                                    |                    |                     |                    |  |  |
|                    | 1.) PP needs to be staked  | down.                              |                    |                     |                    |  |  |
|                    | 2.) SF is needed on the side   | de and rear of the                 | lot due to the n   | ew excavation.      |                    |  |  |
|                    |  |                                    |                    |                     |                    |  |  |
|                    | 1.) Legacy Homes was informed to complete by 12/8/2014.<br>2.) Legacy Homes was informed to complete by 12/8/2014. |                                    |                    |                     |                    |  |  |
|                    | 2.) Legacy Homes was Inf   | ormed to complet                   | e by 12/8/2014.    |                     |                    |  |  |
|                    |  | Lot 183 along                      |                    |                     |                    |  |  |
| Lot 183            | Misc/other   | Greenfield Street                  |                    | Removed             |                    |  |  |
| Current Condition: | Removed- Lot was sodded by Legacy Homes prior to the inspection on 6/27/2014.                                      |                                    |                    |                     |                    |  |  |
|                    |  | Lot 241 along                      |                    |                     |                    |  |  |
| Lot 241            | Silt Fence   | Greenfield Street                  |                    | Removed             |                    |  |  |
| Current Condition: | Removed  | •                                  | •                  | •                   | •                  |  |  |
|                    | SF was removed from the lot due to the installation of sod in the back of the lot prior to the inspection          |                                    |                    |                     |                    |  |  |
|                    |  | Lot 242 along                      |                    |                     |                    |  |  |
| Lot 242            | Misc/other   | Greenfield Street                  |                    | Removed             |                    |  |  |
| Current Condition: | Removed-   |                                    |                    |                     |                    |  |  |
|                    | Lot was sodded by Celebrity Homes prior to 10/2/2013 inspection.   |                                    |                    |                     |                    |  |  |
|                    |  | Lot 243 along                      |                    |                     |                    |  |  |
| Lot 243            | Silt Fence   | Greenfield Street                  | 9/11/2013          | Active              | Yes                |  |  |
| =====              |  |                                    |                    |                     |                    |  |  |

| Current Condition:                     | Fair condition- Dirt was removed from the ROW prior to the inspection on 12/1/2014 by Lega<br>Homes.<br>SF in the front of the lot needs to be repaired as of 12/1/2014.<br>Legacy Homes was requested to repair the SF by 12/8/2014. |                          |                     |                     |                  |  |
|--|---|--------------------------|---------------------|---------------------|------------------|--|
|  |   |                          |                     |                     |                  |  |
|  |   |                          |                     |                     |                  |  |
| Current Condition:                     | Fair condition- Lot 270   |                          |                     |                     |                  |  |
|  | SF repair is needed on<br>exists as of 12/1/2014.<br>Legacy Homes was inf   |                          |                     | be installed in th  | e rear where     |  |
| Lot 303                                | Silt Fence  | Lot 303                  |                     | Removed             |                  |  |
| Current Condition:                     | Removed- Legacy Home  |                          | to the inspection   |                     | removed the      |  |
|  |   |                          |                     |                     |                  |  |
| Lot 304                                | Silt Fence  | Lot 304                  |                     | Removed             |                  |  |
| Current Condition:                     | Removed- Legacy Home  |                          | to the inspection   |                     | removed the      |  |
|  |   |                          |                     |                     |                  |  |
| Lot 305                                | Silt fence  | Lot 305                  |                     | Removed             |                  |  |
| Current Condition:                     | Removed- Lot was sodd   |                          | prior to the inspe  |                     | 4.               |  |
|  |   |                          |                     |                     |                  |  |
| Lot 306                                | Silt Fence  | Lot 306                  |                     | Removed             |                  |  |
| Current Condition:                     | Removed- Lot was sodd   | ed by Legacy Homes p     | prior to the inspe  | ction on 6/27/2014  | 4.               |  |
|  | <b>1 1 1 1</b>  |                          |                     |                     |                  |  |
| Lot 307<br>Current Condition:          | Misc/other<br>Removed-  | Lot 307                  |                     | Removed             |                  |  |
| ounon oonanon.                         | Lot was sodded prior to   | the inspection on 11/7/  | 2013 by Legacy      | Homes.              |                  |  |
|  |   | Along Meridian           |                     |                     |                  |  |
| Lot 51 Replat 2                        | Silt Fence  | Street                   | 40/00/00111         | Removed             | No               |  |
| Current Condition:                     | Removed- Lot was sodd   | ea prior to inspection o | on 10/02/2014 by    | Legacy Homes.       |                  |  |
|  |   | Along Meridian           |                     |                     |                  |  |
| Lot 54 Replat 2                        | Silt Fence  | Street                   |                     | Removed             |                  |  |
| Current Condition:                     | Removed- Lot was sodd   | ed by Legacy Homes p     | prior to the inspe  | ction on 8/7/2014.  |                  |  |
| Lata E2 Daplet 2                       | Silt Fence  | Lot 52 Replat 3          |                     | Removed             |                  |  |
| Lots 52 Replat 3<br>Current Condition: | Removed- SF was remo  |                          | ng stabilized by (  |                     | prior to the in: |  |
|  | on 4/29/2014.   |                          | 3                   |                     |                  |  |
|  |   |                          |                     |                     |                  |  |
| Lots 53 Replat 3<br>Current Condition: | Silt Fence  | Lots 53 Replat 3         | na otobiliza - bi ( | Removed             | vior to the in   |  |
| surrent Condition:                     | Removed- SF was remo<br>on 4/29/2014.   | wed due to the lots bell | ng stabilized by (  | Jelebnity Homes p   |                  |  |
| Lots 54 Replat 3                       | Silt Fence  | Lots 54 Replat 3         |                     | Removed             |                  |  |
| Current Condition:                     | Removed- SF was remo  |                          | ng stabilized by (  |                     | prior to the in  |  |
|  | on 4/29/2014.   |                          |                     |                     |                  |  |
| POD B                                  | Silt Fence  | Lots 63-73               |                     | Removed             |                  |  |
| Current Condition:                     | Silt fence is no longer ne  | eded due to the all lots | s being sodded ir   |                     | inspection or    |  |
|  | by Chris w/ Hearthstone   | Production.              |                     | T                   |                  |  |
| POD C                                  | Silt Fence  | Lots 97-122              |                     | Removed             |                  |  |
| Current Condition:                     | Silt fence is no longer ne<br>by Jeff w/ Hearthstone P  |                          | s being sodded ir   | n this pod prior to | inspection or    |  |
| POD D                                  | Silt Fence  | Lots 123-162             |                     | Removed             |                  |  |
| Current Condition:                     | Silt fence is no longer ne  |                          | s being sodded ir   |                     | inspection or    |  |
|  | by Jeff w/ Hearthstone P  | roduction.               | -                   |                     |                  |  |
| POD E                                  | Silt Fence  | Lots 163-199             | amoved prior to :   | Removed             | 10 by Chric      |  |
| Current Condition:                     | Silt fence installed on the Hearthstone Production  |                          |                     |                     |                  |  |
|  |   |                          |                     |                     |                  |  |
| POD F                                  | Silt Fence  | Lots 209-217             | 4/16/2011           | Active              | No               |  |

|                             |   | Г                                   |                     |                 |                          |  |  |
|-----------------------------|---|-------------------------------------|---------------------|-----------------|--------------------------|--|--|
|                             |   | Lots 51-56 along                    |                     |                 |                          |  |  |
| POD E                       | Silt Fence  | Meridian Street                     |                     | Removed         |                          |  |  |
| Current Condition:          | This silt fence is being mov  | ed to there on lot le               | evel BMP as of 9/   | 14/12.          |                          |  |  |
|                             |   | Lots 38-51                          |                     |                 |                          |  |  |
|                             |   | Meridian Park                       |                     |                 |                          |  |  |
| POD G<br>Current Condition: | Silt Fence<br>Fair condition-   | Replat Three                        | 4/10/2013           | Active          | Yes                      |  |  |
| Current Condition.          |   |                                     |                     |                 |                          |  |  |
|                             | 1.) Trash needs to be removed from the perimeter SF on lots 44-46.          |                                     |                     |                 |                          |  |  |
|                             | 2.) Overseeding needed o  |                                     |                     |                 |                          |  |  |
|                             | 3.) SF repair needed on lo  | ot 39 in th rear.                   |                     |                 |                          |  |  |
|                             | 1.) Celebrity Homes was i   | nformed to compl                    | ete maintenance     | e by 12/8/2014. |                          |  |  |
|                             | 2.) Celebrity Homes was i   |                                     |                     |                 |                          |  |  |
|                             | 3.) Celebrity Homes was i   | nformed to compl                    | ete maintenance     | e by 12/8/2014. |                          |  |  |
|                             |   | Lots 1-37                           |                     |                 |                          |  |  |
|                             |   | Meridian Park                       |                     |                 |                          |  |  |
| POD H                       | Silt Fence  | Replat Three                        | 10/2/2013           | Active          | Yes                      |  |  |
| Current Condition:          | Fair condition- Celebrity F<br>sidewalk, SF check is not                    |                                     |                     |                 |                          |  |  |
|                             | Sidewalk, of check is not   |                                     | as of the inspec    |                 |                          |  |  |
|                             | 1.) SF on the front of lot 34   |                                     |                     |                 |                          |  |  |
|                             | 2.) SF is down on the corr  |                                     |                     | ired.           |                          |  |  |
|                             | <ol> <li>Overseeding is needed</li> <li>Dirt piles need to be re</li> </ol> |                                     |                     |                 |                          |  |  |
|                             | 5.) SF is needed on the ea  |                                     |                     |                 |                          |  |  |
|                             | .,  |                                     |                     |                 |                          |  |  |
|                             | 1.) Celebrity Homes was re  |                                     | F by 10/22/2014.    | Not complete as | s of last inspection. CH |  |  |
|                             | was reminded again on 12  |                                     | ata hu 12/9/2014    |                 |                          |  |  |
|                             | 2.) Celebrity Homes was i<br>3.) Celebrity Homes was i                      |                                     |                     |                 |                          |  |  |
|                             | 4.) Celebrity Homes was i   |                                     |                     |                 |                          |  |  |
|                             | 5.) Celebrity Homes was i   | nformed to compl                    | ete by 12/8/2014    |                 |                          |  |  |
|                             |   |                                     |                     |                 |                          |  |  |
| SB E                        | Sediment Basin  | N41d00m00s<br>W96d00m00s            |                     | Removed         |                          |  |  |
| Current Condition:          | Basin was removed due to  |                                     | ior to inspection o |                 | ouble D Excavating.      |  |  |
|                             |   |                                     |                     |                 |                          |  |  |
|                             |   |                                     |                     |                 |                          |  |  |
|                             |   | N41d00m00s                          |                     |                 |                          |  |  |
| SB F                        | Sediment Basin  | W96d00m00s                          | filled in hy Deuk   | Removed         |                          |  |  |
| Current Condition:          | As of inspection on 5/12/11   | the basin has been                  | Thiled in by Doub   | D Excavating    |                          |  |  |
|                             |   | N41d00m00s                          | 1                   |                 |                          |  |  |
| SB G                        | Sediment Basin  | W96d00m00s                          | 08/26/05            | Active          | No                       |  |  |
| Current Condition:          | Good Condition- 25% Filled  |                                     |                     |                 |                          |  |  |
|                             | Partially Cleaned out and b   | affle repaired prior                | to inspection on '  | 10/12/10 by Bob | Roth.                    |  |  |
| <b>25</b> J                 | 011 5   | N41d00m00s                          | 07/10/05            | - ·             |                          |  |  |
| SF A<br>Current Condition:  | Silt Fence  | W96d00m00s                          | 07/19/05            | Removed         |                          |  |  |
| Current Condition.          | Removed   | N41d00m00s                          |                     |                 |                          |  |  |
| SF B                        | Silt Fence  | W96d00m00s                          |                     | Removed         |                          |  |  |
| Current Condition:          | Removed - Not needed due  |                                     | etative cover in a  | area.           |                          |  |  |
| SF C                        | Silt Fence  | N41d00m00s<br>W96d00m00s            |                     | Removed         |                          |  |  |
| Current Condition:          | Removed - Not needed due  |                                     | etative cover in a  |                 | <u> </u>                 |  |  |
|                             |   |                                     |                     |                 |                          |  |  |
|                             |   | Meridian Park                       |                     |                 |                          |  |  |
| SF 1                        | Silt Fence  | Replat 3 Lot 1                      |                     | Removed         |                          |  |  |
| Current Condition:          | Silt fence was removed price  | or to inspection on ?               | 12/4/12 by Dave I   | lausman/Celebr  | ity Homes.               |  |  |
|                             |   | Meridian Park                       |                     |                 |                          |  |  |
|                             |   | Replat 3 Lots 26,                   |                     |                 |                          |  |  |
| SF 2                        | Silt Fence<br>Silt fence was removed price                                  | 27                                  | 12/4/12 by Dava     | Removed         | ity Homes                |  |  |
| Current Condition:          | Circ rence was removed pric   | Meridian Park                       | Dave I              | ausman/Celebi   |                          |  |  |
|                             |   | Replat 3 Lots 46,                   |                     | Removed         |                          |  |  |
| 05.0                        | Cilt For  |                                     |                     |                 |                          |  |  |
| SF 3<br>Current Condition:  | Silt Fence<br>Silt fence was removed price                                  | 47<br>or to inspection on 2         | 12/4/12 hv Dave I   |                 | ity Homes                |  |  |
| SF 3<br>Current Condition:  | Silt Fence<br>Silt fence was removed pric                                   |                                     | 12/4/12 by Dave I   |                 | ity Homes.               |  |  |
| Current Condition:          | Silt fence was removed pric   | or to inspection on 7<br>N41d00m00s | 12/4/12 by Dave I   | Hausman/Celebr  | ity Homes.               |  |  |
|                             |   | or to inspection on ?               | 12/4/12 by Dave I   |                 | ity Homes.               |  |  |

|                            |  | N41d00m00s                          |                   |                     |                         |
|----------------------------|--|-------------------------------------|-------------------|---------------------|-------------------------|
| ST B                       | Sediment Trap                              | W96d00m00s                          |                   | Removed             |                         |
| Current Condition:         | Sediment trap was remove                   | ed prior to inspection              | n on 10/5/11 due  | to re-grading of t  | he area by Double D.    |
|                            |  | N144-100-m00a                       |                   |                     |                         |
| ST C                       | Sediment Trap                              | N41d00m00s<br>W96d00m00s            |                   | Removed             |                         |
| Current Condition:         | Sediment trap was remove                   |                                     | on 10/5/11 due    |                     | he area by Double D.    |
|                            | ·  |                                     |                   |                     |                         |
| OT D                       | On Frank Trees                             | N41d00m00s                          |                   | Description         |                         |
| ST D<br>Current Condition: | Sediment Trap<br>Sediment trap was remove  | W96d00m00s                          | on 10/5/11 due    | Removed             | he area by Double D     |
| Current Condition.         | Sediment trap was remove                   | a phor to inspection                |                   | to re-grading or t  | The area by Double D.   |
|                            |  | North of Replat                     |                   |                     |                         |
|                            |  | three Lots 1 and                    |                   |                     |                         |
| ST 1                       | Sediment Trap                              | 2                                   | 10/5/2011         | Active              | No                      |
| Current Condition:         | Good Condition- 23% Fille                  |                                     | 1                 | 1                   | 1                       |
|                            |  | Southeast corner                    |                   |                     |                         |
| ST 2                       | Sediment Trap                              | of Replat three<br>lot 1            | 10/5/2011         | Active              | No                      |
| Current Condition:         | Good Condition- 33% Fille                  |                                     | 10/3/2011         | Active              | No                      |
|                            |  |                                     |                   |                     |                         |
|                            |  | Northeast corner                    |                   |                     |                         |
|                            |  | of Replat three                     |                   |                     |                         |
| ST 3                       | Sediment Trap                              | lot 26                              |                   | Removed             |                         |
| Current Condition:         | This trap was installed price              |                                     |                   |                     |                         |
|                            | construction taking place ir built out.    | n the area. The trap                | will need to be r | einstalled prior to | o Replat 3 Lot 26 being |
|                            | built out.                                 |                                     |                   |                     |                         |
|                            |  | Between Replat                      |                   |                     |                         |
| 07 I                       | 0 1 1 7                                    | three Lots 26 and                   |                   |                     |                         |
| ST 4<br>Current Condition: | Sediment Trap<br>Good Condition- 20% Fille | 27                                  | 10/5/2011         | Active              | No                      |
| Current Condition:         | Good Condition- 20% Fille                  | u                                   |                   |                     |                         |
|                            |  | Southeast corner                    |                   |                     |                         |
|                            |  | of Replat three                     |                   |                     |                         |
| ST 5                       | Sediment Trap                              | lot 27                              |                   | Removed             |                         |
| Current Condition:         | This trap was installed price              |                                     |                   |                     |                         |
|                            | construction taking place in               | n the area. The trap                | will need to be r | einstalled prior to | o Replat 3 Lot 27 being |
|                            | built out.                                 | Neglisse                            | 1                 |                     |                         |
|                            |  | Northeast corner<br>of Replat three |                   |                     |                         |
| ST 6                       | Sediment Trap                              | lot 46                              |                   | Removed             |                         |
| Current Condition:         | This trap was installed price              |                                     | ce has been fille |                     | sewer and street        |
|                            | construction taking place ir built out.    |                                     |                   |                     |                         |
|                            |  | N41d14m44s                          | 1                 | 1                   |                         |
| STR                        | Streets                                    | W96d12m59s                          | 8/10/2007         | Active              | Yes                     |
| Current Condition:         | Fair condition-                            |                                     |                   |                     |                         |
|                            |  |                                     |                   |                     |                         |
|                            | Street cleaning needed in                  | n front of lot 271.                 |                   |                     |                         |
|                            |  |                                     |                   |                     |                         |
|                            | Legacy Homes was infor                     | med to complete b                   | y 12/2/2014.      |                     |                         |
| SWPPP Sign                 | SWPPP Sign                                 | Two signs on site                   | 3/28/2008         | Active              | No                      |
| Current Condition:         | Good Condition                             | e elgile en alte                    | 0,20,2000         |                     |                         |
|                            | On 3/28/08 a SWPPP sign                    | was installed at 164                | 4th & Giles and 1 | 68th & Meridian     | St. entrance.           |
|                            |  |                                     |                   |                     | Z+ / 1/2                |
| Inspector Signature:       | 25 Sul                                     |                                     |                   | Reviewed By:        | Zachany K. Jilek        |