E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Zachary A. Jilek, CPESC, CISE Environmental Services Dept.			Eng	ineering Answe	rs
Environmental Services Dept.		E&A - P2021.32	1.000		
Inspector: Shaun McGuire					Stage
		Morgan F	Ridge 2		
Project Name:		1			
For Week Ending:		024			
To Week Linding.	Southwest corner of Kemp			ton. NE (Douglas	
Project Location:		68007			
Grading:	15%				
Sanitary Sewer:	0%				
Storm Sewer: Paving:	0%				
Seeding:	0%				
Utilities:	0%				
Overall Development:	0%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
Sunday:	0.00"				Week
Monday:	0.00"		+	+	
Tuesday	0.26"			<u> </u>	
Wednesday	0.05"		_		
Thursday Friday	0.43" 0.00"	5/2/2024	Overcast 63/46	3:00 PM	
Saturday	0.81"			+	
Existing vegetation (4/18/24). Checklist Questions:	stabilization measures listed in t			truction activity?	
Yes	-,			,·	
Create Corrective Action? N/A					
IWA					
Have disturbed areas been seeded or o	otherwise stabilized as required? List inac	tive portions of the pro	ject and if stabilization measure	are adequate or needed	to prevent erosion.
Create Corrective Action?					
N/A					
Are waste materials (concrete, constru	ction material, hazardous, etc.) being man	naged properly?			
Yes					
Create Corrective Action? N/A					
-	ent streets being maintained adequately?				
Yes Create Corrective Action?					
N/A					
	n activity adequately controlled on the site	e?			
Yes Create Corrective Action?					
N/A					
Comments:					
Comments:					
The site was inactive during the	most recent inspection.				

Findings / Corrective Actions (Date):
Findings / Corrective Actions (Date):
Some maintenance is needed in the BMP section.

	-		D :			
Unique Name D 1	Type Diversion	Location SB E	Projected Install Date 4/18/2024	Status Pending	Maintenance Yes	
Current Condition:	Pending -	JB L	4/10/2024	Pending	162	
Guironi Gorianioni	. 5.139					
	Diversion should be installe	d.				
	Ruff Grading was informed to complete by 5/2/24. Not done as of last inspection.					
	-		-			
D 2	Diversion	SB F	4/18/2024	Pending	Yes	
Current Condition:	Pending -					
	Diversion should be installe	d.				
	Ruff Grading was informed	to complete by 5/2/24.	Not done as of last inspe	ection.		
D 3	Diversion	SB F	4/18/2024	Pending	Yes	
Current Condition:	Pending -					
	Diversion should be installe	d				
	Diversion should be installe	u.				
	Ruff Grading was informed		Not done as of last inspe	ection.		
EM 1	Erosion Matting	See SWPPP	4/18/2024	Pending	No	
Current Condition:	Pending - BMP will be insta					
EM 2 Current Condition:	Erosion Matting Pending - BMP will be insta	See SWPPP	4/18/2024	Pending	No	
EM 3	Erosion Matting	See SWPPP	4/18/2024	Active	No	
Current Condition:	Pending - BMP will be insta					
EM 4	Erosion Matting	See SWPPP	4/18/2024	Pending	No	
Current Condition:	Pending - BMP will be insta	lled when work begins/		· ·		
EM 5	Erosion Matting	See SWPPP	4/18/2024	Pending	No	
Current Condition:	Pending - BMP will be insta			pector will monitor.		
ET 1	Erosion Control Terrace	See SWPPP	4/18/2024	Pending	Yes	
Current Condition:	Pending -					
	Erosion Control Terrace sho	ould be installed.				
	Elocion Control Control of Michael Control					
	Ruff Grading was informed	to complete by 5/2/24.	Not done as of last inspe	ection.		
ET 2	Erosion Control Terrace	See SWPPP	4/18/2024	Pending	Yes	
Current Condition:	Pending -					
	Erosion Control Terrace sho	ould be installed.				
	Ruff Grading was informed	to complete by 5/2/24	Not done as of last inspe	action		
ET 3	Erosion Control Terrace	See SWPPP	4/18/2024	Pending	Yes	
Current Condition:	Pending -	555 577.77				
	-					
	Erosion Control Terrace sho	ould be installed.				
	Ruff Grading was informed	to complete by 5/2/24	Not done as of last inch	ection		
FT X	Fuel Tank	See SWPPP	4/18/2024	Active	No Prading installed a herm	
Current Condition:	Good Condition - Ruff Grad around the fuel tank prior to			mapeciion. Rull C	rauny motaneu a benn	
SB E	Sediment Basin	See SWPPP	4/18/2024	Pending	Yes	
Current Condition:	Pending -			. cding		
	Basin should be installed.					
	Ruff Grading was informed	to complete by 5/2/24	Not done as of last inone	action		
CD F					Vac	
SB F Current Condition:	Sediment Basin Pending -	See SWPPP	4/18/2024	Pending	Yes	
Carrent Condition.	Citaling					
	Basin should be installed.					
	Ruff Grading was informed	, ,	·			
SF 1	Silt Fence	Eastern Perimeter	4/18/2024	Active	Yes	
Current Condition:	Fair Condition - Ruff Gradin	g installed the silt fence	e prior to the 4/18/24 inspe	ection.		
	Silt fence should be extended.					
	Ruff Grading was informed	to complete by 5/2/24.	Not done as of last inspe	ection.		
		Southeastern	4/18/2024			
SF 2	Silt Fence	Perimeter	4/10/2024	Active	Yes	

Current Condition:	Fair Condition - Ruff Grading installed the silt fence prior to the 4/18/24 inspection. Silt fence should be extended.						
	Ruff Grading was informed to complete by 5/2/24. Not done as of last inspection.						
SF 3	Silt Fence	Western Perimeter	4/18/2024	Pending	Yes		
Current Condition:	Pending -						
	Silt fence should be installed. Ruff Grading was informed to complete by 5/2/24. Not done as of last inspection.						
SF 4							Silt Fence
Current Condition:	Pending -	1		1 chaing	103		
Carrotti Condition.	I Griulity -						
	Silt fence should be installed.						
	Ruff Grading was informed to complete by 5/2/24. Not done as of last inspection.						
MS 1	Material Storage	On Site	4/18/2024	Pending	No		
Current Condition:	Pending - Materials will be stored in designated areas.						
WO 1	Concrete Washout	On Site	4/18/2024	Pending	No		
Current Condition:	Pending - Concrete will be						
WS 1	Waste Storage	On Site	4/18/2024	Pending	No		
Current Condition:	Pending - Waste will be sto			1			
STR	Streets	N 156th Street	4/18/2024	Active	No		
Current Condition:	Good Condition - The streets were free of track out as of the 4/18/24 inspection.						
SWPPP Sign	SWPPP Notification Sign	On Site	5/11/2023	Pending	Yes		
Current Condition:	Pending -						
	SWPPP sign should be installed.						
	E&A inspector will install sign once it is received from the shop. Not done as of last inspection.						
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my						
Certification Statement:	direction or supervision in accordance with a system designed to assure that qualified personnel						
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or						
	persons who manage the system or those persons directly responsible for gathering the information,						
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I						
	am aware that there are significant penalties for submitting false information including the possibility						
	of fines and imprisonment for knowing violations."						
	Show Moly m			G	Co Su		
ector Signature:				Reviewed By:			