E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC **Engineering Answers** Environmental Services Dent Manager E&A - P2021.321.000 Inspector: Shaun McGuire Stage Morgan Ridge 1 CSW-202207264 Project Name: 8/19/2023 For Week Ending: Southwest corner of Kempten Creek Drive and 156th Street - Bennington, NE (Douglas 68007 Project Location: County) Grading: 5% 0% Sanitary Sewer: 0% Storm Sewer: 0% Paving: Seeding: 0% **Utilities:** 0% 0% Overall Development: RAIN FALL AMOUNTS Date inspected Amount in tenths Weather Conditions Time Week Sunday: 0.26 Monday 0.00" Tuesday 0.00 Wednesday 0.00 8/17/2023 Sunny 81/56 8:30 AM Thursday 0.00' Friday 0.00' Saturday 0.00 Complaints: Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the Grading the site (4/20/23). Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Grading the site (4/20/23). What temporary or permanent stabilization measures listed in this section are being implemented? Existing vegetation (4/20/23). Northwestern area seeded (7/27/23). Southern area seeded (8/17/23). Yes Corrective Action? N/A lave disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion Yes N/A Yes N/A No, See BMP section. s dust Create N/A

## Comments:

Comments:

The site was active during the most recent inspection.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 1	Construction Entrance	00-23	4/20/2023	Active	No	
Current Condition:	Good Condition - 90% Effect				6/15/23 inspection. Ruff	
	Grading added more rock	to the construction e	ntrance prior to the 8/17	/23 inspection.		
D 1	Diversion	BB-4	6/29/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing installed the diversi				
D 2	Diversion	R-5 to Z-4	7/27/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad				110	
D 3	Diversion	R-5 to S-4	4/20/2023	Pending	Yes	
Current Condition:	Pending -	110100		1 origing	100	
	· chang					
	Diversion should be installe	d per SWPPP.				
	Ruff Grading was informed	to complete by 5/25/23	. Not done as of the last in	spection. Ruff Gra	ding was reminded on	
	6/1/23, 7/14/23, 8/4/23, 8/10	0/23				
D 4	Diversion	I-9 to R-3	8/10/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing installed the diversi	on prior to the 8/10/23 ins	pection.		
D 5	Diversion	I-8 to E-8	7/13/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing installed the diversi	on prior to the 7/13/23 ins	pection.	•	
D 6	Diversion	C-8 to D-8	7/13/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad	ing installed the diversi	on prior to the 7/13/23 ins	pection.		
D 7	Diversion	BB-11 to BB-12	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta	lled when grading begin	ns/ends in the area. E&A i		tor.	
D 8	Diversion	BB-18 to BB-20	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
D 9	Diversion	NN-23	4/20/2023	Pendina	No	
Current Condition:	Pending - BMP will be insta					
D 10	Diversion	AA-33	4/20/2023	Pendina	No	
Current Condition:	Pending - BMP will be insta					
D 11	Diversion	G-13 to H-13	8/3/2023	Active	No No	
Current Condition:	Good Condition - Ruff Grad				INO	
D 12	Diversion	K-14 to H-14	8/3/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad				INU	
EM 1		See SWPPP	4/20/2023		No	
Current Condition:	Erosion Matting Pending - BMP will be insta			Pending		
		See SWPPP				
EM 2	Erosion Matting Pending - BMP will be insta		4/20/2023	Pending	No	
Current Condition:						
EM 3	Erosion Matting	See SWPPP	8/10/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad					
EM 4	Erosion Matting	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
ET 1	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
ET 2	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta					
ET 3	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta		ns/ends in the area. E&A i	nspector will monit	tor.	
ET 4	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta			nspector will moni	tor.	
ET 5	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta	lled when grading begi	ns/ends in the area. E&A i	nspector will monit	tor.	
ET 6	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta	lled when grading begi	ns/ends in the area. E&A i	nspector will monit	tor.	
ET 7	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta	lled when grading begin	ns/ends in the area. E&A i			
ET 8	Erosion Control Terrace	See SWPPP	4/20/2023	Pending	No	
Current Condition:	Pending - BMP will be insta			nspector will monit		
FT 1	Fuel Tank	On site	5/4/2023	Active	No	
Current Condition:	Good Condition - Ruff Grad					
PB 1	Portable toilet	On site	5/4/2023	Pending	No	
Current Condition:	Good Condition - Ruff Grad					
SB A	Sediment Basin	AA-4	4/20/2023	Pending	Yes	
Current Condition:	Pending - Ruff Grading beg				100	
Carrotti Condition.	. Chaing Train Grading Deg	a onaping the basin p	to the oronzo mapeono			
	Basin should be installed pe	er SWPPP.				
	Dubin Should be installed per OWLTT.					
	Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded on					
	Ruff Grading was informed	to complete by 5/25/23	. Not done as of the last in	ispection. Ruff Gra	ading was reminded on	
	Ruff Grading was informed 6/1/23, 7/14/23, 8/4/23, 8/10	the state of the s	. Not done as of the last in	spection. Ruff Gra	ading was reminded on	

	Pending - Ruff Grading beg	an shaping the basin p	rior to the 6/8/23 inspectio	ın.			
	Basin should be installed pe	er SWPPP.					
	Ruff Grading was informed to complete by 5/25/23. Not done as of the last inspection. Ruff Grading was reminded o						
	6/1/23, 7/14/23, 8/4/23, 8/10		4/00/0000				
SB C Current Condition:	Sediment Basin Pending - Ruff Grading beg	D-8	4/20/2023	Pending	Yes		
Current Condition.	Feliding - Rull Glading beg	an shaping the basin p	nor to the 6/29/23 inspecti	iori.			
	Basin should be installed per SWPPP.						
	Ruff Grading was informed		. Not done as of the last in	nspection. Ruff Gra	ding was reminded of		
SB D	6/1/23, 7/14/23, 8/4/23, 8/10	HH-32 to NN-29	4/20/2023	Pending	No		
Current Condition:	Sediment Basin Pending -	1111-32 to MN-29	4/20/2023	Pending	No		
SF 1	Silt Fence	Western Perimeter	4/20/2023	Active	Yes		
Current Condition:	Fair Condition - Ruff Gradin						
	4/20/23 inspection. Ruff Gra	ading installed the rema	inder of the silt fence prio	or to the 5/4/23 insp	ection.		
	City force about the alcohol out						
	Sill ferice should be clearled	Silt fence should be cleaned out.					
	Ruff Grading was informed	to complete by 7/20/23	. Not done as of last inspe	ection. Ruff Grading	was reminded on 8		
	8/10/23						
SF 2	Silt Fence	Southeastern Perimeter	5/4/2023	Active	Yes		
Current Condition:	Fair Condition - Ruff Gradin		the silt fence prior to the		103		
		J,,.					
	1.) Silt fence should be rein						
	2.) Silt fence should be clea	ined out.					
	1.) Ruff Grading was inform	ed to complete by 7/20	/23 Not done as of last in	spection Buff Grad	ding was reminded o		
	8/4/23, 8/10/23	ed to complete by 7720	723. Not done as or last in	spection. Run Grad	aling was reminded to		
	2.) Ruff Grading was inform	ed to complete by 7/20	/23. Not done as of last in	spection. Ruff Grad	ding was reminded o		
	8/4/23, 8/10/23			•			
05.0	Oile Farance	Southeastern	5/4/2023	0 -45	V		
SF 3 Current Condition:	Silt Fence	Perimeter	nrior to the 5/4/23 inspec	Active	Yes		
Current Condition.	Fair Condition - Ruff Grading installed the silt fence prior to the 5/4/23 inspection.						
	Silt fence should be cleaned out.						
	Ruff Grading was informed 8/10/23	to complete by 7/20/23	. Not done as of last inspe	ection. Ruff Grading	was reminded on 8		
SF 4	Silt Fence	Eastern Perimeter	5/4/2023	Active	Yes		
Current Condition:	Fair Condition - Ruff Gradin		prior to the 5/4/23 inspec				
	Silt fence should be cleaned	d out.					
	Ruff Grading was informed	to complete by 7/20/23	Not done as of last inspe	ection, Ruff Gradino	was reminded on 8		
	8/10/23				,		
05.5	074.5	Northeastern	5/4/2023		V		
SF 5 Current Condition:	Silt Fence	Perimeter		Active	Yes		
	Tall Collabor Tall Cladin	a installed the silt tence	prior to the 5/4/23 inspec				
		g installed the silt fence	prior to the 5/4/23 inspec				
	Silt fence should be cleaned		e prior to the 5/4/23 inspec				
		d out and repaired.		ction.			
	Ruff Grading was informed	d out and repaired.		ction.	ing was reminded or		
	Ruff Grading was informed 8/10/23.	d out and repaired. to complete by 8/10/23	Not done as of last insp	pection. Ruff Grad	<u> </u>		
SF 6 Current Condition:	Ruff Grading was informed	d out and repaired.  to complete by 8/10/23  Northern Perimeter	Not done as of last insp 4/20/2023	pection. Ruff Grad	No		
SF 6	Ruff Grading was informed 8/10/23. Silt Fence	d out and repaired.  to complete by 8/10/23  Northern Perimeter	Not done as of last insp 4/20/2023 ns/ends in the area. E&A i	pection. Ruff Grad	No		
SF 6	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta	d out and repaired.  to complete by 8/10/23  Northern Perimeter  lled when grading beging  Northeastern  Perimeter	Not done as of last insu 4/20/2023 ns/ends in the area. E&A i 4/20/2023	pection. Ruff Grad Pending Inspector will monit Pending	No or.		
SF 6 Current Condition: SF 7 Current Condition:	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta	d out and repaired.  to complete by 8/10/23  Northern Perimeter lled when grading beging Northeastern Perimeter lled when grading begingled when grading begingled when grading beging b	Not done as of last insu 4/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i	Pending inspector will monit Pending inspector will monit	No or. No or.		
SF 6 Current Condition:  SF 7 Current Condition: ST A	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap	d out and repaired.  Northern Perimeter  When the discount of the complete by 8/10/23  Northern Perimeter  Northeastern  Perimeter  Red when grading begin of the complete by	A/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 8/3/2023	Pending inspector will monit Pending Active	No or. No or. No		
SF 6 Current Condition: SF 7 Current Condition:	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began s	A/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 8/3/2023 haping the sediment trap	Pending inspector will monit Pending Active	No or. No or. No		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began sorior to the 8/3/23 inspec	A/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 8/3/2023 haping the sediment trap	Pending inspector will monit Pending Active prior to the 7/27/23	No or.  No or.  No inspection. Ruff Gra		
SF 6 Current Condition:  SF 7 Current Condition: ST A	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began s	A/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 8/3/2023 haping the sediment trap	Pending inspector will monit Pending Active	No or. No or. No		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:  MS 1 Current Condition:  WO 1	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap    Material Storage	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began sorior to the 8/3/23 inspec	A/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 8/3/2023 haping the sediment trap	Pending inspector will monit Pending Active prior to the 7/27/23	No or.  No or.  No inspection. Ruff Gra		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:  MS 1 Current Condition:  WO 1 Current Condition:	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap  Material Storage Pending -  Concrete Washout Pending -	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began s prior to the 8/3/23 inspection on Site  On Site	A/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 8/3/2023 haping the sediment trap iction. 4/20/2023	Pending Inspector will monit Pending Inspector will monit Pending Inspector will monit Active Prior to the 7/27/23 Pending Pending	No or. No or. No inspection. Ruff Gra No		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:  MS 1 Current Condition:  WO 1 Current Condition:  WS 1	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap Material Storage Pending - Concrete Washout Pending - Waste Storage	d out and repaired.  Northern Perimeter  Illed when grading begin  Northeastern  Perimeter  Illed when grading begin  H-13  Ruff Grading began sorior to the 8/3/23 inspectors.	A/20/2023 ns/ends in the area. E&A i 4/20/2023 ns/ends in the area. E&A i 8/3/2023 haping the sediment trap action. 4/20/2023	Pending Inspector will monit Pending Inspector will monit Active Prior to the 7/27/23 Pending	No or.  No or.  No inspection. Ruff Gra  No		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:  MS 1 Current Condition:  WO 1 Current Condition:  WS 1 Current Condition:	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap    Material Storage Pending -  Concrete Washout Pending -  Waste Storage Pending -	Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began sorior to the 8/3/23 inspector to the Site On Site On Site	A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  8/3/2023  haping the sediment trap action.  A/20/2023  4/20/2023	Pending Inspector will monit Pending Inspector will monit Pending Inspector will monit Active Prior to the 7/27/23 Pending Pending Pending Pending	No Or. No Or. No Inspection. Ruff Gra No No No		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:  MS 1 Current Condition:  WO 1 Current Condition:  WS 1 Current Condition:  STR	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap    Material Storage Pending - Concrete Washout Pending - Waste Storage Pending - Streets	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began sorior to the 8/3/23 inspector to the Site On Site  N 156th Street	A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  8/3/2023  apaing the sediment trap action.  A/20/2023  A/20/2023  A/20/2023  A/20/2023	Pending Inspector will monit Pending Inspector will monit Pending Inspector will monit Active Prior to the 7/27/23 Pending Pending Pending Active Active	No or.  No or.  No or.  No inspection. Ruff Gra  No No No No Yes		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:  MS 1 Current Condition:  WO 1 Current Condition:  WS 1 Current Condition:	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap    Material Storage Pending -  Concrete Washout Pending -  Waste Storage Pending -	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began sorior to the 8/3/23 inspector to the Site On Site  N 156th Street	A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  8/3/2023  apaing the sediment trap action.  A/20/2023  A/20/2023  A/20/2023  A/20/2023	Pending Inspector will monit Pending Inspector will monit Pending Inspector will monit Active Prior to the 7/27/23 Pending Pending Pending Active Active	No or.  No or.  No or.  No inspection. Ruff Gra  No No No No Yes		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:  MS 1 Current Condition:  WO 1 Current Condition:  WS 1 Current Condition:  STR	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap Material Storage Pending - Concrete Washout Pending - Waste Storage Pending - Streets Fair Condition - The streets the 8/17/23 inspection.	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began sorior to the 8/3/23 inspector to the Site On Site  N 156th Street	A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  8/3/2023  apaing the sediment trap action.  A/20/2023  A/20/2023  A/20/2023  A/20/2023	Pending Inspector will monit Pending Inspector will monit Pending Inspector will monit Active Prior to the 7/27/23 Pending Pending Pending Active Active	No or.  No or.  No or.  No inspection. Ruff Gra  No No No No Yes		
SF 6 Current Condition:  SF 7 Current Condition:  ST A Current Condition:  MS 1 Current Condition:  WO 1 Current Condition:  WS 1 Current Condition:  STR	Ruff Grading was informed 8/10/23.  Silt Fence Pending - BMP will be insta  Silt Fence Pending - BMP will be insta  Sediment Trap Good Condition - 3% Filled installed the sediment trap   Material Storage Pending - Concrete Washout Pending - Waste Storage Pending - Streets Fair Condition - The streets	d out and repaired.  Northern Perimeter Illed when grading begin Northeastern Perimeter Illed when grading begin H-13 - Ruff Grading began sorior to the 8/3/23 inspector to the Site On Site  N 156th Street	A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  A/20/2023  as/ends in the area. E&A i  8/3/2023  apaing the sediment trap action.  A/20/2023  A/20/2023  A/20/2023  A/20/2023	Pending Inspector will monit Pending Inspector will monit Pending Inspector will monit Active Prior to the 7/27/23 Pending Pending Pending Active Active	No or.  No or.  No or.  No inspection. Ruff Gra  No No No No Yes		

SWPPP Sign	SWPPP Notification Sign	On Site	5/11/2023	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign during the 5/11/23 inspection.						
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my						
	direction or supervision in accordance with a system designed to assure that qualified personnel						
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or						
	persons who manage the system or those persons directly responsible for gathering the information,						
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I						
	am aware that there are significant penalties for submitting false information including the possibility						
	of fines and imprisonment for knowing violations."						
Inspector Signature:  Paylowed By:							
Inspector Signature: Reviewed By:							