

E & A Consulting Group, Inc.
 10909 Mill Valley Road, Suite 100
 Omaha, NE 68154
 tel 402.895.4700
 fax 402.895.3599
 www.eacg.com




Engineering Answers

Zachary A. Jilek, CPESC, CISEC
 Environmental Services Dept. Manager

E & A CONSULTING GROUP, INC.
 ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

E&A - P1996.080.000

Inspector: Sam Fletcher				Stage
Project Name:	Northwest Village NER100704			3
For Week Ending:	6/13/2015			
Project Location:	N 92nd Avenue and Military Road Omaha, NE (Douglas County)			68122
Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	50%			
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	
				Week 1
Sunday:	0.17"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.19"			
Thursday	0.54"			
Friday	0.10"	05/15/15	70/53 rain	
Saturday	0.17"			
				Week 2
Sunday:	0.05"			
Monday	0.00"			
Tuesday	0.01"			
Wednesday	0.06"			
Thursday	0.00"			
Friday	0.01"			
Saturday	0.02"			
				Week 3
Sunday:	0.18"			
Monday	0.00"			
Tuesday	0.24"			
Wednesday	0.00"			
Thursday	0.11"			
Friday	0.01"			
Saturday	0.02"			
				Week 4
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.36"			
Thursday	0.05"			
Friday	0.00"			
Saturday	0.14"			
				Week 5
Sunday:	0.09"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.30"			
Thursday	1.91"			
Friday	0.00"	06/12/15	68/62 cloudy	

Saturday	0.00"				
Complaints:	None				
Construction Sequencing:					
Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?					
Entire site; grading completed and site seeded prior to 2005.					
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :					
Entire site; grading completed and site seeded prior to 2005.					
What temporary or permanent stabilization measures listed in this section are being implemented?					
Paving, dense vegetation and landscaping installed (prior to 2005)					
SUMMARY QUESTIONS:					
Are approved entrances and adjacent streets being maintained adequately?					
Yes					
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?					
Yes					
CHECKLIST QUESTIONS:					
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?					
Yes					
Is dust associated with the construction activity adequately controlled on the site?					
Yes					
Comments:					
Comments:					
No construction is active.					
Findings / Corrective Actions (Date):					
Findings / Corrective Actions (Date):					
1) No required maintenance in BMP section.					
Unique Name	Type	Location	Projected Install Date	Status	Maintenance Scheduled
SB 1	Sediment Basin	N41d18m50s W96d03m24s	In Place	Active	No
Current Condition:	Good Condition -10% Filled- Basin Cleaned by Bob Roth on 05/27/09.				
STR	Streets	N41d18m50s W96d03m24s	In Place	Active	No
Current Condition:	Good Condition- No major signs of track off.				
SWPPP Sign	Signs	1 Sign	8-19-08	Active	No
Current Condition:	Good Condition -92 and Military Rd.				
Inspector Signature:			Reviewed By:	