E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept.	managor	E&A- P2003.19	01.000	
Inspector: Sam Fletcher				Stage
		Na	wport Hill	3
Project Name:			ER110499	
For Week Ending:			2/13/2016	
Project Location:	180th S	t and NE Highway	36- Bennington NE (Douglas Co	ounty) 68007
Grading:	1009	%		
Sanitary Sewer:	100			
Storm Sewer:	100			
Paving:	100			
Seeding:	100			
Utilities:	100			
Overall Development:	36	%		
				<u> </u>
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions	Wester
Sunday:	0.00"			Week 1
Monday	0.00"	+	- - - - - - - - - - 	
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
	To one			Week 2
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.04"	04/00/40	00/47	
Wednesday	0.00"	01/20/16	20/17 sunny	
Thursday Friday	0.00" 0.00"			
Saturday	0.00"			
Catarday	0.00			Week 3
Sunday:	0.00"			Wesk
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				Week 4
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.38"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			M/o o l - C
Sunday:	0.00"	1		Week 5
Monday	0.00"		+	
Tuesday	0.00"			
Wednesday	0.00"		 	
Thursday	0.00"		 	

Friday	0.00"				
Saturday	0.00"				
Complaints:	None				
Construction Sequencing: Which portion(s) (i.e. drainage basins) o	of the site have had a temp	orary or permanent cessatio	on of grading, earthwo	ork, or ground disturbance in	the last 14 days?
Entire Site, grading was completed	d on 6/11/07.				
Which portion(s) (i.e. drainage basins) o		ding, earthwork, or ground d	isturbance scheduled	I in the next 14 days? :	
Entire Site, grading was completed	d on 6/11/07.	1	1	T	1
What temporary or permanent stabilizat	ion moscures listed in this	costion are being implemen	atod2		
Seeded (6/2007), Re-seeded (9/20 (4/21/15)	007), Paving (9/2007),	Seeded (4/2008), Small (drainage ditch beh	ind lot 41 was seeded and	d matted
SUMMARY QUESTIONS:					
Are approved entrances and adjacent st	reets being maintained ad	lequately?			
No, See BMP section.					
Are receiving waters adjacent to the pro	ject free of any significant	signs of erosion or sedimer	nt that would be asso	ciated with the construction a	ctivity?
Yes					
CHECKLIST QUESTIONS:					
Are waste materials (concrete, construc	tion material, hazardous,	etc.) being managed properly	y?		
Yes	<u> </u>	, , , , , ,			
Is dust associated with the construction	activity adequately contro	olled on the site?			
Yes					
Comments:					
Comments: Multiple houses are being built as	of the last inspection.	Site was covered with 5-	-7" of snow during	the last inspection.	
Findings / Corrective Actions (D	ate):				
Findings / Corrective Actions (D 1) Maintenance required in the BM 2) The area East of lot 41 needs to by 8/12/15. The debris was remove	IP section. be stabilized and the				ned to complete
			Projected Install		
Unique Name	Туре	Location	Date	Status	Maintenance
		South of Northern Dr.			
DS 1	Swale	between SB 1 and 2	6/13/2007	Active	No
Current Condition:	Good Condition	West of 182nd Cir.	1	T	1
DS 9	Swale	towards SB 4	6/13/2007	Active	No
Current Condition:	Good Condition	towardo ob 1	0/10/2001	710.110	110
		East of Northern Dr.	ı	Ι	1
		and 182nd Cir towards			
DS 12	Swale	SB 5	6/13/2007	Active	No
Current Condition:	Good Condition				<u> </u>
		East of Star grass Rd			
DS 13	Swale	towards SB 6	6/13/2007	Active	No
Current Condition:	Good Condition	North of Otes D. I	1	Π	ı
DS 14	Swale	North of Star grass Rd towards SB 6	6/13/2007	Active	No
Current Condition:	Good Condition		2 2. 200.	1	
1 -4 41 -4 4	Cill Fancis	Late and at 4	44/00/0045	Danding	V/22

Current Condition:	Pending						
	The silt fence was removed to pour the side walk and needs to be reinstalled.						
	The Home Company was informed to complete by 11/26/15. Not done as of last inspection.						
Lot 2	Individual Lot	Lot 2		Removed			
Current Condition:	Removed - Barr H	lomes sodded the lot p	rior to the 11/13/15	inspection.	•		
Lot 4	Silt Fence	Lot 4		Removed			
Current Condition:	Removed - Pendi	ng Changed from Lot 4	to Lot 1 replat 1.				
Lot 5	Silt Fence	Lot 5		Removed			
Current Condition:	Removed - Reger	ncy Homes sodded the	lot prior to the 8/18/	15 inspection.	•		
Lot 6	Silt Fence	Lot 6	8/25/2015	Pending	Yes		
Current Condition:	Pending			,			
		o be installed on the fro					
Lot 9	Individual Lot	Lot 9	11/19/2015	Active	Yes		
Current Condition:	buffer strip.	is needed as of the last		he area being flat and h	aving a vegetated		
	The builder is unk	nown as of the last insp	pection. Not done a	s of last inspection.			
Lot 10	Individual Lot	Lot 10	9/5/2015	Active	No		
Current Condition:	Active - The lot number was changed from 9 to 10. No BMP is needed as of the last inspection due t the area being flat and having a vegetated buffer strip.						
Lot 11	Individual Lot	Lot 11	11/13/2015	Active	No		
Current Condition:		er is unknown. No BMI Concrete debris was cle		a vegetated buffer strip a 12/16/15 inspection.	as of the last		
Lot 17	Individual Lot	Lot 17	10/24/2015	Active	No		
Current Condition:	Active - Ramm is inspection.	Active - Ramm is the builder. No BMP is needed due to a vegetated buffer strip as of the last inspection.					
Lot 18	Silt Fence	Lot 18	8/25/2015	Pending	Yes		
Current Condition:	Pending Silt fence needs to be installed on the front of the lot. Empire Homes was informed to complete by 8/25/15. Not done as of last inspection. Empire Home was reminded on 9/28/15.						
Lot 23	Silt Fence	Lot 23		Removed			
Current Condition:	Removed - The H	lome Company sodded	the lot prior to the 7	7/29/15 inspection.			
Lot 32	Silt Fence	Lot 32	10/31/2015	Pending	Yes		
Current Condition:	Pending						
	Silt fence needs to be installed on the front of the lot.						
	Prairie Homes was informed to complete by 10/31/15. Not done as of last inspection.						
Lot 36	Silt Fence	Lot 36		Removed			
Current Condition:		lome Company sodded	the lot prior to the 1		1		
		. ,	1	•			
Lot 41	Silt Fence	Lot 41		Removed			
Current Condition:		eston Homes sodded th	e lot prior to the 7/2		•		

1 -4 40	المسائدة فالمسالية	L at 40	7/40/0045	A ations	Na
Lot 43 Current Condition:	Individual Lot	Lot 43 s active on the lot as of 7	7/16/2015	Active	No ated buffer
Current Condition.	Active - Building is	s active on the lot as of h	/10/13. NO DIVII 13	needed due to a veget	ated buller.
Lot 44	Individual Lot	Lot 44	10/24/2015	Active	No
Current Condition:		y Homes is the builder.			
Janont Johannon.	last inspection.	,	. 10 2 10 1100000		
Lot 45	Silt Fence	Lot 45	10/24/2015	Active	No
Current Condition:		The builder installed silt			
Lot 46	Silt Fence	Lot 46	8/18/2015	Active	No
Current Condition:		Silt fence was installed on.	on the back of the lo	ot prior to the 8/18/15 in	
Lot 56	Silt Fence	Lot 56		Removed	
Current Condition:		s Werner sodded the lot	prior to the 6/12/15		
Lot 58	Individual Lot	Lot 58		Removed	
Current Condition:		Construction sodded th	ne lot prior to the 12		
		T	· 	·	1
Lot 62	Individual Lot	Lot 62	12/16/2015	Active	No
Current Condition:		ad Builders is building or f the last inspection.	the lot as of the 12	2/16/15 inspection. The	lot is flat so n
Lot 80	Individual Lot	Lot 80		Removed	
Current Condition:	Removed - The lo	t was sodded prior to the	e 12/16/15 inspection	on by Prairie Homes.	•
Lot 81	Individual Lot	Lot 81	10/24/2015	Active	No
Current Condition:		s needed due to a veget			
Lot 90	Silt Fence	Lot 90		Removed	
Current Condition:	Removed - Landn	nark Homes sodded the	lot prior to the 11/1	3/15 inspection.	
		South of Northern Dr.			
		on southwest corner			
SB 1 Current Condition:	Sediment Basin	of site 45% Filled. The voluntee	04/06/07	Active	No No
Current Condition:	inspection.	15% Filled. The voluntee	er trees were remov	ed from the basin prior	to the 3/20/13
		South of Northern Dr.			
SB 2	Sediment Basin	between 185th St and 184th St.	4/9/2007	Active	No
Current Condition:	Good Condition -2	20% Filled. The volunted			
	inspection.	South of Northern Dr.	 		1
		between 182th St and			
SB 3	Sediment Basin	184th St.	04/06/07	Active	No
Current Condition:	Good Condition - inspection.	27% Filled. The volunte	er trees were remo	ved from the basin prio	r to the 3/20/1
		South of Northern Dr. between 182th St and			
SB 4	Sediment Basin	184th St.	04/06/07	Active	No
Current Condition:	Good Condition -2 inspection.	22% Filled. The voluntee	er trees were remov	ved from the basin prior	to the 3/20/15
SB 5	Sediment Basin	East of 182nd Cir.	04/06/07	Active	No
Current Condition:	Good Condition - 22% Filled. The volunteer trees were removed from the basin prior to the 3/20/15 inspection.				
SB 6	Sediment Basin	Northeast of Star	1/0/6337		
		grass Rd.	4/9/2007	Active	No

Current Condition:	Good Condition - 22% Filled -Cleaned by ME Collins 6/2008					
SB 7	Sediment Basin	North of Star grass Rd. East of 182nd St.	4/9/2007	Active	No	
Current Condition:	Good Condition - 40% Filled					
SB 8	Sediment Basin	North of Star grass Rd. between 184th St and 182nd St	4/20/2007	Active	No	
Current Condition:	Good Condition - 40% Filled					
STR	Streets	Entire Site	3/20/2007	Active	No	
Current Condition:	Good Condition - No major signs of track off. All streets cleaned by snow plows due to recent					
	snows as of the	snows as of the 1/20/16 inspection.				
SWPPP signs	Signs	1 sign	8/19/2008	Pending	Yes	
Current Condition:	Pending The sign is missing as of the 6/12/15 inspection. The inspector will look for the sign. If it cannot be found a new sign will be ordered.					
Inspector Signature:			Reviewed By:	Zachany L. Jilek		