|   | E&A- 200                  | 3.191.000                    |                       |                    |  |  |  |  |
|---|---------------------------|------------------------------|-----------------------|--------------------|--|--|--|--|
| Inspector: Phillip Dechant                          |                           |                              |                       | Stage              |  |  |  |  |
| Project Name:                                       |                           | 2                            |                       |                    |  |  |  |  |
| For Week Ending:                                    |                           |                              |                       |                    |  |  |  |  |
|   |                           | 10/25/2008                   |                       | <u> </u>           |  |  |  |  |
| Grading:  | 100%                      |                              |                       |                    |  |  |  |  |
| Sanitary Sewer:                                     | 100%                      |                              |                       |                    |  |  |  |  |
| Storm Sewer:  | 100%                      |                              |                       |                    |  |  |  |  |
| Paving:   | 100%                      |                              |                       |                    |  |  |  |  |
| Seeding:  | 100%                      |                              |                       |                    |  |  |  |  |
| Utilities:  | 100%                      |                              |                       |                    |  |  |  |  |
| Overall Development: 35%                            |                           |                              |                       |                    |  |  |  |  |
|   | American the terration    |                              |                       |                    |  |  |  |  |
| RAIN FALL AMOUNTS                                   | Amount in tenths          | Date inspected               |                       | Week 1             |  |  |  |  |
| Sunday:   | 0.00"                     |                              |                       | Week 1             |  |  |  |  |
| Monday  | 1.27"                     |                              |                       |                    |  |  |  |  |
| Tuesday   | 0.46"                     | 10/14/08                     |                       |                    |  |  |  |  |
| Wednesday   | 0.28"                     | 10/15/08                     |                       |                    |  |  |  |  |
| Thursday  | 0.00"                     |                              |                       |                    |  |  |  |  |
| Friday  | 0.06"                     |                              |                       |                    |  |  |  |  |
| Saturday  | 0.00"                     |                              |                       |                    |  |  |  |  |
|   | 0.00"                     |                              |                       | Week 2 / 3         |  |  |  |  |
| Sunday:   | 0.00"                     |                              |                       |                    |  |  |  |  |
| Monday<br>Tuesday                                   | 0.00"<br>0.31"            |                              |                       |                    |  |  |  |  |
| Wednesday   | 1.18"                     |                              |                       |                    |  |  |  |  |
| Thursday  | 0.13"                     | 10/23/08                     |                       |                    |  |  |  |  |
| Friday  | 0.11"                     | 10/24/08                     |                       |                    |  |  |  |  |
| Saturday  | 0.00"                     |                              |                       |                    |  |  |  |  |
|   |                           |                              |                       |                    |  |  |  |  |
|   | None                      |                              |                       |                    |  |  |  |  |
| Complaints:   | -                         |                              |                       |                    |  |  |  |  |
|   |                           |                              | _                     | (                  |  |  |  |  |
|   |                           |                              |                       | L                  |  |  |  |  |
| Construction Sequencing:                            |                           |                              |                       |                    |  |  |  |  |
| Which portion(s) (i.e. drainage basins) of the site | have had a temporary      | or permanent cessation of g  | rading, earthwork, or | ground disturbance |  |  |  |  |
| in the last 14 days?                                |                           |                              |                       |                    |  |  |  |  |
| Entire Site, grading was completed on 6/1           | 1/07.                     |                              |                       |                    |  |  |  |  |
|   | 1                         | 1                            |                       |                    |  |  |  |  |
|   |                           |                              |                       |                    |  |  |  |  |
| Which portion(s) (i.e. drainage basins) of the site | do not have grading, e    | earthwork, or ground disturb | ance scheduled in the | next 14 days? :    |  |  |  |  |
| ,   | 0 0,                      |                              |                       |                    |  |  |  |  |
| Entire Site, grading was completed on 6/1           | 1/07.                     |                              |                       |                    |  |  |  |  |
|   |                           |                              |                       |                    |  |  |  |  |
|   |                           |                              |                       |                    |  |  |  |  |
| What temporary or permanent stabilization measure   | ures listed in this secti | on are being implemented?    |                       | <u> </u>           |  |  |  |  |
|   |                           |                              |                       |                    |  |  |  |  |
| Seeded 6/2007 by Hausman, Re-seeded                 | 9/2007, Paving 9/2        | 007, Seeded 4/2008 by        | Wenninghoff.          |                    |  |  |  |  |
|   |                           |                              |                       |                    |  |  |  |  |
| Comments:   |                           |                              |                       |                    |  |  |  |  |
| Comments:   |                           |                              |                       |                    |  |  |  |  |
| No activity on site at time of inspection.          |                           |                              |                       |                    |  |  |  |  |
|   |                           |                              |                       |                    |  |  |  |  |
| Findings / Corrective Actions (Date):               |                           |                              |                       |                    |  |  |  |  |

## Findings / Corrective Actions (Date):

1) See BMP section for required maintenance.

2) There are various pieces of lot level silt fence throughout the site that are full after rains. Boyer Young is aware of these areas, these items will be left as is for now to let vegetation establish more densely. After this is accomplished the silt fence will be removed and area repaired as needed by Boyer & Young.

3) There are various pieces of lot level silt fence throughout the site that are undermined and down. Boyer Young to complete maintenance by 7/5/08. Not completed prior to last inspection.

4) Silt fence around an area inlet in the SE corner of job site is damaged and need to be repaired. Boyer Young to complete maintenance by 6/27/08. Not completed as of last inspection due to heavy rains; new completion date set for 7/5/08. Not completed prior to last inspection.

5) Lee Schwendiman with NewStreet requested an inspection to determine if certain pieces of silt fence can be removed due to the dense vegetation. Inspector met with Darryl Longemann 10-1-08 onsite to determine which silt fence hooks can be removed, and it was decided to remove most all of them with a few exceptions in various locations. New Street to 6) Rills along the streets are beginning to undermine the street. NewStreet was requested to repair by 10-21-08. Darryl Lo

| Unique Name        | Туре               | Location        | Projected Install<br>Date | Status     | Maintenance |
|--------------------|--------------------|-----------------|---------------------------|------------|-------------|
| Unique Maine       | Construction       | N41d00m00s      | Date                      | Otatus     | Wantenance  |
| CE 1               | Entrance           | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Removed for pavir  |                 |                           |            |             |
|                    |                    | N41d00m00s      |                           |            |             |
| DS 1               | Swale              | W96d00m00s      | 6/13/2007                 | Active     | No          |
| Current Condition: | Good Condition     | W3000011003     | 0/10/2001                 | Active     | NO          |
| ourrent condition. |                    | N41d00m00s      | - T                       |            |             |
| DS 2               | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Swale deleted repl |                 |                           | Removed    |             |
| Current Condition. | Owale deleted repl | N41d00m00s      |                           |            |             |
| DS 3               | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Removed due to g   |                 |                           | Kenioveu   |             |
| Current Condition. |                    | N41d00m00s      |                           |            |             |
| DS 4               | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Removed due to g   |                 |                           | Removed    |             |
| ourient condition. |                    | N41d00m00s      |                           |            |             |
| DS 5               | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Removed due to g   | rading in area. |                           |            |             |
|                    |                    | N41d00m00s      |                           |            |             |
| DS 6               | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Removed due to g   | rading in area. |                           |            |             |
|                    |                    | N41d00m00s      |                           |            |             |
| DS 7               | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Removed due to g   | rading in area. |                           |            |             |
|                    |                    | N41d00m00s      |                           |            |             |
| DS 8               | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Removed due to g   | rading in area. |                           |            |             |
|                    |                    | N41d00m00s      |                           |            |             |
| DS 9               | Swale              | W96d00m00s      | 6/13/2007                 | Active     | No          |
| Current Condition: | Good Condition     |                 |                           |            |             |
|                    |                    | N41d00m00s      |                           |            |             |
| DS 10              | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Removed due to g   |                 |                           |            | 1           |
|                    |                    | -               | - <del> </del>            |            |             |
|                    |                    | N41d00m00s      |                           | <b>.</b> . |             |
| DS 11              | Swale              | W96d00m00s      |                           | Removed    |             |
| Current Condition: | Swale deleted repl | aced by DS 12.  |                           |            |             |
|                    |                    | N41d00m00s      |                           |            |             |
| DS 12              | Swale              | W96d00m00s      | 6/13/2007                 | Active     | No          |
| Current Condition: | Good Condition     |                 |                           |            |             |
|                    |                    | N41d00m00s      | T                         |            |             |
| DS 13              | Swale              | W96d00m00s      | 6/13/2007                 | Active     | No          |
| Current Condition: | Good Condition     | VV 9000011005   | 0/13/2007                 | Active     | INU         |
| Current Conultion. | Cood Condition     |                 |                           |            |             |

|                            |                                      | N41d00m00s               |                      |                       |              |
|----------------------------|--------------------------------------|--------------------------|----------------------|-----------------------|--------------|
| DS 14                      | Swale                                | W96d00m00s               | 6/13/2007            | Active                | No           |
| Current Condition:         | Good Condition                       |                          |                      |                       |              |
|                            |                                      | N41d00m00s               |                      |                       |              |
| DS 15                      | Swale                                | W96d00m00s               |                      | Removed               |              |
| Current Condition:         | Swale deleted.                       |                          |                      |                       |              |
|                            |                                      | N41d00m00s               |                      |                       |              |
| DS 16                      | Swale                                | W96d00m00s               |                      | Removed               |              |
| Current Condition:         | Swale deleted.                       |                          |                      |                       |              |
|                            |                                      | N41d00m00s               |                      |                       |              |
| SB 1                       | Sediment Basin                       | W96d00m00s               | 04/06/07             | Active                | No           |
| Current Condition:         | Good Condition- 38                   | 3% Filled                |                      |                       |              |
|                            | -Cleaned by Hausn                    | nan 9/2007.              |                      |                       |              |
|                            |                                      | N41d00m00s               |                      |                       |              |
| SB 2                       | Sediment Basin                       | W96d00m00s               | 4/9/2007             | Active                | No           |
| Current Condition:         | Good Condition -19                   |                          |                      |                       |              |
|                            | -Cleanout marks w                    | ere painted 11/2/07.     |                      |                       |              |
|                            |                                      | N41d00m00s               |                      |                       |              |
| SB 3                       | Sediment Basin                       | W96d00m00s               | 04/06/07             | Active                | No           |
| Current Condition:         | Good Condition - 2                   |                          |                      |                       |              |
|                            | -Cleanout as a prev                  | ventative maintenance    | was completed price  | or to inspection 11/2 | 2/07.        |
| SB 4                       | Sediment Basin                       | N41d00m00s<br>W96d00m00s | 04/06/07             | Activo                | No           |
| Current Condition:         | Good Condition -21                   |                          | 04/06/07             | Active                | INU          |
| Current Condition.         |                                      |                          |                      |                       |              |
| SB 5                       | Codimont Dopin                       | N41d00m00s<br>W96d00m00s | 04/06/07             | Active                | No           |
| Current Condition:         | Sediment Basin<br>Good Condition - 2 |                          | 04/06/07             | Active                | INU          |
| Current Condition.         |                                      |                          | 1                    | I                     |              |
|                            | Carlin ant Dasia                     | N41d00m00s               | 4/0/0007             | A ative               | Nia          |
| SB 6<br>Current Condition: | Sediment Basin<br>Good Condition - 2 | W96d00m00s               | 4/9/2007             | Active                | No           |
| Current Condition.         | -Cleaned by ME Co                    |                          |                      |                       |              |
|                            |                                      | N41d00m00s               |                      |                       |              |
| SB 7                       | Sediment Basin                       | W96d00m00s               | 4/9/2007             | Active                | No           |
| Current Condition:         | Good Condition - 4                   |                          |                      |                       |              |
|                            |                                      | N41d00m00s               | 1                    |                       |              |
| SB 8                       | Sediment Basin                       | W96d00m00s               | 4/20/2007            | Active                | No           |
| Current Condition:         | Good Condition - 4                   | 0% Filled                |                      |                       |              |
|                            | I                                    | N41d00m00s               |                      |                       |              |
| SF 1                       | Silt Fence                           | W96d00m00s               | 4/4/2007             | Active                | No           |
| Current Condition:         | Fair Condition:                      |                          |                      |                       |              |
|                            | Slightly damaged in                  | n a couple areas, not i  | n need of repairs at | this point.           |              |
|                            |                                      | N111 d0000               |                      |                       |              |
| SF 2                       | Silt Fence                           | N41d00m00s<br>W96d00m00s | 4/2/2007             | Activo                | Yes          |
| Current Condition:         | Fair Condition                       | VV SOUDUIIIUUS           | 4/2/2007             | Active                | res          |
| Current Condition.         | -Maintenaced by C                    | S 6/2008                 |                      |                       |              |
|                            | Silt fence is either o               | down/damaged, or und     | dermined and requir  | es maintenace.        |              |
|                            |                                      | s informed of repair sil | t fence that need to | be completed by 0     | 7/05/08. Not |
|                            | completed prior to l                 |                          |                      |                       |              |
|                            |                                      | N41d00m00s               |                      | Domesiad              |              |
| SF 3<br>Current Condition: | Silt Fence                           | W96d00m00s               |                      | Removed               |              |
| Current Condition:         | Removed per gradi                    | ng mounication.          |                      |                       |              |
|                            |                                      | N144-10000               |                      |                       |              |
|                            |                                      | N41000m00s               |                      |                       |              |
| SF 4                       | Silt Fence                           | N41d00m00s<br>W96d00m00s |                      | Removed               |              |

| SF 5                       | Silt Fence  | N41d00m00s<br>W96d00m00s  | 4/20/2007                                   | Active            | Yes                 |
|----------------------------|---|---|---|-------------------|---------------------|
| Current Condition:         | Fair Condition  | W 90000111003   | 4/20/2007                                   | Active            | 163                 |
|                            | replaced or repair<br>Boyer & Young wa<br>Schwendiman was | /damaged in one spot, a<br>ed.<br>as informed of repair silt<br>s sent an e-mail on 10-3<br>ipleted as last inspectio | fence that need to<br>3-08 stating that the | be completed by ( | )7/05/08. Lee       |
| SF 6                       | Silt Fence  | N41d00m00s<br>W96d00m00s  | 4/5/2007                                    | Active            | No                  |
| Current Condition:         | Good Condition  |   |   |                   |                     |
| SF 7<br>Current Condition: | Silt Fence<br>Good Condition                              | N41d00m00s<br>W96d00m00s  | 4/5/2007                                    | Active            | No                  |
| Current Condition.         |   | pleted prior to inspectior  | n on 7/24/08 by Nic                         | k Wenninghoff.    |                     |
| SF 8                       | Silt Fence  | N41d00m00s<br>W96d00m00s  | 4/5/2007                                    | Active            | Yes                 |
|                            | Boyer & Young wa  | mined in two spots, and<br>as informed of repair silt<br>ast inspection due to hea                                    | fence that need to                          | be completed by 6 | 6/27/08. Not        |
| SF 9<br>Current Condition: | Silt Fence  | N41d00m00s<br>W96d00m00s  | 4/5/2007                                    | Active            | Yes                 |
| SF 10                      |   | mined in the north hook<br>as informed of repair silt<br>last inspection.<br>N41d00m00s<br>W96d00m00s                 |   | be completed by C | 07/05/08. Not<br>No |
| Current Condition:         | Removed due to c  |   |   |                   | -                   |
| SF 11                      | Silt Fence  | N41d00m00s<br>W96d00m00s  | 4/5/2007                                    | Active            | Yes                 |
| Current Condition:         | Boyer & Young wa  | 1   | fence that need to                          | be completed by 6 | 6/27/08. Not        |
| SF 12                      | Silt Fence  | N41d00m00s<br>W96d00m00s  | 4/5/2007                                    | Active            | Yes                 |
| Current Condition:         | Boyer & Young wa  | mined in the middle of t<br>as informed of repair silt<br>ast inspection due to hea<br>last inspection.               | fence that need to                          | be completed by 6 | 6/27/08. Not        |
| SF 13                      | Silt Fence  | N41d00m00s<br>W96d00m00s  | 4/5/2007                                    | Active            | Yes                 |

| Good Condition  | Good Condition<br>Silt fence is undermined in the middle of the run, and needs to be backfilled and compacted.   |  |   |  |  |
|---|--|--|---|--|--|
| Silt fence is underr  |  |  |   |  |  |
| Boyer & Young wa  | as informed of repair silt   | fence that need to   | be compelted by 6   | 6/27/08. Not   |  |
|   |  | avy rains; new com   | pletion date set for  | r 7/5/08. Not  |  |
|   | ·  |  |   |  |  |
| Silt Fence  | N41d00m00s<br>W96d00m00s   | 4/5/2007   | Active  | Yes  |  |
| Good Condition  |  |  |   |  |  |
| Silt fence is underr  | Silt fence is undermined in the middle of the run, and needs to be backfilled and compacted  |  |   |  |  |
| Boyer & Young wa  | as informed of repair silt   | fence that need to   | be compelted by   | 6/27/08. Not   |  |
| completed as of la  | st inspection due to hea   |  |   |  |  |
| completed prior to  |  |  |   |  |  |
| Silt Fence  | W96d00m00s   | 4/5/2007   | Active  | Yes  |  |
| Good Condition  |  |  |   |  |  |
| Silt fence is under   | Cill force is undermined in the middle of the run, and needs to be backfilled and compared   |  |   |  |  |
|   |  | ne run, and needs  | to be backfined an  | d compacted  |  |
| Boyer & Young wa  | Boyer & Young was informed of repair silt fence that need to be compelted by 6/27/08. Not  |  |   |  |  |
| a superior to a set la  |  |  |   |  |  |
| completed as of la<br>completed prior to  | st inspection due to hea   |  |   |  |  |
|   | st inspection due to hea   |  |   |  |  |
| completed prior to<br>Silt Fence  | st inspection due to hea<br>last inspection.   |  |   |  |  |
| completed prior to Silt Fence Good Condition  | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s   | avy rains; new com   | pletion date set for  | r 7/5/08. Not  |  |
| Completed prior to<br>Silt Fence<br>Good Condition<br>-Maintenaced by C   | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008  | avy rains; new com<br>6/25/2007  | pletion date set for<br>Active  | r 7/5/08. Not  |  |
| Completed prior to<br>Silt Fence<br>Good Condition<br>-Maintenaced by C   | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s   | avy rains; new com<br>6/25/2007  | pletion date set for<br>Active  | r 7/5/08. Not  |  |
| completed prior to<br>Silt Fence<br>Good Condition<br>-Maintenaced by C<br>Silt fence is underr   | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008  | avy rains; new com<br>6/25/2007<br>moved East or rep   | pletion date set for<br>Active<br>aired.  | r 7/5/08. Not  |  |
| completed prior to<br>Silt Fence<br>Good Condition<br>-Maintenaced by C<br>Silt fence is underr   | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008<br>mined and needs to be<br>as informed of repair silt   | avy rains; new com<br>6/25/2007<br>moved East or rep   | pletion date set for<br>Active<br>aired.  | r 7/5/08. Not  |  |
| completed prior to<br>Silt Fence<br>Good Condition<br>-Maintenaced by C<br>Silt fence is underr<br>Boyer & Young wa<br>completed prior to   | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008<br>mined and needs to be<br>as informed of repair silt<br>last inspection.<br>N41d00m00s   | 6/25/2007  | Active  | 7/5/08. Not<br>Yes   |  |
| completed prior to<br>Silt Fence<br>Good Condition<br>-Maintenaced by C<br>Silt fence is underr<br>Boyer & Young wa<br>completed prior to<br>Streets  | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008<br>mined and needs to be<br>as informed of repair silt<br>last inspection.<br>N41d00m00s<br>W96d00m00s   | 6/25/2007<br>6/25/2007<br>moved East or rep<br>fence that need to<br>3/20/2007   | pletion date set for<br>Active<br>aired.  | r 7/5/08. Not  |  |
| completed prior to<br>Silt Fence<br>Good Condition<br>-Maintenaced by C<br>Silt fence is underr<br>Boyer & Young wa<br>completed prior to<br>Streets  | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008<br>mined and needs to be<br>as informed of repair silt<br>last inspection.<br>N41d00m00s   | 6/25/2007<br>6/25/2007<br>moved East or rep<br>fence that need to<br>3/20/2007   | Active  | 7/5/08. Not<br>Yes   |  |
| completed prior to<br>Silt Fence<br>Good Condition<br>-Maintenaced by C<br>Silt fence is underr<br>Boyer & Young wa<br>completed prior to<br>Streets<br>Good Condition- N   | st inspection due to hea<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008<br>mined and needs to be<br>as informed of repair silt<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>lo major signs of track c                                | avy rains; new com<br>6/25/2007<br>moved East or rep<br>fence that need to<br>3/20/2007<br>off.  | Active  | r 7/5/08. Not<br>Yes<br>07/05/08. No<br>No   |  |
| completed prior to         Silt Fence         Good Condition         -Maintenaced by C         Silt fence is underr         Boyer & Young wa         completed prior to         Streets         Good Condition- N         Signs         Good Condition. | st inspection due to hear<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008<br>mined and needs to be<br>as informed of repair silt<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>lo major signs of track of<br>1 sign                    | 6/25/2007<br>6/25/2007<br>moved East or rep<br>fence that need to<br>3/20/2007   | Active  | 7/5/08. Not<br>Yes   |  |
| completed prior to         Silt Fence         Good Condition         -Maintenaced by C         Silt fence is underr         Boyer & Young wa         completed prior to         Streets         Good Condition- N         Signs                         | st inspection due to hear<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>CS 6/2008<br>mined and needs to be<br>as informed of repair silt<br>last inspection.<br>N41d00m00s<br>W96d00m00s<br>lo major signs of track of<br>1 sign                    | avy rains; new com<br>6/25/2007<br>moved East or rep<br>fence that need to<br>3/20/2007<br>off.  | Active  | r 7/5/08. Not<br>Yes<br>07/05/08. No<br>No   |  |
| -   | Silt fence is under<br>Boyer & Young wa<br>completed as of la<br>completed prior to<br>Silt Fence<br>Good Condition<br>Silt fence is under<br>Boyer & Young wa<br>completed as of la<br>completed prior to<br>Silt Fence<br>Good Condition<br>Silt Fence | Silt fence is undermined in the middle of the Boyer & Young was informed of repair silt completed as of last inspection due to heat completed prior to last inspection.          Silt Fence       N41d00m00s         Good Condition       W96d00m00s         Silt fence is undermined in the middle of the mid | Silt fence is undermined in the middle of the run, and needs         Boyer & Young was informed of repair silt fence that need to completed as of last inspection due to heavy rains; new com completed prior to last inspection.         Silt Fence       N41d00m00s         Silt Fence       W96d00m00s         Good Condition       Silt fence is undermined in the middle of the run, and needs         Boyer & Young was informed of repair silt fence that need to completed as of last inspection due to heavy rains; new com completed prior to last inspection.         Silt Fence       N41d00m00s         Boyer & Young was informed of repair silt fence that need to completed as of last inspection.         Silt Fence       N41d00m00s         Silt Fence       N41d00m00s         Silt Fence       N41d00m00s         Silt Fence       W96d00m00s         Silt Fence       Silt fence is undermined in the middle of the run, and needs         Silt fence is undermined in the middle of the run, and needs | Silt fence is undermined in the middle of the run, and needs to be backfilled an         Boyer & Young was informed of repair silt fence that need to be compelted by a completed as of last inspection due to heavy rains; new completion date set for completed prior to last inspection.         Silt Fence       N41d00m00s         Silt Fence       W96d00m00s         Good Condition       Active         Silt fence is undermined in the middle of the run, and needs to be backfilled an         Boyer & Young was informed of repair silt fence that need to be compelted by a completed as of last inspection due to heavy rains; new completion date set for completed as of last inspection.         Silt Fence       N41d00m00s         Silt Fence       Silt fence is undermined in the middle of the run, and needs to be backfilled and the set for completed prior to last inspection.         Silt Fence       Silt fence is undermined in the middle of the run, and needs to be backfilled and the set for completed prior to last inspection.         Silt fence is undermined in the middle of the run, and needs to be backfilled and the set for completed prior to last inspection. |  |