E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Comments:



Zachary A. Jilek, CPESC, CISEC ENGINEERING • PLANNING • FIELD SERVICES Erosion Control Specialist- Manager E&A - P2004.020.000 Stage Inspector: Mike Jacobson, CISEC **Palisades** NER110500 Project Name: 9/11/2010 For Week Ending: 68136 168th & Cornhusker Road- Omaha, NE (Sarpy County) Project Location: RAIN FALL AMOUNTS Amount in tenths Date inspected Sunday: 0.00" Monday 0.22 8/18/10 Tuesday 0.65 Wednesday 0.00" 0.00" Thursday Friday 0.12" Saturday 0.00" Sunday: 0.00" Monday 1.26" Tuesday 0.42 08/24/10 Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00" Tuesday 0.10" Wednesday 0.39" Thursday 0.01 09/02/10 0.00" Friday Saturday 0.00" Sunday: 0.00" Monday Trace Tuesday 0.00" Wednesday 0.00" Thursday 0.03" Friday 0.05" Saturday 0.00" Sunday: N/A N/A N/A Monday N/A Tuesday N/A N/A Wednesday Thursday N/A N/A Friday Saturday N/A N/A None Complaints: Construction Sequencing: sins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days? Entire site; grading completed and site seeded Spring 2005. Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? Entire site; grading completed and site seeded Spring 2005. sures listed in this section are being implemented? Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around SB 3 and where silt was placed was re-seeded (4/2009)

Comments:

Home construction is active in varies areas on site.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1) Some required maintenance in the BMP section.

| | | | Projected Install | | | | |
|--|---|--|---|--|--|--|--|
| Unique Name | Туре | Location | Date | Status | Maintenan | | |
| Lot 21 | Silt Fence | Lot 21 | 4/29/2010 | Active | Yes | | |
| Current Condition: | Fair Condition- Active hor | me construction on lot | | | | | |
| | Dumpster was emptied prior to inspection on 8/18/10 by Urban Homes. | | | | | | |
| | Lot level silt fence needs to be installed. As of inspection 5/11/10 silt fence was installed, but it was not | | | | | | |
| | trenched in correctly and it needs to be installed. As of inspection 3/11/10 slit felice was installed, but it was not | | | | | | |
| | across the front of the lot has been partially removed and it needs to be reinstalled. Silt fence needs to be | | | | | | |
| | installed on the North side of the lot. | | | | | | |
| | On 5/11/10 , 6/2/10, 6/22/10, 7/5/10 and again on 8/24/10 Urban Homes was called and left a message | | | | | | |
| | informing them that silt fence needs to be installed correctly ASAP. Maintenance not completed as of last inspection. | | | | | | |
| | mopeodori. | | | | | | |
| Lot 51 | Misc/Other | Lot 51 | | Removed | | | |
| Current Condition: | Lot was sodded prior to in | | y Timberline Homes. | Ttomoved | | | |
| | | | | | | | |
| Lot 62 | Silt Fence | Lot 62 | 7/12/2010 | Active | Yes | | |
| Current Condition: | Pending- Active home co | nstruction on lot. | | | | | |
| | Lot level silt fence needs | to be installed along (| Chutney Drive. | | | | |
| | | · · | | | | | |
| | Builder is unknow. On 7/1 | | | | | | |
| | this lot. Once builder is de has not gotten back to ins | | | | | | |
| | time. | | | | | | |
| 1.400 | 0.11. 5 | 1.100 | 7/40/0040 | A | V | | |
| Lot 80 Current Condition: | Silt Fence Silt fence is no longer nee | Lot 80 | 7/12/2010 | Active | Yes erwood Homes | | |
| Current Condition. | Oilt refice is no longer flet | caea ade to lot bellig t | souded prior to inspecti | on on 773/10 by on | crwood riomes. | | |
| | Part of the outlot behind t | he lot was disturbed a | and needs to be re-seed | led. | | | |
| | Puildor is unknow On 7/1 | 2/10 Inspector has or | mailed Nie w/ Pover Vo | ing acking him who | the builder is a | | |
| | Builder is unknow. On 7/12/10 Inspector has emailed Nic w/ Boyer Young asking him who the builder is or this lot. Once builder is determined then maintenance will address accordly. As of today Nic w/ Boyer You | | | | | | |
| | has not gotten back to ins | | | | | | |
| | complete maintenance A | SAP. | | | | | |
| Lot 81 | Silt Fence | Lot 81 | 8/18/2010 | Active | No | | |
| Current Condition: | Good Condition- Active h | | | 710070 | | | |
| | Silt fence was installed or | n the back of the lot p | ior to increation on 0/4 | 0/401 01 | | | |
| | | | ior to inspection on 6/1 | 8/10 by Sherwood | Homes. | | |
| Lot 101 | | | lor to inspection on 6/1 | 8/10 by Sherwood | Homes. | | |
| Current Condition: | Silt Fence | Lot 101 | 4/9/2010 | Active | Homes. | | |
| Current Condition: | Good Condition- Vacant I | ot. | 4/9/2010 | Active | No | | |
| Current Condition: | | ot. | 4/9/2010 | Active | No | | |
| Current Condition: | Good Condition- Vacant I Empty lot was cleaned up | ot. | 4/9/2010 | Active | No | | |
| Lot 113 | Good Condition- Vacant I Empty lot was cleaned up Construction. | ot. o and the disturbed are Lot 113 | 4/9/2010 ea was re-seeded prior 5/4/2010 | Active | No | | |
| | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence | ot. o and the disturbed an Lot 113 e check installed on lo | 4/9/2010 ea was re-seeded prior 5/4/2010 ot. Vacant lot. | Active to inspection on 7/2 | No 21/10 by Muhle | | |
| Lot 113 | Good Condition- Vacant I Empty lot was cleaned up Construction. | ot. o and the disturbed an Lot 113 e check installed on lo | 4/9/2010 ea was re-seeded prior 5/4/2010 ot. Vacant lot. | Active to inspection on 7/2 | No 21/10 by Muhle | | |
| Lot 113 | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence | ot. o and the disturbed an Lot 113 e check installed on lo | 4/9/2010 ea was re-seeded prior 5/4/2010 ot. Vacant lot. | Active to inspection on 7/2 | No 21/10 by Muhle | | |
| Lot 113 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence Silt fence was tied up ins Silt Fence Good Condition- Silt fence | ot. Do and the disturbed and the disturbed and the disturbed and the theoretical tension of the theor | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. | Active to inspection on 7/2 Active | No 21/10 by Muhle No | | |
| Lot 113 Current Condition: Lot 134 | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence Silt fence was tied up ins Silt Fence | ot. Do and the disturbed and the disturbed and the disturbed and the theoretical tension of the theor | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. | Active to inspection on 7/2 Active | No 21/10 by Muhle No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence Silt fence was tied up ins Silt Fence Good Condition- Silt fence Silt fence was tied up by | ot. Lot 113 e check installed on locector during inspectio Lot 134 e check installed on locector during inspection during inspection during inspection during inspection during inspection during inspection during inspection. | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. | Active to inspection on 7/2 Active Active | No 21/10 by Muhle No | | |
| Lot 113 Current Condition: Lot 134 | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence Silt fence was tied up ins Silt Fence Good Condition- Silt fence | Lot 113 e check installed on locector during inspection Lot 134 e check installed on locector during inspection | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. ection on 6/22/10. | Active to inspection on 7/2 Active Active | No 21/10 by Muhle No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fenc Silt fence was tied up ins Silt Fence Good Condition- Silt fenc Silt fence was tied up by Silt Fence | Lot 113 e check installed on lot lot 134 e check installed on lot lot 134 e check installed on lot inspection during inspection during inspection for 207 | 4/9/2010 ea was re-seeded prior 5/4/2010 tt. Vacant lot. on on 8/24/10. 6/9/2010 tt. Vacant lot. ection on 6/22/10. | Active to inspection on 7/2 Active Active | No 21/10 by Muhle No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fenc Silt fence was tied up ins Silt Fence Good Condition- Silt fenc Silt fence was tied up by Silt Fence Silt fence was removed ponce there is active home | Lot 113 e check installed on lot lot 134 e check installed on lot lot 134 e check installed on lot inspection during inspection during inspection for 207 | 4/9/2010 ea was re-seeded prior 5/4/2010 tt. Vacant lot. on on 8/24/10. 6/9/2010 tt. Vacant lot. ection on 6/22/10. | Active to inspection on 7/2 Active Active Removed be responsible to responsib | No 21/10 by Muhle No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence Silt fence was tied up ins Silt Fence Good Condition- Silt fence Silt fence was tied up by Silt Fence Silt fence was tied up by Silt Fence Silt fence was removed ponce there is active home | Lot 113 e check installed on lopector during inspection Lot 134 e check installed on lopector during inspection during inspection during inspection during inspection on 8 expection on the local loca | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. ection on 6/22/10. | Active to inspection on 7/2 Active Active | No 21/10 by Muhle No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fenc Silt fence was tied up ins Silt Fence Good Condition- Silt fenc Silt fence was tied up by Silt Fence Silt fence was removed ponce there is active home | Lot 113 e check installed on lopector during inspection Lot 134 e check installed on lopector during inspection during inspection during inspection during inspection on 8 expection on the local loca | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. ection on 6/22/10. | Active to inspection on 7/2 Active Active Removed be responsible to responsib | No 21/10 by Muhle No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 Current Condition: Lot 213 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence Silt Fence was tied up ins Silt Fence Good Condition- Silt fence Silt fence was tied up by Silt Fence Silt fence was tied up by Silt Fence Silt fence was removed ponce there is active home Silt Fence/Other Lot was sodded prior to in | Lot 113 e check installed on locector during inspection Lot 134 e check installed on locector during inspection during inspection during inspection on seconstruction on the local l | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. ection on 6/22/10. | Active to inspection on 7/3 Active Active Removed be responsible to r | No 21/10 by Muhle No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fence Silt fence was tied up ins Silt Fence Good Condition- Silt fence Silt fence was tied up by Silt Fence Silt fence was tied up by Silt Fence Silt fence was removed ponce there is active home | Lot 113 e check installed on locector during inspection Lot 134 e check installed on locector during inspection during inspection during inspection on 8 construction on the location on 8/18/10 location on | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. ection on 6/22/10. //24/10. The builder will ot. ov McCaul Homes. | Active to inspection on 7/2 Active Active Removed be responsible to responsib | No 21/10 by Muhle No No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 Current Condition: Lot 213 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fenc Silt fence was tied up ins Silt Fence Good Condition- Silt fenc Silt fence was tied up by Silt Fence Silt fence was removed p once there is active home Silt Fence/Other Lot was sodded prior to in | Lot 113 e check installed on locector during inspection Lot 134 e check installed on locector during inspection during inspection during inspection on 8 construction on the location on 8/18/10 location on | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. ection on 6/22/10. //24/10. The builder will ot. ov McCaul Homes. | Active to inspection on 7/2 Active Active Removed be responsible to responsib | No 21/10 by Muhle No No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 Current Condition: Lot 213 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fenc Silt fence was tied up ins Silt Fence Good Condition- Silt fenc Silt fence was tied up by Silt Fence Silt fence was removed p once there is active home Silt Fence/Other Lot was sodded prior to in | Lot 113 e check installed on locector during inspection Lot 134 e check installed on locector during inspection during inspection during inspection on 8 construction on the location on 8/18/10 location on | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. ection on 6/22/10. //24/10. The builder will ot. ov McCaul Homes. | Active to inspection on 7/2 Active Active Removed be responsible to responsib | No 21/10 by Muhle No No No | | |
| Lot 113 Current Condition: Lot 134 Current Condition: Lot 207 Current Condition: Lot 213 Current Condition: | Good Condition- Vacant I Empty lot was cleaned up Construction. Silt Fence Good Condition- Silt fenc Silt fence was tied up ins Silt Fence Good Condition- Silt fenc Silt fence was tied up by Silt Fence Silt fence was removed p once there is active home Silt Fence/Other Lot was sodded prior to in | Lot 113 e check installed on locector during inspection Lot 134 e check installed on locector during inspection during inspection during inspection on 8 construction on the location on 8/18/10 location on | 4/9/2010 ea was re-seeded prior 5/4/2010 et. Vacant lot. on on 8/24/10. 6/9/2010 et. Vacant lot. ection on 6/22/10. //24/10. The builder will ot. ov McCaul Homes. | Active to inspection on 7/2 Active Active Removed be responsible to responsib | No 21/10 by Muhle No No einstall silt feno | | |

| Current Condition: | Good ConditionActive has Silt fence check installed | | | // Charleston Home | s. | |
|-------------------------------|---|--|--------------------------|--------------------|------------------------|--|
| Lot 257 | Silt Fence | Lot 257 | 7/15/2010 | Active | No | |
| Current Condition: | Removed- Active home construction on lot. Dirt piled in the R.O.W. was removed prior to inspection on 7/15/10 by Sudbeck construction. Silt fence check was removed and the lot has been fine graded prior to inspection on 9/2/10 by Sudbeck construction. | | | | | |
| Lot 303 | Silt Fence | Lot 303 | | Removed | | |
| Current Condition: | Silt fence was removed | | lded prior to inspection | | Construction. | |
| Lot 313 | Silt Fence | Lot 313 | 4/29/2010 | Active | Yes | |
| Current Condition: | Good Condition- Silt fence installed on the back of the lot. Active home construction on lot. Sand and gravel in the street and R.O.W. and the dirt in the R.O.W. was removed prior to inspection on 5/11/10 by Horizon Homes. Lot level silt fence needs to be installed on the front of the lot. Horizon Homes was informed to install silt fence by 4/29/10. On 8/18/10 Horizon Homes was called and left a message reminding them that maintenance needs to be completed ASAP. | | | | | |
| Lot 389 | Silt Fence | Let 390 | 8/18/2010 | Active | Voc | |
| Current Condition: | Pending- Active home co | Lot 389 onstruction on lot. | G/10/2010 | Active | Yes | |
| | Lot level silt fence needs Horizon Homes was info | | | ince not completed | as of last inspection. | |
| Lot 402 | Silt Fence | Lot 402 | 4/29/2010 | Active | No | |
| Current Condition: | Good Condition- Silt fend Additional silt fence was | | | | t. | |
| | Additional Sill Terice was | installed prior to inspec | ction on 7/5/10 by Zych | Construction. | | |
| Lot 418 Current Condition: | Silt Fence Lot was sodded prior to | Lot 418 | Charusad Hamas | Removed | | |
| Lot 420 Current Condition: | Silt Fence Pending- Active home co | Lot 420 onstruction on lot. | 9/1/2010 | Active | Yes | |
| | Lot level silt fence needs to be installed on the back of the lot. Charleston Homes was informed to install silt fence by 8/25/10. Silt fence was installed prior to inspection on 9/1/10 by Charleston Homes. | | | | | |
| Lot 423 | Silt Fence | Lot 423 | | Removed | | |
| Current Condition: | Silt fence was removed proceeds seeded/matted. | | /15/10 by CS as it is no | | e the area being | |
| | | N41d00m00s | | | | |
| SB 1 Current Condition: | Sediment Basin Good Condition - 31% Fi Cleaned out 06/05 | W96d00m00s illed | In Place | Active | No | |
| SB 2 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No | |
| Current Condition: | This has been convert to | | | HOUVE | 140 | |
| SB 3 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Activo | No | |
| Current Condition: | Good Condition - 18% Fi | illed | | Active | No | |
| | Clean out was completed | | 1/22/09 by M.E. Collin | S. | | |
| SB 4 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No | |
| Current Condition: | Good Condition - 39% Fit Cleaned out 07/05 | illed | | | | |
| 05.4 | | N41d00m00s | | D | | |
| SF 1 Current Condition: | Silt Fence W96d00m00s Removed The remainder of silt fence was removed prior to inspection on 8/8/09 by Boyer Young due to good vegetation. The builder will be responsible for re-installation of silt fence prior to activity home construction in this area. Lot 293 was sodded prior to inspection on 9/28/09 by Jeff w/ McCaul Homes, therefore the silt fence is no longer needed. | | | | | |
| ST 1 Current Condition: | Silt Trap Removed; berm constru | N41d00m00s W96d00m00s cted and area matted a | and seeded. | Removed | | |

| STR | Streets | N41d00m00s W96d00m00s | In Place | Active | Yes | |
|----------------------|--|--------------------------|-----------|--------------|-----------------|--|
| Current Condition: | Fair Condition- | | | | | |
| | Some minor signs of run off and needs to be cleaned up. | | | | | |
| | Boyer Young was informed to clean up streets by 9/3/10. | | | | | |
| SWPPP Sign | SWPPP Sign | Three signs on site | 3/28/2008 | Active | No | |
| Current Condition: | Good Condition On 3/28/08 inspector install SWPPP a sign at 172nd & Cornhusker Rd., 168th & Chutney Dr and 168th & Palisades Drive entrance. | | | | | |
| Inspector Signature: | I Jawlan | | | Reviewed By: | adnary L. Jilde | |