E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



E&A CONSULTING GROUP, INC. ENGINEERING • PLANNING • FIELD SERVICES

| Zachary A. Jilek, CPESC, CISEC Erosion Control Specialist- Manag | or | | ENGINE | EERING • PLANN | ING • FIELD SERVICE |
|---|---------------------------------|------------------------------|------------------------------|----------------------|------------------------|
| LIUSION CONTO Specialist- Manag | ei | E&A - P2004.020 | .000 | | |
| nspector: Mike Jacobson, CISEC | | | | | Stage |
| | | Palie | sades | | 3 |
| | | | | | |
| Project Name: | | | 10500 | | |
| For Week Ending: | | 2/12 | /2011 | | |
| Project Location: | 1681 | h & Cornhusker Road | · Omaha, NE (Sarpy C | ounty) | 68136 |
| RAIN FALL AMOUNTS | Amount in tenths Date inspected | | | | |
| | | | | | Weel |
| Sunday: | 0.37" | | | | |
| londay Tuesday | 0.31" | | | | |
| Vednesday | Trace Trace | | | | |
| hursday | Trace | | | | |
| Friday | Trace | | | | |
| Saturday | 0.00" | | | | |
| | | | | | Weel |
| Sunday: | Trace | | | | |
| Nonday | Trace | | | | |
| uesday | 0.04" | | | | |
| Vednesday | 0.12" | | | | |
| hursday | Trace | | | | |
| Friday | 0.00" | | | | |
| Saturday | 0.29" | | | | |
| | | | | | Weel |
| Sunday: | 0.06" | | | | |
| londay | 0.00" | | | | |
| uesday | 0.00" | | | | |
| Vednesday | Trace | | | | |
| hursday | 0.00" | | | | |
| riday | 0.00" | | | | |
| Saturday | 0.00" | | | | |
| Sum day u | Trees | | | | Weel |
| Sunday: | Trace | | | | |
| londay Tuesday | 0.13" 0.25" | | | | |
| Vednesday | 0.00" | | | | |
| hursday | 0.00" | | | | |
| riday | 0.00" | | | | |
| Saturday | 0.00" | | | | |
| aturday | 0.01 | | | | Wee |
| Sunday: | 0.02" | | | | |
| londay | 0.00" | | | | |
| uesday | 0.00" | | | | |
| Vednesday | 0.00" | | | | |
| hursday | 0.00" | 2/10/2011 | | | |
| Friday | 0.00" | - | | | |
| Saturday | 0.00" | | | | |
| - | • | • | • | • | • |
| | None | | | | |
| Complaints: | | | | | |
| | | | | | |
| | | | | | |
| Construction Sequencing: | | | | | |
| /hich portion(s) (i.e. drainage basins) of t | he site have had a tempo | prary or permanent cessation | on of grading, earthwork, or | r ground disturbance | e in the last 14 days? |
| | | | | | |
| ntire site; grading completed and sit | te seeded Spring 200 | 5. | | | |
| | | | | | |
| /hich portion(s) (i.e. drainage basins) of t | he site do not have grad | ing, earthwork, or ground d | isturbance scheduled in th | e next 14 davs? | I |
| | | | | | |
| Entire site; grading completed and sit | ie seeded Spring 200 | ວ. | | | |
| | | | | | |
| | | | | | 1 |
| Vhat temporary or permanent stabilizatior | measures listed in this | section are being impleme | nted? | | |
| | | | | led and seeded/m | att (9/2008): Area |
| aving, seeding (Spring 05), dense v | egetative cover; Drai | nage way west of sedim | | led and seeded/m | att (9/2008); Area |
| | egetative cover; Drai | nage way west of sedim | | ded and seeded/m | att (9/2008); Area |

Comments:

Home construction is active in various areas on site.

Drive thru inspection was conducted due to winter conditions and snow cover.

This project went over on days between inspections to avoid inspecting during winter and/or dangerous driving conditions. Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date): 1) Some required maintenance in the BMP section.

| Unique Name | Туре | Location | Projected Install Date | Status | Maintenance | | |
|--------------------|--|---------------------|---------------------------|---------|-------------|--|--|
| Lot 21 | Silt Fence | Lot 21 | | Removed | | | |
| Current Condition: | Lot was sodded prior to inspection on 9/20/10 by Urban Homes. | | | | | | |
| Lot 5 | Silt Fence | Lot 5 | 2/17/2011 | Pending | Yes | | |
| Current Condition: | Pending- Active home co | onstruction on lot. | | | | | |
| | Lot level silt fence needs to be installed on the back of the lot. There is dirt piled in the R.O.W. and it needs to be removed or add silt fence around it. There is a grate inlet along the front of the lot and it needs silt fence or temporary straw wattle installed above it. | | | | | | |
| | Chris w/ Hearthstone Production was informed to complete maintenance by 12/20/10. Maintenance not completed due to winter conditions, therefore another seven days is given to complete maintenance until 2/17/11. Chris w/ Hearthstone Production was informed to complete maintenance by 2/17/11. Chris w/ Hearthstone Production was informed to complete maintenance by 2/17/11. | | | | | | |
| Lot 22 | Silt Fence | Lot 22 | 9/18/2010 | Active | Yes | | |
| Current Condition: | No BMP's installed on lo Lot was cleaned up prior | t- Vacant lot. | • | 7104110 | | | |
| | The disturbed areas of the lot needs to be re-seeded and silt fence needs to be installed in a few area to prevent from run off until the vegetation is established on the lot due to the home construction that was on lot 21. Urban Homes was called and left a message informing them to complete the maintenance by 9/26/10. Maintenance not completed as of last inspection. As of inspection on 12/13/10 re-seeding of the lot is not going to take place until next spring due to winter conditions. | | | | | | |
| Lot 36 | Silt Fence | Lot 36 | 11/12/2010 | Active | No | | |
| Current Condition: | Good Condition-Active h Silt fence was installed p | | | mes. | | | |
| Lot 81 | Silt Fence | Lot 81 | 8/18/2010 | Active | Yes | | |
| Current Condition: | No BMP installed on the lot- Active home construction on lot. Silt fence was removed due to the lot being fine graded prior to inspection on 11/12/10 by Sherwood Homes Silt fence needs to be reinstalled or the lot needs to be sodded. Sherwood Homes was informed to complete maintenance by 12/21/10. On 12/14/10 Sherwood Homes calle inspector and stated that they are not responsible for re-installing the silt fence on the back of the lot due to the outlot behind their lot needing to be re-graded. The lot is going to be sodded in the spring. Maintenance not completed as of last inspection. | | | | | | |
| Lot 101 | Silt Fence | L ot 101 | 4/9/2010 | Active | No | | |
| Current Condition: | Silt Fence Lot 101 4/9/2010 Active No Good Condition- Vacant lot. Empty lot was cleaned up and the disturbed area was re-seeded prior to inspection on 7/21/10 by Muhle Construction. Construction. | | | | | | |
| Lot 103 | Silt Fence | Lot 103 | 12/20/2010 | Active | No | | |
| Current Condition: | No BMP's is needed on lot at this time- Active home construction on lot. Dirt pile was removed from R.O.W. prior to inspection on 2/10/11 by Mick Smith Construction. | | | | | | |
| Lot 109 | Silt Fence | Lot 109 | 12/20/2010 | Active | Yes | | |
| Current Condition: | No BMP's is needed on lot at this time- Active home construction on lot. Dirt pile was removed from R.O.W. prior to inspection on 2/10/11 by Chris w/ Hearthstone Production. Due to the driveway being paved there is new dirt that is piled in the R.O.W. and it needs to be removed or add silt fence around it. Chris w/ Hearthstone Production was informed to complete maintenance by 2/17/11. | | | | | | |

| Lot 110 Current Condition: | Silt Fence | Lot 110 | 12/20/2010 | Pending | Yes | | | |
|-------------------------------|---|--|-----------------------------|---------------------|-------------------|--|--|--|
| current condition. | Pending- Active home construction on lot. Dirt pile was removed from R.O.W. prior to inspection on 2/10/11 by Chris w/ Hearthstone Production. | | | | | | | |
| | | | | | | | | |
| | 1) Lot level silt fence nee | | | | da ta ha ramaya | | | |
| | Due to the driveway b add silt fence around it. | eing paved there is nev | v dirt that is plied in the | e R.O.W. and it nee | eas to be removed | | | |
| | | | | | | | | |
| | | 1) Chris w/ Hearthstone Production was informed to complete maintenance by 12/20/10. Maintenance not | | | | | | |
| | completed due to winter | conditions, therefore a | nother seven days is gi | iven to complete m | aintenance until | | | |
| | 2/17/11. 2) Chris w/ Hearthstone | Production was informe | ed to complete mainter | ance by 2/17/11 | | | | |
| | | | | | | | | |
| Lot 113 | Silt Fence | Lot 113 | 5/4/2010 | Active | No | | | |
| Current Condition: | Good Condition- Silt fend | | | 7101170 | 110 | | | |
| | | | | | | | | |
| Lot 134 | Silt Fence | Lot 134 | | Removed | | | | |
| Current Condition: | Silt fence check on vaca | nt lot was removed price | or to inspection on 10/1 | 2/10 by Commerci | al Seeding. | | | |
| | | | | | | | | |
| Lot174 | Silt Fence | Lot 174 | 2/17/2011 | Pending | Yes | | | |
| Current Condition: | Pending- Active home co | | 2/11/2011 | rending | 165 | | | |
| | | | | | | | | |
| | Lot level silt fence needs | to be installed on the l | back of the lot. | | | | | |
| | | | | 7/44 | | | | |
| | Carson Custom Homes | was informed to compl | ete maintenance by 2/1 | 7/11 | | | | |
| Lot 180 | Silt Fence | Lot 180 | 11/12/2010 | Active | No | | | |
| Current Condition: | No BMP installed on the | | | Active | INU | | | |
| ourient oonation. | | | | | - | | | |
| | | | | | | | | |
| Lot 185 | Silt Fence | Lot 185 | 11/12/2010 | Active | No | | | |
| Current Condition: | No BMP installed on the | lot- Active home const | ruction on lot. | | | | | |
| | | | | | | | | |
| Lot 291 | Silt Fence | Lot 291 | | Removed | | | | |
| Current Condition: | Lot was sodded prior to | inspection on 12/13/10 | by Charleston Homes. | | | | | |
| | | | | | | | | |
| Lot 292 | Silt Fence | Lot 292 | | Removed | | | | |
| Current Condition: | Lot was sodded prior to i | | by Charleston Homes. | | | | | |
| | | | - | r | 1 | | | |
| 1 | | 1 | 10/1/0010 | A | | | | |
| Lot 299 Current Condition: | Silt Fence Good Condition- Active h | Lot 299 | 12/1/2010 | Active | No | | | |
| Current Condition: | Silt fence was installed o | | | 1/10 by Zych const | truction. | | | |
| | | | | | | | | |
| Lot 347 | Silt Fence | Lot 347 | 12/13/2010 | Active | Yes | | | |
| Current Condition: | Fair Condition- Active ho | me construction on lot. | | | | | | |
| | Sill force is down(domograd and poods to be seen in d | | | | | | | |
| | Silt fence is down/damaged and needs to be repaired. Dream Scape Homes was informed to complete maintenance by 12/20/10. Maintenance not complete | | | | | | | |
| | | | | | | | | |
| | last inspection. | | | | pietea u | | | |
| | | | | | | | | |
| Lot 379 | Silt Fence | Lot 379 | 11/12/2010 | Active | Yes | | | |
| Current Condition: | Fair Condition-Active hor | me construction on lot. | | | | | | |
| | Silt fence is down along | Silt fence is down along the front of the lot and needs to be re-tied. | | | | | | |
| | | | | | | | | |
| | Zych construction was informed to complete maintenance by 2/17/11. | | | | | | | |
| | | | | | | | | |
| Lot 389 | Silt Fence | Lot 389 | 8/18/2010 | Active | Yes | | | |
| Current Condition: | Pending- Active home co | onstruction on lot. | | | | | | |
| | | | | | | | | |
| | Lot level silt fence needs to be installed on the back of the lot. Horizon Homes was informed to install silt fence by 8/25/10. On 9/20/10 Horizon Homes was called and message reminding them that maintenance needs to be completed ASAP. Maintenance not completed last inspection. | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | Silt Fence | Lot 415 | 8/18/2010 | Active | Yes | | | |

| Current Condition: | Pending- Active home c | Pending- Active home construction on lot. Lot level silt fence needs to be installed on the back of the lot. | | | | |
|--------------------|---|---|---------------------|----------------------|----------------|--|
| | Lot level silt fence need | | | | | |
| | Builder is unknown at this time. When builder is determined then they will be informed to complete maintenance. | | | | | |
| SB 1 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No | |
| Current Condition: | | Good Condition - 31% Filled | | | | |
| SB 2 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No | |
| Current Condition: | This has been convert to | This has been convert to permanent pond for the school site. | | | | |
| SB 3 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No | |
| Current Condition: | | Good Condition - 19% Filled Clean out was completed prior to inspection on 1/22/09 by M.E. Collins. | | | | |
| SB 4 | Sediment Basin | N41d00m00s W96d00m00s | In Place | Active | No | |
| Current Condition: | Good Condition - 39% F Cleaned out 07/05 | Good Condition - 39% Filled Cleaned out 07/05 | | | | |
| SF 1 | Silt Fence | N41d00m00s W96d00m00s | | Removed | | |
| Current Condition: | The remainder of silt fer | The remainder of silt fence was removed prior to inspection on 8/8/09 by Boyer Young due to good | | | | |
| ST 1 | Silt Trap | N41d00m00s W96d00m00s | | Removed | | |
| Current Condition: | Removed; berm constru | Removed; berm constructed and area matted and seeded. | | | | |
| STR | Streets | N41d00m00s W96d00m00s | In Place | Active | No | |
| Current Condition: | Good Condition- Street was cleaned up due to the streets being plowed by the county. | | | | | |
| SWPPP Sign | SWPPP Sign | Three signs on site | 3/28/2008 | Active | No | |
| Current Condition: | Good Condition On 3/28/08 inspector in Palisades Drive entranc | nstall SWPPP a sign at 1 ce. | 72nd & Cornhusker F | Rd., 168th & Chutney | Dr and 168th & | |
| spector Signature: | I Jawlam | | | Reviewed By: Za | drany k. Jild | |