E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

	T	E&A - P2004.020			01	
Inspector: Mike Jacobson, CISEC Project Name:			Stage 3			
For Week Ending:		3/10/2012				
Project Location:	168	unty)	68136			
RAIN FALL AMOUNTS	Amount in tenths	Date inspected				
CAINT ALL AMOUNTS	Janoani in tonalo	Date Inspected			Wee	
Sunday:	0.00"					
Monday	0.07"					
Tuesday	0.00"					
Vednesday Thursday	Trace 0.00"					
Friday	0.00"					
Saturday	0.00"					
	0.00#				Wee	
Sunday:	0.00"			+		
Monday Tuesday	0.31" Trace			+		
Wednesday	0.01"			+		
Thursday	0.05"			1		
Friday	0.10"					
Saturday	0.00"					
Sunday	0.00"				Wee	
Sunday: Monday	0.00"			+		
Monday Tuesday	0.00" 0.28"			+		
Wednesday	0.00"				+	
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday:	0.00"					
Monday Tuesday	0.00"	03/06/12				
Wednesday	Trace	03/06/12				
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday:	N/A	N/A				
Monday Tuesday	N/A N/A	N/A N/A		-		
Wednesday	N/A	N/A				
Thursday	N/A	N/A				
Friday	N/A	N/A				
Saturday	N/A	N/A				
	To a					
Complaints:	None					
•						
Construction Sequencing:	site have had a tempora	ry or normanant cosession of	grading parthwork or crown	d disturbance in the lea	et 14 days?	
Which portion(s) (i.e. drainage basins) of the	and have had a tempora	ry or permanent cessation of	grading, carmwork, or groun	a arsturpance in the las	or 14 uays:	
Entire site; grading completed and sit	e seeded Spring 200	5.				
	1	T	1	1		
Which portion(s) (i.e. drainage basins) of the	site do not have grading	. earthwork, or ground distur	bance scheduled in the next	4 days?		
			Same Someanea in the next	- cayo:		
Entire site; grading completed and sit	e seeaea Spring 200	. Jo.				
What tomporary or pormanent stabilization	nageuroe lietad in this	etion are being implemented	2			
What temporary or permanent stabilization in Paving, seeding (Spring 05), dense verses				d and spedad/matt	(9/2008): Area are:::	
SB 3 and where silt was placed was r						
	l					
Comments:						
Comments:						
Home construction is active in various						

## Findings / Corrective Actions (Date):

Some required maintenance in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
Lot 77	Silt Fence	Lot 76	6/25/2011	Active	Yes		
Current Condition:	Fair Condition- The disturbed area was  1) A silt fence check nee 2) The silt fence check o  1) As of inspection on 11 disturbed area has been construction was informe extra days were given du maintenance needs to be 2) Zych construction was	re-seeded prior to insponds to be installed along in the South side of the installed along in the South side of the installed and a silt feed on 11/21/11 to re-installed to the holiday weeke e completed ASAP. Ma	ection on 11/21/11 by Z g the front of the lot. lot is down/damaged a nce has been complete nce check has been in stall silt fence check in t and. On 1/9/12 Zych cor intenance not complete	ych construction.  Ind it needs to be red  If prior to inspection stalled in the wrong the proper location struction was rem d as of last inspec	epaired. In on 11/21/11. The g spot. Zych by 11/30/11. Two inded that		
	2) Zyon donardon was	simonica to complete	Indimendince by 6/16/11				
Lot 217 Current Condition:	Pending- Lot 217 11/10/2011 Pending Yes  Pending- Lot level silt fence needs to be installed on the back of the lot.  Newport Homes was informed to complete maintenance by 11/10/11. Newport Homes was informed of overdue maintenance on 11/21/11 and to complete ASAP. On 1/9/12 and again on 3/6/12 Newport Homes was reminded that maintenance needs to be completed ASAP.						
Lot 352	Silt Fence	Lot 352		Removed			
Current Condition:	Lot was sodded prior to i		y Frontier Construction				
Lot 404	Silt Fence	Lot 404	11/10/2011	Active	No		
Current Condition:	Good Condition- A silt fence check was installed on the Southeast corner of the lot prior to inspection on 3/6/12 by Newport Homes.						
POD A	Silt Fence	Lots 103-133	4/20/2011	Active	Yes		
	1) Lot 112 has a portable toilet that needs to be staked down or removed. 2) Lot 112 and lot 121 has dirt piled in the R.O.W. and it needs to be removed or add silt fence around it. 3) Lot 112 and Lot 119 has silt fence that is damaged on the lots and it needs to be repaired, replaced if needed.  1) Scott W Hearthstone was informed to complete maintenance by 3/14/12. 2) Scott W Hearthstone was informed to complete maintenance by 3/14/12. 3) Scott W Hearthstone was informed to complete maintenance by 3/14/12.						
POD B Current Condition:	Silt Fence Fair Condition- Active ho  1) The Outlot area behin and it needs to be re-gra 2) Lot 112 and lot 121 ha 3) The silt fence on lots  1) As of inspection on 11 was reminded that maint was reminded that maint inspection due to winter allow. On 3/7/12 Scott w/ 2) Scott w/ Hearthstone of 3) Scott w/ Hearthstone of	d lots 142-146 was dar ded out and stabilized. as dirt piled in the R.O.! 144-146 is down/damag 1/21/11 maintenance we enance needs to be co enance needs to be co conditions. Maintenanc / Hearthstone was remi was informed to comple was informed to comple	maged due to the home W. and it needs to be re ged and it needs to be re as not completed. On 1 mpleted ASAP. On 11/ mpleted ASAP. Mainter se will need to be compl nded that maintenance te maintenance by 3/1-	emoved or add silt replaced. 1/21/11 Jeff w/ Hea 30/11 Mert w/ Hear nance not complete teted in the spring needs to be comp 4/12.	fence around it.  arthstone Production thstone Production ad as of last when conditions		
SB 1	Sediment Basin	N41d00m00s W96d00m00s		Removed			
Current Condition:	Basin was removed prior The disturbed area of the	to inspection on 5/12/			1 by CS.		
SB 2 Current Condition:	Sediment Basin This has been convert to	N41d00m00s W96d00m00s permanent pond for th	In Place e school site.	Active	No		
SB 3	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 23% Fi Clean out was completed		1/22/09 by M.E. Collins	s.			

		N41d00m00s					
SB 4	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 39% Filled						
	Cleaned out 07/05						
		N41d00m00s					
SF 1	Silt Fence	W96d00m00s		Removed			
Current Condition:	The remainder of silt fence was removed prior to inspection on 8/8/09 by Boyer Young due to good vegetat						
		N41d00m00s					
ST 1	Silt Trap	W96d00m00s		Removed			
Current Condition:	Removed; berm constructed and area matted and seeded.						
		N41d00m00s					
STR	Streets	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- No major signs of track off.						
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No		
Current Condition:	Good Condition On 3/28/08 inspector i Palisades Drive entran	nstall SWPPP a sign at 17	72nd & Cornhusker R	d., 168th & Chutney	/ Dr and 168th 8		

Inspector Signature: Achael Jawlan

Reviewed By: Zachary K. Jila