E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A - P2004.020.0	000			
Inspector: Matthew Vanicek						
-		Palisa	ndes		Stage	
					3	
Project Name:		NER110500				
For Week Ending:		8/10/2019 168th & Cornhusker Road- Omaha, NE (Sarpy County)				
Project Location:	168th)	68136			
0	1000/	1				
Grading:	100% 100%					
Sanitary Sewer: Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	94%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
					Wee	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.37"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
	0.000				Wee	
Sunday:	0.69"	T/00/00/10	00/07 D // 01			
Monday	0.00"	7/22/2019	80/65 Partly Cloudy			
Tuesday	0.00"					
Wednesday	0.00"					
Thursday Friday	0.03" 0.00"					
Saturday	0.00"					
Saturday	0.00				Wee	
Sunday	0.21"				Wee	
Sunday: Monday	0.00"					
Tuesday	0.04"					
Wednesday	0.01"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday:	0.00"		T			
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.02"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Tuesday	N/A	N/A				
Wednesday	N/A	N/A				
Thursday	N/A	N/A				
Friday	N/A	N/A				
Saturday	N/A	N/A				
	1					
	None					

Construction Sequencing:

Which portion(s) (i.e. drainage pasins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; grading completed and site seeded Spring 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; grading completed and site seeded Spring 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around SB 3 and where silt was placed was re-seeded (4/2009); The drainage area just West of SB 3 was repaired and seeded/matted(10/2011)

Swale down to basin #3 was regraded, seeded and matted prior to inspection on 9/11/2013; Matting was installed on SB 3 Slopes (8/28/2015). The outlot adjacent to lot 204 and the outlot adjacent to lot 88 were seeded and matted (4/25/18).

SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

No, See BMP Section.

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

CHECKLIST QUESTIONS:

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

ust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Home construction is active on one lot as of the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) See BMP Section for required maintenance.

	_			5			
Unique Name	Туре	Location South end of Outlet C	Projected Install Date	Status	Maintenance		
CW 1	Concrete Washout	along Palisades Drive		Removed			
Current Condition:	•		 				
Current Condition.	Removed- Washout pit was removed by Celebrity Homes prior to 11/12/2015. South end of Outlet C						
CW 2	Concrete Washout	along Palisades Drive		Removed			
Current Condition:		was removed by Boyer You	II ing prior to 11/12/2015	rtemoved			
Current Condition.	removed washout pit v	South end of Outlet C					
CW 3	Concrete Washout	along Palisades Drive		Removed			
Current Condition:	Removed - Celebrity Homes removed the washout in preparation for sod on lot 203. The inspector will monitor the need to re-install.						
Lot 24	Individual lot	Lot 24		Removed			
Current Condition:	The lot has naturally vegetated and no runoff was observed during the inspection on 4/25/18. The inspector will remove the lot from the report and continue to monitor the need for stabilization.						
Lot 35 Current Condition:	Silt Fence Fair Condition -	Lot 35	4/25/2018	Active	Yes		
	The silt fence needs repaired/reinstalled on the sides of the lot that face the street. Nathan Dalrymple was informed to complete by 10/18/18. Not done as of the last inspection. Nathan Dalrymple was reminded on 2/1/19, 3/16/19, 5/25/19, 7/6/19						
Lot 88	Silt Fence	Lot 88		Removed			
Current Condition:		m Homes sodded the lot p	rior to the inspection on 10				
Lot 386	Silt Fence	Lot 386		Removed			
Current Condition:		mes sodded the lot prior to	the inspection on 4/25/18				
Lot 387	Silt Fence	Lot 387		Removed			
Current Condition:		mes sodded the lot prior to					
SB 3	Sediment Basin	Commercial Lot #5	In Place	Active	No		
Current Condition:	Good Condition - 15% F	illed-Cleaned out was com	pleted prior to inspection o	on 7/31/15 by Dusty	Roth.		
CD 4	Cadimant Basis	173rd Street and		Damassad			
SB 4 Current Condition:	Sediment Basin	Palisades Drive moved prior to the inspection	n an 2/24/46	Removed			
Current Condition:	Removed- basin was rei	Cornhusker, 168th, and) 0 3/24/ 16. 				
STR	Streets	Interior Streets	In Place	Active	Yes		
Current Condition:	Fair Condition - No track	out was observed during t	he inspection on 8/22/18.				

SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No
Current Condition:	Good Condition- On 3/28	0/08 inspector installed SW	PPPs at 172nd & Cornhu	sker Rd., 168th & 0	Chutney Dr and 168th
	& Palisades Drive entran	ce.			
Inspector Signature:				Reviewed By:	Cot Se