E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

		E&A - P2004.	020.000		
nspector: Shaun McGuire					Stage
		- Ciago			
		3			
Project Name:		68136			
or Week Ending:					
Project Location:	168				
A	4000				
Grading: Ganitary Sewer:	1009				
Storm Sewer:	1009				
Paving:	100%				
Seeding:	100%				
Itilities:	1009	6			
Overall Development:	99%	6			
AIN FALL AMOUNTS	Ta a a a a		Too a second	I	1
AIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration
unday:	0.00"				We
unday: londay	0.00	+			+
uesday	0.29"	+			6:45 AM - 5:00 PM
Vednesday	0.00"	4/17/2024	Sunny 69/45	10:45 AM	J J / III J J J J J J J J J J J J J J J J
hursday	0.12"		2, 00		1
riday	0.00"				
aturday	0.00"				
	0.00"				We
Sunday:	0.00"				
londay	0.00"				
uesday	0.00"				
Vednesday Thursday	0.00" 0.01"				
riday	0.97"	4/26/2024	Rain 73/53	9:35AM	12:00 AM - 5:00 PM
Saturday	0.10"	4/20/2024	Rain 75/55	3.33AW	12.007441 0.001441
					We
Sunday:	0.16"				10:00 AM - 4:00 PM
Monday	0.00"	4/29/2024	Sunny 71/52	10:00 AM	
uesday	0.18"				
Vednesday	0.07"				
hursday	0.44"	5/2/2024	Overcast 63/46	8:30 AM	3:30 AM - 7:00 AM
riday	0.00"				
aturday	0.67"				1:00 AM - 4:00 AM We
unday:	0.00"				vve
londay	0.66"	5/6/2024	Cloudy 70/52	11:20 AM	6:15 PM - 12:00 AM
uesday	0.02"	5/7/2024	Sunny 74/53	2:35 PM	12:00 AM - 1:00 AM
Vednesday	0.00"	J.172024		2.00 1 111	
hursday	0.00"				
riday	0.00"				
aturday	0.00"				
	N/A				We
Sunday:	N/A				
Monday	N/A	+			1
uesday Vednesday	N/A N/A	+			+
hursdav	N/A N/A	+			+
riday	N/A	+			+
Saturday	N/A				1
•	<u>t</u>	1		1	ı
omplaints:	None				
onstruction Sequencing:					
thich portion(e) (i.e. drainage basins) of	of the site have had a temporary	or permanent cessation of	grading, earthwork, or ground dis	turbance in the last 14	davs?

Entire site; grading completed and site seeded Spring 2005.

Paving, seeding (Spring 05), dense vegetative cover; Drainage way west of sediment basin 3 was re-graded and seeded/matt (9/2008); Area around SB 3 and where silt was placed was re-seeded (4/2009); The drainage area just West of SB 3 was repaired and seeded/matted(10/2011)

Swale down to basin #3 was regraded, seeded and matted prior to inspection on 9/11/2013; Matting was installed on SB 3 Slopes (8/28/2015). The outlot adjacent to lot 204 and the outlot adjacent to lot 88 were seeded and matted (4/25/18).

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

s dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

Home construction was inactive as of the last inspection.

Findings / Corrective Actions (Date)

Findings / Corrective Actions (Date):

1.) No maintenance is required in the BMP section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		South end of Outlet C					
CW 1	Concrete Washout	along Palisades Drive		Removed			
Current Condition:	Removed - Washout pit was removed by Celebrity Homes prior to 11/12/2015.						
		South end of Outlet C					
CW 2	Concrete Washout	along Palisades Drive		Removed			
Current Condition:	Removed - Washout pit was removed by Boyer Young prior to 11/12/2015.						
		South end of Outlet C					
CW 3	Concrete Washout	along Palisades Drive		Removed			
Current Condition:	Removed - Celebrity Homes removed the washout in preparation for sod on lot 203. The inspector will monitor the n						
	to re-install.						
SB 3	Sediment Basin	Commercial Lot #5	In Place	Active	No		
Current Condition:	Good Condition - 25% Filled - Clean out was completed prior to inspection on 7/31/15 by Dusty Roth.						
		173rd Street and					
SB 4	Sediment Basin	Palisades Drive		Removed			
Current Condition:	Removed - Basin was removed prior to the inspection on 3/24/16.						
		Cornhusker, 168th, and					
STR	Streets	Interior Streets	In Place	Active	No		
Current Condition:	Good Condition - The streets around lot 35 were clean as of the inspection on 12/5/19. Story Homes LLC cleaned the						
	streets around lot 24 prior to the 4/26/22 inspection.						
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No		
Current Condition:	Good Condition - On 3/28/08 inspector installed SWPPPs at 172nd & Cornhusker Rd., 168th & Chutney Dr and 168						
	Palisades Drive entrance.						
Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my						
ocitalogion Gatement.	direction or supervision in accordance with a system designed to assure that qualified personnel						
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or						
	persons who manage the system or those persons directly responsible for gathering the information,						
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I						
	am aware that there are significant penalties for submitting false information including the possibility						
	of fines and imprisonment for knowing violations."						
	41 C -						
	Sim May m	ĺ		I	Set Se		

Inspector Signature:

Reviewed By: