E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

		E&A - P2004.0	020.000		
Inspector: Dylan Wagner					Stage
Project Name:			sades 110500		3
For Week Ending:		11/9	/2024		
Project Location:	168t		- Omaha, NE (Sarpy County)		68136
			F	-	
Grading: Sanitary Sewer:	<u> </u>				
Storm Sewer:	100%				
Paving:	100%				
Seeding:	100%				
Utilities:	100%				
Overall Development:	99%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration
NAIT TALE ANOTHE	, anounc an concilo	Dute mopeoled		inspection fine	Week 1
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"				
Monday	0.03"				
Tuesday	0.11"				
Wednesday	0.00"				
Thursday Friday	0.00"				
Saturday	0.00"				
	0.00				Week 3
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.62" 0.06"	40/04/0004	M	0.00 414	1055 AM - 555 PM
Thursday Friday	0.00"	10/31/2024	Mostly Sunny 52/37	8:20 AM	
Saturday	0.06"				
					Week 4
Sunday:	0.68"				855 PM - 1200 AM
Monday	0.61"	11/4/2024	Cloudy 61/50	5:15 PM	355 PM - 1155 PM
Tuesday	0.51" 0.00"	11/5/2024	Cloudy 51/38	5:00 PM	1200 AM - 955 AM
Wednesday Thursday	0.00"				
Friday	0.00"				
Saturday	0.07"				
					Week 5
Sunday:	N/A				
Monday	N/A				
Tuesday	N/A				
Wednesday	N/A				
Thursday	N/A				
Friday	N/A				
Saturday	N/A				
			·		
Complaints:	None				
		1	-		1
Construction Sequencing:			I		
construction bequencing:					

Which portion(s) (i.e. drainage basins) of the	e site have had a temporary or p	permanent cessation of grading	earthwork, or ground disturbanc	e in the last 14 days?	
Entire site; grading completed and si Which portion(s) (i.e. drainage basins) of the		work or ground disturbance of	shadulad in the part 14 days?		
Entire site: grading completed and si		work, or ground disturbance s	inequied in the next 14 days?		
What temporary or permanent stabilization		re being implemented?			
Paving, seeding (Spring 05), dense w where silt was placed was re-seeded Swale down to basin #3 was regrade to lot 204 and the outlot adjacent to l	(4/2009); The drainage ar d, seeded and matted prio	ea just West of SB 3 was r to inspection on 9/11/20	repaired and seeded/matted	(10/2011)	
Checklist Questions:					
Are receiving waters adjacent to the pro-	piect free of any significant	signs of erosion or sedimen	that would be associated wit	h the construction a	ctivity2
Yes	oject nee of any significants	signs of erosion of sediment		in the construction a	cuvity :
Create Corrective Action?					
N/A					
Have disturbed areas been seeded or o erosion.	therwise stabilized as requi	red? List inactive portions o	f the project and if stabilizatio	n measures are ade	quate or needed to prevent
Yes					
Create Corrective Action?					
N/A					
Are waste materials (concrete, constru	ction material, hazardous, et	c.) being managed properly	?		
Yes					
Create Corrective Action?					
N/A					
Are construction entrances and adjace Yes	nt streets being maintained a	adequately?			
Create Corrective Action? N/A					
IN/A					
Is dust associated with the construction	n aativity adagustaly control	lad on the cite?			
Yes	in activity adequately control	ieu on the site?			
Create Corrective Action?					
N/A					
Comments:					
Comments:					
Home construction was inactive as o					
Findings / Corrective Actions (Date	1				
Findings / Corrective Actions (Date 1.) No maintenance is required in the					
Unique Name	Туре	Location South end of Outlet C	Projected Install Date	Status	Maintenance
CW 1	Concrete Washout	along Palisades Drive		Removed	
Current Condition:			Homes prior to 11/12/2015.		
		South end of Outlet C			
CW 2	Concrete Washout	along Palisades Drive		Removed	
Current Condition:	Removed - Washout pit	was removed by Boyer Yo	ung prior to 11/12/2015.		1
	Concrate Machaut	South end of Outlet C		Pomovod	
CW 3 Current Condition:	Concrete Washout	along Palisades Drive	in preparation for sod on lo	Removed	r will monitor the need to
ourient condition.	re-install.				
SB 3	Sediment Basin	Commercial Lot #5	In Place	Active	No
Current Condition:			leted prior to inspection on		
		173rd Street and		, , , , ,	
SB 4	Sediment Basin	Palisades Drive		Removed	
Current Condition:	Removed - Basin was re	emoved prior to the inspec	tion on 3/24/16.		1
oto	Otra t-	Cornhusker, 168th, and	In Di	A ather	
STR	Streets	Interior Streets	In Place	Active	No
Current Condition:	around lot 24 prior to the		ean as of the inspection on	12/3/19. Story Hon	nes LLC cleaned the street
SWPPP Sign	SWPPP Sign	Three signs on site	3/28/2008	Active	No
Current Condition:			VPPPs at 172nd & Cornhus		
ourrent oundition.		e.			

Certification Statement:	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment for knowing violations."		
Inspector Signature:	Jufun Wagner	Reviewed By:	