E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Environmental Services D	ept. Manager	E&A - D2	2021.167.005					
Inspector: Jason Brackett		EQA-F2	.021.107.005		Stage			
Project Name:	Ponde	1						
For Week Ending:		1/	20/2024					
Project Location:	SE of Ponderos	SE of Ponderosa Drive and S 72nd Street, Papillion, Sarpy County, Nebraska 68133						
				,,				
Grading:	2%	, D						
Sanitary Sewer:	0%							
Storm Sewer:	0%							
Paving:	0%	-						
Seeding:	0%							
Utilities:	0%	b						
Overall Development:	0%	, D						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time				
					Week 1			
Sunday:	0.00"							
Monday:	0.00"							
Tuesday:	0.00"							
Wednesday:	0.00"	1/17/2024	Sunny 24/9	12:05 PM	_			
Thursday:	0.00"							
Friday: Saturday:	0.00"				-			
Saturday.	0.00							
Rough grading in the norther Which portion(s) (i.e. drainage ba Rough grading in the norther What temporary or permanent st Existing vegetation (12/6/23) Checklist Questions:	ast corner began (12/6/23). asins) of the site do not have grad ast corner began (12/6/23). abilization measures listed in this ).	Grading ceased (12/ ding, earthwork, or grour Grading ceased (12/ s section are being imple	nd disturbance scheduled in the n 21/23). emented?	next 14 days?				
Are receiving waters adjacent to Yes	the project free of any significan	t signs of erosion or sed	liment that would be associated w	vith the construction activity	?			
Create Corrective Action?								
N/A								
Yes Create Corrective Action?	ed or otherwise stabilized as requ	uired? List inactive portion	ons of the project and if stabilizati	ion measure are adequate or	r needed to prevent erosion.			
N/A								
Are waste materials (concrete, co	onstruction material. hazardous.	etc.) being managed pro	perly?					
Yes		,						
Create Corrective Action?								
N/A								
Are construction entreness and	adiacont stroots bains maintains	d adoquatoly?						
Are construction entrances and a Yes	aujacent streets being maintaine	u auequatery?						
Tes Create Corrective Action?								
N/A								
	truction activity adequately contr	olled on the site?						
Yes Create Corrective Action?								
Create Corrective Action?								

N/A

## Comments:

Comments: Site was inactive.

A drive-by inspection was conducted on due to snow covered conditions. Not all BMPs could be observed.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

No maintenance is required in the BMP section of this report.
 CIR 163973 was received and reviewed on 1/8/2024. CIR is consistent with E&A inspector's report.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 01	Construction Entrance	NW Corner	3/3/2024	Pending	No		
Current Condition:	Pending - The construction entrance will be installed as needed.						
D 01	Diversion	SW of SB A	3/3/2024	Pending	No		
Current Condition:	Pending - The diversion will be installed with SB A.						
D 02	Diversion	E of SB A	3/3/2024	Pending	No		
Current Condition:	Pending - The diversion will be installed with SB A.						
D 03	Diversion	N of SB B	3/3/2024	Pending	No		
Current Condition:	Pending - The diversion w	ill be installed with SB I		0			
D 04	Diversion	S of SB B	3/3/2024	Pending	No		
Current Condition:	Pending - The diversion w	ill be installed with SB					
D 05	Diversion	SE of SB B2	3/3/2024	Pending	No		
Current Condition:	Pending - The diversion w			g			
EM 01	Erosion Control Matting	W of SB A	3/3/2024	Pending	No		
Current Condition:			alled after the area reaches fin				
EM 02	Erosion Control Matting	N and E of SB A	3/3/2024	Pending	No		
Current Condition:			alled after the area reaches fin				
MS 01	Material Storage	On Site	3/3/2024	Pending	No		
Current Condition:	Pending - Materials will be			1 onding	110		
SB A	Sediment Basin	NW	3/3/2024	Pending	No		
Current Condition:	Pending - The basin will b			rending	110		
SB B	Sediment Basin	W Central	3/3/2024	Pending	No		
Current Condition:	Pending - The basin will b			rending	110		
SB B2	Sediment Basin	SW Corner	3/3/2024	Pending	No		
Current Condition:	Pending - The basin will b			rending	110		
SF 01	Silt Fence	Western Perimeter	3/3/2024	Pending	No		
Current Condition:	Pending - The silt fence w			rending	110		
SF 02	Silt Fence	Southern Perimeter	3/3/2024	Pending	No		
Current Condition:	Pending - The silt fence w			rending	NO		
SF 03	Silt Fence	Northeast Corner	12/6/2023	Active	No		
Current Condition:							
Current Condition.	Good Condition - Ruff Grading installed the silt fence around the portion of the northeast corner where they are working prior the 12/6/23 inspection. A small portion of the silt fence was removed to continue grading prior to the 12/13/23 inspection, the						
	inspector will monitor for reinstallation.						
			10/00/0000	A	NL-		
SWPPP Sign	SWPPP Sign	At CE 01	12/20/2023	Active	No No		
Current Condition:			SWPPP sign at the central st				
WO 01	Concrete Washout	On Site	3/3/2024	Pending	No		
Current Condition:			en concrete work begins on s				
WS 01	Waste Storage	On Site	3/3/2024	Pending	No		
Current Condition:	Pending - Waste will be p						
	"I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in						
	accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information						
antification Ctatements	submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for						
Certification Statement:	gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.						
	am aware that there are significant penalties for submitting false information including the possibility of fines and imprisonment						
	for knowing violations."						
	- <u> </u>						
	Jule Mant				Porto Sales		
actor Signatura:				Poviowod By:	ONTO Dre		

Inspector Signature:

Reviewed By: