E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC **Environmental Services Dept. Manager**

Engineering Answers

Project Name: For Week Ending: Project Location: Grading: Sanitary Sewer: Storm Sewer: Paving: Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Sunday: Monday Tuesday Wednesday Thursday Thursday Saturday Sunday: Saturday Sunday: O.00" O.00" Sunday: O.00"	30% 0% 0% 0% 0% 0% 0% 4%	CSW-2	den Hollow per Ni 201802726 22/2018 t and Highway 36 Weather Conditions	DEQ NOI)	Stage 1 68007
Project Name: For Week Ending: Project Location: Grading: Sanitary Sewer: Storm Sewer: Paving: Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Sunday: Monday Tuesday Wednesday Thursday Thursday Saturday Sunday: Saturday Sunday: O.00" O.00" Sunday: O.00"	30% 0% 0% 0% 0% 0% 0% 4%	12/2 156th Stree	201802726 22/2018 t and Highway 36	DEQ NOI)	68007
For Week Ending: Project Location: Grading: Sanitary Sewer: Storm Sewer: Paving: Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Amount in tents Sunday: Monday Tuesday Wednesday Thursday Thursday Saturday Saturday Sunday: O.00" Wednesday Thursday Sunday: Sunday: O.00" Wednesday O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" O.00" O.00" Sunday: O.00" O.00"	0% 0% 0% 0% 0% 4%	12/2 156th Stree	22/2018 t and Highway 36		
Project Location: Grading: Sanitary Sewer: Storm Sewer: Paving: Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Amount in tents Sunday: Monday Tuesday Wednesday Thursday Thursday Friday Saturday Saturday Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" O.00" Sunday: O.00"	0% 0% 0% 0% 0% 4%	156th Stree	t and Highway 36		
Grading: Sanitary Sewer: Storm Sewer: Paving: Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Amount in tents Sunday: Monday 0.00" Tuesday 0.00" Thursday 0.00" Thursday 0.00" Saturday 0.00" Saturday 0.00" Sunday: 0.00" Sunday: 0.00" Oo" Oo" Oo" Oo" Oo" Oo" Oo" Oo" Oo" Oo	0% 0% 0% 0% 0% 4%				We
Sanitary Sewer: Storm Sewer: Paving: Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Amount in tent Sunday: Monday Tuesday Wednesday Thursday Thursday Friday Saturday Saturday Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00"	0% 0% 0% 0% 0% 4%	e inspected	Weather Conditions		We
Sanitary Sewer: Storm Sewer: Paving: Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Amount in tent Sunday: Monday Tuesday Wednesday Thursday Thursday Friday Saturday Saturday Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00"	0% 0% 0% 0% 0% 4%	inspected	Weather Conditions		We
Storm Sewer: Paving: Seeding: Utilities: Overall Development:	0% 0% 0% 0% 4%	inspected	Weather Conditions		We
Paving: Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Sunday: Monday Tuesday Wednesday Thursday Friday Saturday Sunday: O.00" Friday Saturday Sunday: O.00" Sunday: O.00" O.00" Sunday: O.00"	0% 0% 0% 4%	e inspected	Weather Conditions		We
Seeding: Utilities: Overall Development: RAIN FALL AMOUNTS Sunday: Monday Tuesday Wednesday Thursday Friday Saturday Sunday: O.00" Wednesday O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Sunday: O.00" Monday O.00"	0% 0% 4%	e inspected	Weather Conditions		We
Utilities: Overall Development: RAIN FALL AMOUNTS Sunday: Monday Tuesday Wednesday Thursday Friday Saturday Saturday Sunday: 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00" 0.00"	0% 4%	e inspected	Weather Conditions		We
Overall Development: RAIN FALL AMOUNTS Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 1.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Outline Saturday 0.00" Sunday: 0.00" Monday 0.00"	4%	e inspected	Weather Conditions		We
Amount in tents		e inspected	Weather Conditions		We
Sunday: 0.00" Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00"	hs Date	inspected	Weather Conditions		We
Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00"					We
Monday 0.00" Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00"					
Tuesday 0.00" Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00"					
Wednesday 0.00" Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00"					
Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00"					
Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00"					
Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00"					
Saturday 0.00" Sunday: 0.00" Monday 0.00"					
Sunday: 0.00" Monday 0.00"					
Monday 0.00"					We
Monday 0.00"					
		12/17/18	46/27 Clear		
Tuesgav 10.00°					
Wednesday 0.00"					
Thursday 0.00"					
Friday 0.00"					
Saturday 0.00"					
					We
Sunday: NA					
Monday NA					
Tuesday NA					
Wednesday NA					
Thursday NA					
Friday NA					
Saturday NA					
Complaints:	None				

Entire Site: Grading commenced (11/8/18)
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?:

Entire Site: Grading commenced (11/8/18)

What temporary or permanent stabilization me

Existing vegetation (11/8/18)

SUMMARY QUESTIONS:

Yes

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No. See BMP Section

CHECKLIST QUESTIONS:

ı			
ı	Y	ρ	¢

Is dust associated with the construction activity adequately controlled on the site?

Yes

Comments:

Comments:

Grading is active on site. The site was covered in 1" of snow during the last inspection. Sediment basin B has been partially constructed. The inspector is recommending installment of the basin be completed.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1) Some maintenance is required in the BMP section.
- 2) The t-posts along the entire run of per miter silt fence needs to be spaced properly. They are currently too wide. Negis Construction was informed to complete by 11/29/18. Not done as of the last inspection. **Negis Construction was reminded on 12/19/18**.
- 3) Repair of equipment is underway adjacent to SB A. Oil was present on the ground and should be cleaned up. Negis Construction was informed to complete by 12/25/18.
- 4. A temporary diversion was installed draining into the waterway. The diversion is adjacent to SF 3. The inspector has recomended SF 3 be installed to protect the waterway.

			1					
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance			
CE 1	Stabilized Construction Entrance	N Molley Street (EE11)	11/20/2018	Active	No			
Current Condition:	Good Condition- Negis Co	onstruction installed the en	ntrance prior to the inspec	tion on 11/20/18.				
CW 1	Concrete Washout	Site	11/15/2018	Pending	No			
Current Condition:	Pending - A concrete washout will be recommended when paving is close to commencing.							
D1	Temporary Diversion Ditch	(Z17-II17)	11/15/2018	Pending	Yes			
Current Condition:	Pending -							
	The diversion needs to be installed.							
	Negis Construction was	informed to complete b	y 12/25/18.					
D2	Temporary Diversion	(F25-P21)	11/15/2018	Pending	Yes			
DZ	Ditch	(F25-F21)	11/15/2016	rending	162			
Current Condition:	Pending -							
	The diversion needs to	oe installed.						
	Negis Construction was	informed to complete b	y 12/25/18.					
D3	Temporary Diversion Ditch	(P21-R20)	11/15/2018	Pending	Yes			
Current Condition:	Pending -							
Carroni Condition.	· onamy							
	The diversion needs to	ne installed						
	The diversion needs to	oo motamou.						
	Negis Construction was	informed to complete h	ov 12/25/18.					
5.4	Temporary Diversion			5 "	.,			
D4	Ditch	(B26-D26)	11/15/2018	Pending	Yes			
Current Condition:	Pending -		<u>'</u>					
	The diversion needs to be installed.							
	Negis Construction was	informed to complete b	y 12/25/18.					
EM 1	Erosion Control Matting	(C22-DD11)	11/15/2018	Pending	No			
Current Condition:	Pending - The matting wi	,		. onang	.,,,			
SB A	Sediment Basin	D26	11/15/2018	Pending	Yes			
Current Condition:	Pending -			. <u></u>				
	The basin should be installed.							
	Negis Construction was	informed to complete b	y 12/25/18.					
SB B	Sediment Basin	R20	11/15/2018	Pending	Yes			
Current Condition:	Pending -							
	The basin should be ins	talled.						
				Negis Construction was informed to complete by 12/25/18.				
	Negis Construction was	informed to complete b	y 12/25/18.					

Current Condition:	Fair Condition - Negis Construction installed the silt fence prior to the inspection on 11/8/18.					
	The silt fence needs extended to cover an existing inlet flowing into the adjacent waterway and a gap behind SB A. Negis Construction was informed to complete by 11/29/18. Not done as of the last inspection. Negis Construction was					
	reminded on 12/19/18.					
SF 2	Silt fence	II18	11/8/2018	Active	No	
Current Condition:	Good Condition - Negis Construction installed the silt fence prior to the inspection on 11/8/18.					
SF 3	Silt fence	II17	11/29/2018	Pending	Yes	
SF 4	The silt fence needs to be Negis Construction was in reminded on 12/19/18. Silt fence	·	·	he last inspection. Ne	gis Constructing was	
Current Condition:	Good Condition - Negis Construction installed the silt fence prior to the inspection on 11/8/18.					
OTD			· · · · · ·		N-	
STR	Streets	Site	11/8/2018	Active	No	
Current Condition:	Good Condition- No major signs of track off.					
SWPPP Sign	Misc/Other	168th Street/ Military Road	12/17/2018	Active	No	
Current Condition:	Good Condition- The ins	spector installed the sig	n during the inspectio	n on 12/17/18.		
Inspector Signature:	Chave auland			Reviewed By:	Gut Sol	