E&A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

		E&A- P2017	<b>'.463.001</b>			
Inspector: Avery Dresser						
	Prairie Ho	2				
Project Name:		CSW-201802726				
For Week Ending:	8/24/2019				68007	
Project Location:	156th Stre					
Grading:	95%					
Sanitary Sewer:	50%					
Storm Sewer:	75%					
Paving:	0%					
Seeding: Utilities:	0%					
Overall Development:	20%					
Overall Development.	20 /0					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions			
					Week	
Sunday:	2.14"					
Monday	0.36"	8/12/2019	Overcast 87/71			
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.22"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.33"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Week	
Sunday:	N/A	N/A				
Monday	N/A	N/A				
Tuesday	N/A	N/A				
Wednesday	N/A N/A	N/A N/A				
Thursday Friday	N/A N/A	N/A N/A				
Saturday	N/A N/A	N/A				
Saturday	IN/A	IN/A				
	None					
Complaints:						
0						
Construction Sequencing:	: asins) of the site have had a tempor	rom, or normanant co	on of grading porthwark	ound disturbance in the	not 14 days?	
vincii portion(s) (i.e. grainage ba	isilis) of the site have had a tempol	ary or permanent cessati	on or gracing, earthwork, or gr	ound disturbance in the l	asi 14 days?	

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire Site: Grading commenced (11/8/18). Grading temporarily ceased due to winter conditions (3/5/19). Entire site: Grading resumed (4/9/19). Major grading complete, minor grading at a later date (4/23/19). Grading along future location of N. Allen Street (6/17/19). Excavation for storm sewer installation in the southern portion of the site (7/15/19). Minor grading in the southern portion of the site (8/12/19).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (11/8/18).

#### SUMMARY QUESTIONS:

Are approved entrances and adjacent streets being maintained adequately?

No, See BMP Section

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

No, See BMP Section

### **CHECKLIST QUESTIONS:**

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

No, See Findings Section

Is dust associated with the construction activity adequately controlled on the site?

Yes

### Comments:

# Comments:

Site was active during the last inspection.

## Findings / Corrective Actions (Date):

### Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) The t-posts along the entire run of perimeter silt fence needs to be spaced properly. They are currently too wide. Negus & Son's Construction was informed to complete by 11/29/18. Not done as of the last inspection. Negus & Son's Construction was reminded on 12/19/18, 1/23/19, 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19.
- 3.) A white fuel tank was observed on-site near CE 1 during inspection on 5/20/19. The fuel tank had appropriate secondary containment as of last inspection. E&A inspector will continue to monitor.
- 4.) The portable toilet on site was moved to a location near CE 1 (Y9). The portable toilet should be staked down. Negus & Son's Construction was informed to complete by 8/12/19. **Not done as of the last inspection.**

Unique Name	Туре	Location	Projected Install Date	Status	Maintenanc	
OF 4	Stabilized Construction	N Malloy Street (FF44)	11/20/2012	A ativ :-	Vee	
CE 1 Current Condition:	Entrance 400/ office	N Molley Street (EE11)	11/20/2018 estruction installed the entra	Active	Yes	
	Rock needs added to the entrance.  Negus & Son's Construction was informed to complete by 1/15/19. Not done as of the last inspection. Negus & Son's Construction was reminded on 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19. Mikhail Negus & Son's Construction was reminded on-site on 7/15/19.					
	Stabilized Construction					
CE 2 Current Condition:	Entrance	N 2nd Street (B24)	6/24/2019 estruction began using the e	Active	Yes	
	Negus and Son's Construction was informed to complete by 6/24/19. Not done as of the last inspection. Negus and Sor Construction was reminded on 6/24/19, 7/24/19, 8/05/19. Mikhail with Negus & Son's Construction was reminded on sit on 7/15/19.					
CW 1	Concrete Washout	Site	11/15/2018	Pending	No	
Current Condition:	Pending - A concrete washout will be recommended when paving is close to commencing.					
D1 Current Condition:	Temporary Diversion Ditch	(Z17-II17)	11/15/2018	Pending	Yes	
		The diversion needs to be installed.  Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Negus & Son' Construction was reminded on 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19. Mikhail Negus & Son's Construction was reminded on-site on 7/15/19.				
	Negus & Son's Construct Construction was reminde	ion was informed to comp ed on 3/16/19, 3/29/19, 4/2	<mark>24/19, 5/20/19, 6/06/19, 6/1</mark>			
	Negus & Son's Construct Construction was reminde	ion was informed to comp ed on 3/16/19, 3/29/19, 4/2	<mark>24/19, 5/20/19, 6/06/19, 6/1</mark>			
D2	Negus & Son's Construct Construction was reminde Negus & Son's Construct Temporary Diversion Ditch	ion was informed to comp ed on 3/16/19, 3/29/19, 4/2	<mark>24/19, 5/20/19, 6/06/19, 6/1</mark>			
D2 Current Condition:	Negus & Son's Construct Construction was reminde Negus & Son's Construct Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct Construction was reminde	ion was informed to compled on 3/16/19, 3/29/19, 4/2 ion was reminded on-site (F25-P21)  e installed. ion was informed to comp	24/19, 5/20/19, 6/06/19, 6/19 on 7/15/19. 11/15/2018 lete by 12/25/18. Not done a 24/19, 5/20/19, 6/06/19, 6/19	Pending  as of the last inspec	19, 8/05/19. Mikha Yes tion. Negus & Son	
Current Condition:	Negus & Son's Construct Construction was reminde Negus & Son's Construct Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct Construction was reminde Negus & Son's Construct Temporary Diversion	ion was informed to compled on 3/16/19, 3/29/19, 4/2 ion was reminded on-site (F25-P21)  e installed. ion was informed to compled on 3/16/19, 3/29/19, 4/2 ion was reminded on-site	24/19, 5/20/19, 6/06/19, 6/19 on 7/15/19. 11/15/2018 11/15/2018 lete by 12/25/18. Not done a 24/19, 5/20/19, 6/06/19, 6/19 on 7/15/19.	Pending  as of the last inspect	19, 8/05/19. Mikha Yes tion. Negus & Son 19, 8/05/19. Mikha	
	Negus & Son's Construct Construction was reminde Negus & Son's Construct Temporary Diversion Ditch Pending - The diversion needs to be Negus & Son's Construct Construction was reminde Negus & Son's Construct	ion was informed to compled on 3/16/19, 3/29/19, 4/2 ion was reminded on-site (F25-P21)  e installed. ion was informed to compled on 3/16/19, 3/29/19, 4/2	24/19, 5/20/19, 6/06/19, 6/19 on 7/15/19. 11/15/2018 lete by 12/25/18. Not done a 24/19, 5/20/19, 6/06/19, 6/19	Pending  as of the last inspec	19, 8/05/19. Mikha Yes tion. Negus & Son	

5.4	Temporary Diversion	(Dog Dog)	44/45/0040	5 "			
D4 Current Condition:	Ditch Pending -	(B26-D26)	11/15/2018	Pending	Yes		
cuiton conunion	The diversion needs to be installed.  Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Negus & Son's Construction was reminded on 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19. Mikhail witl						
	Negus & Son's Construction was reminded on-site on 7/15/19.						
EM 1	Erosion Control Matting	,	11/15/2018	Pending	No		
Current Condition: SB A	Pending - The matting wi Sediment Basin	II be recommended upon D26	11/15/2018	Pending	Yes		
Current Condition:	Pending -			J			
	The basin should be installed.  Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Negus & Son's Construction was reminded on 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19. Mikhail wi Negus & Son's Construction was reminded on-site on 7/15/19.						
SB B Current Condition:	Sediment Basin Pending -	R20	11/15/2018	Pending	Yes		
	The basin should be installed.  Negus & Son's Construction was informed to complete by 12/25/18. Not done as of the last inspection. Negus & Son's Construction was reminded on 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19.						
SF 1 Current Condition:	Silt fence	, ,			Yes		
SF 2	Silt fence	II18	11/29/2018	Pending	Yes		
OI Z	Ont lettice	1 110	1 1/23/2010	I renaing	169		

Current Condition:	Pending -					
	The silt fence needs to be installed to cover the adjacent waterway.					
	Name & Carda Caracterities was informative to At 100100 New York Caracteristics Name & Carda					
	Negus & Son's Construction was informed to complete by 11/29/18. Not done as of the last inspection. Negus & Son's Construction was reminded on 12/19/18, 1/23/19, 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19.					
	8/05/19. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19.					
SF 3	Silt fence	II17	11/29/2018	Pending	Yes	
Current Condition:	Pending -					
	The silt fence needs to be installed to cover the adjacent waterway.					
	Negus & Son's Construction was informed to complete by 11/29/18. Not done as of the last inspection. Negus & Son's					
	Construction was reminded on 12/19/18, 1/23/19, 3/16/19, 3/29/19, 4/24/19, 5/20/19, 6/06/19, 6/18/19, 6/24/19, 7/24/19,					
	8/05/19. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19.					
SF 4	Silt fence	(DD1-DD14)	11/8/2018	Active	Yes	
Current Condition:	Fair Condition - Negus & Son's Construction installed the silt fence prior to the inspection on 11/8/18.  The silt fence needs removed.					
	Negus & Son's Construction will be informed to complete when winter conditions allow as of the inspection on 2/19/19.					
	Not done as of the last inspection. Negus & Son's Construction was reminded on 3/16/19, 3/29/19, 4/24/19, 5/20/19,					
	6/06/19, 6/18/19, 6/24/19, 7/24/19, 8/05/19. Mikhail with Negus & Son's Construction was reminded on-site on 7/15/19.					
STR	Streets	Site	11/8/2018	Active	No	
Current Condition:	Good Condition - Negus & Son's Construction cleaned up the trackout on the adjacent streets prior to inspection on 8/05/19.					
		At CE1, end N. Molley				
SWPPP Sign	Misc/Other	St.	12/17/2018	Active	No	
Current Condition:	Good Condition- The insp	pector installed the sign du	ing the inspection on 12/	1//18.		
	A				St Su	
Inspector Signature:	Reviewed By:					