E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Engineering Answers

Environmental Services	s Dept. Manager	F0.4 B0004	274 204		
Incompation Zook Door		E&A- P2021.	3/4.001		Ctogo
Inspector: Zach Roza Project Name:	The Grove Apartments CSW-202207157				Stage 1
For Week Ending:		2/3/202	γΔ		68508
Project Location:	S Folsom St		ncoln, NE (Lancaster County)	\	
r roject Location.	3 1 0130111 31	G OW Amaranti En - En	com, NE (Lancaster County)	1	
Grading:	25%			T	
Sanitary Sewer:	0%				
Storm Sewer:	0%				
Paving:	0%				
Seeding:	0%				
Utilities:	0%				
Overall Development:	5%				
RAIN FALL AMOUNTS	Amount in tenths	Data in an arte d	Washan Candidiana	Time	Charac Frank Direction
RAIN FALL AWOUNTS	Amount in tentils	Date inspected	Weather Conditions	Time	Storm Event Duration Week
Sunday	0.00"				- Neck
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"	1/31/2024	Mostly Sunny 60 / 27	12:40 PM	
Thursday	0.00"				
Friday	0.00"				
Saturday	0.49"				1:54 PM - 5:54 PM
Construction Sequenci Which portion(s) (i.e. drainag	ing: ge basins) of the site have had a tempor	ary or permanent cessation o	f grading, earthwork, or ground dis	sturbance in the last	l4 days?
Grading began (10/11/23	3).				
Which portion(s) (i.e. drainag Grading began (10/11/23	ge basins) of the site do not have gradin 3).	g, earthwork, or ground distu	rbance scheduled in the next 14 da	iys?	
What temporary or permane Existing vegetation (10/1	nt stabilization measures listed in this s 1/23).	ection are being implemented	!? 		
Checklist Questions: Are receiving waters acactivity? Yes	ljacent to the project free of any	significant signs of eros	sion or sediment that would l	be associated wi	th the construction
Create Corrective Action	on?				
N/A					
or needed to prevent en Yes		red as required? List ina	ctive portions of the project	and if stabilization	on measure are adequate
Create Corrective Action					
N/A	oncrete, construction material, h	azardous, etc.) being ma	anaged properly?		

 ,	•	

Are construction entrances and adjacent streets being maintained adequately?

Vaa

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Commente

Comments:

- 1.) E&A Began site inspections on 10/11/2023
- 2.) Site was inactive during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

There are no current findings in the BMP Section.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance	
CE 01	Construction Entrance	Northwest Corner of Site	10/11/2023	Active	No	
Current Condition:	Good Condition- 80% effective- Edward Rose installed a construction entrance prior to the inspection on 10/11/23.					
FT 01	Fuel Tank	On Site	12/13/2023	Active	No	
Current Condition:	Good Condition- Edward Rose installed a mobile fuel tanker with secondary containment on site prior to the inspection on 12/13/23.					
IP 01 - 02	Inlet Protection	Southeast Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Inlet protection will be		or when the inlet is at grad	le.		
IP 03 - 14	Inlet Protection	Southwest Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Inlet protection will be		or when the inlet is at grad	le.		
IP 15 - 17	Inlet Protection	Northwest Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Inlet protection will be		or when the inlet is at grad	le.		
IP 18 - 26	Inlet Protection	Southeast Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Inlet protection will be		or when the inlet is at grad	le.		
IP 27 - 35	Inlet Protection	Northeast Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Inlet protection will be	installed once paving is done,	or when the inlet is at grad	le.		
IP 36 - 37	Inlet Protection	Southeast Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Inlet protection will be	installed once paving is done,	or when the inlet is at grad	le.		
IP 38 - 39	Inlet Protection	Northeast Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Inlet protection will be	installed once paving is done,	or when the inlet is at grad	le.		
IP 40 - 45	Inlet Protection	Northwest Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Inlet protection will be installed once paving is done, or when the inlet is at grade.					
MS 01	Material Storage	On Site	11/11/2023	Pending	No	
Current Condition:	Pending- Material storage will be installed as necessary.					
PM 01	Erosion Control Matting	Northeast Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Matting will be installed after final grade is established.					
PM 02	Erosion Control Matting	Northern Perimeter	11/11/2023	Pending	No	
Current Condition:	Pending- Matting will be installed	d after final grade is establishe	d.	-		
PM 03	Erosion Control Matting	Northeast Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Matting will be installed	d after final grade is establishe	d.		-	
PM 04	Erosion Control Matting	Northwest Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Matting will be installed		d.			
PT 01	Portable Toilet	On Site	10/11/2023	Active	No	
Current Condition:	Good Condition- Edward Rose i	nstalled a portable toilet on site	prior to the inspection on	10/11/23.		
SF 01 - 10	Silt Fence	Northwest Quadrant of SWPPP	11/11/2023	Pending	No	
Current Condition:	Pending- Silt fence will be instal					

SF 9b - 14	Silt Fence	Northeast Quadrant of	11/11/2023	Pending	No
Current Condition:	Pending- Silt fence will be installed once grading starts.				
SF 15	Silt Fence	Perimeter Silt Fence	10/11/2023	Active	No
Current Condition:	Fair Condition- Edward Rose installed silt fence along the majority of the north and eastern perimeter prior to the inspection on 10/11/23. Edward Rose was in the process of installing silt fence along the eastern and southern perimeter during the inspection on 10/25/23. Edward Rose installed the silt fence along the eastern and southern perimeter prior to the inspection on 11/1/23. Portions of the silt fence were observed to be damaged during the inspection on 1/31/24. Maintenance will not be recommended at this time.				
SF 16 - 24	Silt Fence	Southeast Quadrant of SWPPP	11/11/2023	Pending	No
Current Condition:	Pending- Silt fence will be install	led once grading starts.			•
SF 25 - 30	Silt Fence	Southwest Quadrant of SWPPP	11/11/2023	Pending	No
Current Condition:	Pending- Silt fence will be installed once grading starts.				
STR	Streets	ADJ and Internal Streets	10/11/2023	Active	No
Current Condition:	Good Condition- There was no sign of track off during the inspection on 10/11/23. Minor trackout was observed during the inspection on 11/29/23. Edward Rose cleaned up the minor trackout prior to the inspection on 12/6/23.				
SWPPP Sign	SWPPP Signs	ADJ to CE 01	10/11/2023	Active	No
Current Condition:	Good Condition- E&A inspector	installed a SWPPP sign prior to	the inspection on 10/11/	23.	•
WO 01	Concrete Washout	On Site	11/11/2023	Pending	No
Current Condition:	Pending- A concrete washout will be installed once paving starts.				
WS 01	Waste Storage Area	On Site	11/11/2023	Pending	No
Current Condition:	Pending- A waste storage area will be installed as necessary.				
Certification Statement	"I certify, under penalty of law, the with a system designed to assur inquiry of the person or persons information submitted is, to the benealties for submitting false info	e that qualified personnel prop who manage the system or tho pest of my knowledge and belie	erly gathered and evaluat ose persons directly respo f, true, accurate, and com	ed the information sonsible for gathering applete. I am aware t	submitted. Based on my g the information, the hat there are significant
Inspector Signature:	Joh Ryo			Reviewed By:	Ch Se