E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

	E& <i>A</i>	- P2001.097.000				
Inspector: Scott Fryant				Stage		
		Sunridge		3		
Project Name:		NER101348 1/14/2012				
Project Name:						
For Week Ending:		68136				
Project Location:	180th and					
One disc.	4000/	T T	<u> </u>			
Grading: Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Utilities:	100%					
Overall Development:	75%					
-						
RAIN FALL AMOUNTS	Amount in inches	Date inspected				
ALL AMOUNTS		Date Hisperieu		Wee		
Sunday:	0.00"					
Monday	0.00"					
uesday	0.20"					
Vednesday	0.18"					
hursday	0.00"					
riday	0.00"					
Saturday	0.00"					
	0.00	<u> </u>		Wee		
Sunday:	0.00"					
Monday	0.00"					
uesday Vednesday	0.00" 0.01"					
hursday	0.01"					
riday	0.00"					
Saturday	0.00"					
Juliu duy	0.00			Wee		
Sunday:	0.00"					
Monday	0.00"					
uesday	0.00"					
Vednesday	0.00"					
Thursday	0.01"					
Friday	0.01"					
Saturday	0.06"					
N	lo cor	T T		Wee		
Sunday:	0.00"					
Monday Tuesday	0.00"					
Vednesday Vednesday	0.00"	 				
hursday	0.00"	 				
riday	0.00"	 				
Saturday	0.00"					
	<u>,</u>	·		Wee		
Gunday:	0.00"					
Monday	0.00"	01/09/12				
uesday	0.00"					
Vednesday	0.01"					
hursday	0.01"					
riday	0.00"	ļ				
aturday	0.00"					
	IN.					
Complainte	None					
Complaints:						
		Т	I			
Construction Sequencing		I l				
Construction Sequencing: Vhich portion(s) (i.e. drainage basin	s) of the site have had a temporary or p	ermanent cessation of grading, earthwe	ork, or ground disturbance in	the last 14 days?		
F =	.,		. , g wow.bando III			
ntire site: grading completed	and stabilized prior to Spring 2005.					
3 1 7 1 1 1						

Entire site; grading completed and stabilized prior to Spring 2005.								
	1				ı			
What temporary or permanent stabilization	measures listed in this section as	e heing implemented?						
What temporary or permanent stabilization measures listed in this section are being implemented? Dense Vegetation, seeding/sodding, (Re-seeding 6/2005), matting, paving, and landscaping. Commercial portion of site was re-seeded 4/2008 by Commercial Seeding.								
Comments:								
Comments: Site is idle.								
Findings / Corrective Actions (Date	e):							
Findings / Corrective Actions (Date): 1) No required maintenance in the BMP section.								
Unique Name	Туре	Location	Projected Install	Status	Maintenance			
Onique Name	туре	N41d00m00s	Date	Status	Walliterlance			
CE 1	Construction Entrance	W96d00m00s		Removed				
Current Condition:	Paved entrance.							
		N41d00m00s						
SB 1	Sediment Basin	W96d00m00s		Removed				
Current Condition:	Sediment basin removal cor		n on 7/24/07.		1			
SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed				
Current Condition:	Removed 12/2006	VV 30000111003		Removed	l .			
		N41d00m00s						
SB 3	Sediment Basin	W96d00m00s		Removed				
Current Condition:	Removed 5/2006 by Dave Hausman N41d00m00s							
SF 1	Silt Fence	W96d00m00s		Removed				
Current Condition:	Silt fence was removed due to lots being sodded.							
		N41d00m00s						
SF 2	Silt Fence	W96d00m00s		Removed				
Current Condition:	Silt fence removed due to dense vegetation and will need re-installed when construction resumes in this area.							
SF 3	Silt Fence	N41d00m00s						
		W96d00m00s		Removed				
Current Condition:	Silt fence removed due to dense vegetation and will need re-installed when construction resumes in this area.							
SF 4	Silt Fence	N41d00m00s W96d00m00s		Removed				
Current Condition:	Silt fence removed due to dense vegetation and will need re-installed when construction resumes in this area.							
STR	STREETS	N41d00m00s W96d00m00s	In Place	Active	No			
Current Condition:	Good Condition - No major :		III I Idoc	Active	140			
	,							
SWPPP Sign	Signs	2 Signs	8-19-08	Active	No			
Current Condition:	Good Condition - 180th and Josephine, 183rd and Harrison							
Inspector Signature: Scott Tryant			Reviewed By:	Zadrany L. Ji	LAC			