E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 P •8 tel 402.895.4700 fax 402.895.3599 www.eacg.com E&A CONSULTING GROUP, INC. Zachary A. Jilek, CPESC, CISEC ENGINEERING • PLANNING • FIELD SERVICES Erosion Control Specialist- Manager E&A- P2005.030.000 Stage Inspector: Scott Fryant 3 The Heritage NER110495 Project Name: 3/10/2012 For Week Ending: East of 156th Street and North and South of Rainwood Road- Bennington, NE 68007 (Douglas County) Project Location: Grading: 100% Sanitary Sewer: Storm Sewer: 100% 100% Paving: 100% Seeding: 100% Utilities: 100% Overall Development: 40% RAIN FALL AMOUNTS Amount in inches Date inspected Sunday: 0.00" Monday 0.07" Tuesday 0.00" Wednesday 0.01" Thursday 0.00' Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.31" Tuesday).01" Wednesday).01" Thursday 0.05' 02/23/12 Friday 0.10" Saturday 0.00" Sunday: 0.00" Monday 0.00' Tuesday).28 Wednesday 0.00' Thursday 0.00 Friday 0.00' Saturday 0.00" Sunday: 0.00" Monday 0.00' Tuesday 0.00" Wednesday 0.01' Thursday 0.00" Friday 0.00" Saturday 0.00" Sunday: N/A N/A Monday N/A N/A Tuesday N/A N/A Wednesday N/A N/A Thursday N/A N/A N/A Friday N/A N/A N/A Saturday None Complaints: Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessat ion of grading, earthwork, or ground disturbance in the last 14 days? Entire site, grading completed 7/2006 and site seeded 9/5/06.

Week

Weeł

Week 5

Which portion(s) (i.e. drainage basins) of the	e site do not have grading, ea	rthwork, or ground disturb	ance scheduled in the nex	tt 14 days? :					
Entire site, grading completed 7/2006	and site seeded 9/5/06.								
What temporary or permanent stabilization r	neasures listed in this sectio	n are being implemented?							
Wetlands Mitigation Seeding (5/31/06)	Slopes Seeded/Matted	(8/30/06) Temp Seed	led (9/5/06) Re-Seede	d 5/21/07 Re-Seeder	1 ROW on 9/5/07				
& 11/14/07, Erosion seeded in various		(
			1		1				
Comments:									
Comments:									
Three homes are under construction a	is of last inspection.								
Findings / Corrective Actions (Date):								
Findings / Corrective Actions (Date									
1) See required maintenance in the BI	MP section.								
			Projected Install						
Unique Name	Type Construction	Location N41d00m00s	Date	Status	Maintenance				
CE 1	Entrance	W96d00m00s		Removed					
Current Condition:	Entrance has been Construction	paved. N41d00m00s			1				
CE 2	Entrance	W96d00m00s		Removed					
Current Condition:	Entrance has been	paved.	•						
CW 1	Concrete Washout	Lot 20	6/14/2010	Active	Yes				
Current Condition:	Good Condition-	20120	0,1 , 2010	7101170					
	Silt fance is damaged around wachout. Silt fance around wachout needs to be reappired								
	Sill tence is damage	Silt fence is damaged around washout. Silt fence around washout needs to be reapaired.							
	Cassi with Newstree	et was informed to repa	ir silt fence by 3/1/12.						
CW 2 Current Condition:	Concrete Washout Good Condition-	Lot 162	6/14/2010	Active	No				
		vas cleaned by Cassi w	ith Newstreet prior to in	nspeciton on 1/3/12.					
Lot 5 Current Condition:	Silt Fence	Lot 5 d by Dreamscape Hom	es prior to inspection (Removed					
	Lot has been bound								
Lot 76	Miscellaneous	Lot 76	2/23/2012	Active	Yes				
Current Condition:	Fair condition	Lot ro	2/20/2012	Active	103				
	Dirt in the Right of y	rov poods to be remove	ad.						
		Dirt in the Right of way needs to be removed.							
	Bill Purdue with Reg	ency Homes was infor	med to remove dirt from	m right of way by 3/1/	12.				
	0111 5								
Lot 91 Current Condition:	Silt Fence Lot has been sodde	Lot 91 d by Home Enterprises	prior to inspection on	Removed 7/6/11.					
		,		[
Lot 110	Berm	Lot 110	11/10/2011	Active	No				
Current Condition:	Good condition- Berm was installed	on low end of lot by Me	lvin Sudbeck prior to in	spection on 12/5/11					
		N41d00m00s							
SB 1	Sediment Basin	W96d00m00s		Removed					
Current Condition:	Removed per Gradi	ng Modification; to be c	constructed when school	ol site is graded.					
SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed					
Current Condition:	Removed per Gradi		1	Removed	1				
		N41d00m00s							
SB 3	Sediment Basin Good Condition- 19	W96d00m00s	11/14/2005	Active	No				
Current Condition:	Cleanout 9/24/07 by								
		N41d00m00s							
SB 4 Current Condition:	Sediment Basin Good Condition- 20	W96d00m00s	11/14/2005	Active	No				
			r	[
SB 5	Sediment Basin	N41d00m00s W96d00m00s	11/2/2005	Active	No				

Current Condition:	Good Condition- 23		o undermining (/000)				
	Outlet Pipe recomp	acted by Sudbeck due t	o undermining- 4/2006	0			
	Carlins and Dania	N41d00m00s	44/0/0005	A =45	NI-		
SB 6 Current Condition:	Sediment Basin Good Condition- 36	W96d00m00s	11/2/2005	Active	No		
Current Condition:	Cleanout 10/2006 b						
	010411041 10/2000 0			11			
	Oilth Earnag	N41d00m00s		Demoved			
SF 1 Current Condition:	Silt Fence	W96d00m00s Venninghoff prior to insp	action on 10/15/00 du	Removed			
Current Condition:	Removed by Nick V	venningnon prior to insp	ection on 10/15/09 dt	le to dense vegetation.			
		N41d00m00s					
SF 2	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed- Part of S	Silt fence #2 has been re	moved from the Herit	age SWPPP due to New	v SWPPP f		
	Bennington Elementary School project.						
	Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.						
		N41d00m00s					
SF 3	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed						
	Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.						
		N41d00m00s					
SF 4	Silt Fence	W96d00m00s		Removed	No		
Current Condition:	Removed due to pe	rmanent vegetation					
	0.1% 5	N41d00m00s		- ·			
SF 5	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.						
	Sill tence has been	N41d00m00s	ward prior to inspecti	011 011 4/20/11.			
SF 6	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed	VV 9000011003		Removed			
Current Condition:	Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.						
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	2/26/2007	Active	Yes		
Current Condition:	Fair Condition-						
	1) Some signs of track off located on Rosewater Parkway.						
	2) Some signs of track off located on Bluestem Circle.						
	 Bill Purdue with Regencey Homes was informed to clean street on 2/23/12. XK constuction was informed to clean Bluestem circle on 2/23/12. 						
	2) XK constuction w	as informed to clean Bl	uestem circle on 2/23	/12.			
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	No		
Current Condition:	Good Condition:						
	156th and Clevelan	d Blvd					
~	_1				I		
فمنطر	t Fryant			Zachany K. Jili	lC		
or Signature:		J	Reviewed By:				