E&A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 P •8 tel 402.895.4700 fax 402.895.3599 www.eacg.com E&A CONSULTING GROUP, INC. Zachary A. Jilek, CPESC, CISEC ENGINEERING • PLANNING • FIELD SERVICES Erosion Control Specialist- Manager E&A- P2005.030.000 Stage Inspector: Scott Fryant 3 The Heritage NER110495 Project Name: 11/10/2012 For Week Ending: East of 156th Street and North and South of Rainwood Road- Bennington, NE 68007 (Douglas County) Project Location: Grading: 100% Sanitary Sewer: Storm Sewer: 100% 100% Paving: 100% Seeding: 100% Utilities: 100% Overall Development: 40% RAIN FALL AMOUNTS Amount in inches Date inspected Week Sunday: 0.06' Monday 0.00" Tuesday 0.00" Wednesday 0.03" Thursday 0.05 Friday 0.02" Saturday 0.00" Weeł Sunday: 0.00" Monday ).05' Tuesday 0.00" Wednesday ).03' Thursday ).53" 10/25/12 Friday 0.00" Saturday 0.00" Sunday: 0.00" Monday 0.00' Tuesday 0.00' Wednesday 0.00' Thursday 0.00 Friday 0.00' Saturday 0.00" Sunday: 0.02" Monday 0.02" Tuesday 0.00" Wednesday 0.00" Thursday ).03" Friday 0.00" Saturday 0.15" Week 5 Sunday: N/A N/A Monday N/A N/A Tuesday N/A N/A Wednesday N/A N/A Thursday N/A N/A N/A Friday N/A N/A N/A Saturday None Complaints: Construction Sequencing: Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessal ion of grading, earthwork, or ground disturbance in the last 14 days? Entire site, grading completed 7/2006 and site seeded 9/5/06.

Which portion(s) (i.e. drainage basins) of the	ne site do not have grading, ear	thwork, or ground distur	bance scheduled in the new	tt 14 days? :	
Entire site, grading completed 7/2006	and site seeded 9/5/06.				
What temporary or permanent stabilization	measures listed in this section	are being implemented?	•		
mattemporary or permanent stabilization		are being implemented.			
Wetlands Mitigation Seeding (5/31/06 & 11/14/07, Erosion seeded in variou				d 5/21/07, Re-Seede	d ROW on 9/5/07
Comments:					
Comments:					
Home construction is active on site. Findings / Corrective Actions (Date	a).				
Findings / Corrective Actions (Date	•				
1) No required maintenance in the BM	,		-		
			Projected Install		
Unique Name	Туре	Location	Date	Status	Maintenance
CE 1	Construction Entrance	N41d00m00s W96d00m00s		Removed	
Current Condition:	Entrance has been p			Kenloveu	
05.0	Construction	N41d00m00s			
CE 2 Current Condition:	Entrance Entrance has been p	W96d00m00s aved.		Removed	
CW 1 Current Condition:	Concrete Washout	Lot 20	6/14/2010	Active	No
Current Condition:	Good condition- Washout was cleane Newstyle.	ed out and silt fence w	as repaired prior to insp	pection on 8/21/12 by	Cassi with
CW 2	Concrete Washout	Lot 162	6/14/2010	Active	No
Current Condition:	Good condition-			I	
	Silt fence was repair	ed prior to inspection	on 8/21/12 by Cassi wit	h Newstyle.	
Lot 1	Silt Fence	Lot 1		Removed	
Current Condition:			prior to inspection on 5/2		
Lot 2	Silt Fence	Lot 2	ingen en 1/04/40	Removed	
Current Condition:	Lot was sodded by G	Lee Homes prior to	inspection on 8/21/12.	Γ	-
Lot 5	Silt Fence	Lot 5		Removed	
Current Condition:	Lot has been sodded	by Dreamscape Hor	nes prior to inspection of	on 7/6/11.	
Lot 76	Miscellaneous	Lot 76		Removed	
Current Condition:	Lot has been sodded	by Regency Homes	prior to inspection on 0	6/11/12.	1
Lot 91	Silt Fence	Lot 91		Removed	
Current Condition:	Lot has been sodded	by Home Enterprise	s prior to inspection on	7/6/11.	
	_				
Lot 110 Current Condition:	Berm Lot has been sodded	Lot 110 by Melvin Sudbeck r	prior to inspection on 6/2	Removed	
1	011 5				
Lot 195 Current Condition:	Silt Fence Good condition-	Lot 195	4/15/2012	Active	No
		completed prior to insp N41d00m00s	pection on 5/22/12 by C	ommercial Seeding.	
SB 1	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed per Gradir	<b>.</b>	constructed when scho	ol site is graded.	•
SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:	Removed per Gradir		1	Removed	
		N41d00m00s			
SB 3	Sediment Basin	W96d00m00s	11/14/2005	Active	No
Current Condition:	Good Condition- 20% Cleanout 9/24/07 by				
	Í	N41d00m00s			
SB 4	Sediment Basin	W96d00m00s	11/14/2005	Active	No

Current Condition:	Good Condition- 22% Filled						
SB 5	Sediment Basin	N41d00m00s W96d00m00s	11/2/2005	Active	No		
Current Condition:	Good Condition-26% Filled Outlet Pipe recompacted by Sudbeck due to undermining- 4/2006						
SB 6	Sediment Basin	N41d00m00s W96d00m00s		Removed			
Current Condition:	Sediment Basin 6 has been removed prior to inspection on 5/2/12 by Ed Jochim. Area was also se and matted.						
SF 1	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed by Nick Wenninghoff prior to inspection on 10/15/09 due to dense vegetation.						
SF 2	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed- Part of Silt fence #2 has been removed from the Heritage SWPPP due to New SWPPP Bennington Elementary School project. Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.						
SF 3	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.						
SF 4	Silt Fence	N41d00m00s W96d00m00s		Removed	N		
Current Condition:	Removed due to per						
SF 5	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.						
SF 6	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed Silt fence has been removed by Mike Woodward prior to inspection on 4/26/11.						
STR	Street Cleaning	N41d00m00s W96d00m00s	2/26/2007	Active	N		
Current Condition:	Good Condition- No	major signs of track o	ff and/or run off noted	during last inspection.			
SWPPP Sign	Signs	1 sign on site	8-19-08	Active	N		
Current Condition:	Good Condition: 156th and Cleveland	Blvd					
<b>یکی در</b> or Signature:	& Fryant		Reviewed By:	Zachrany k. fil	de		