

E & A Consulting Group, Inc.  
 10909 Mill Valley Road, Suite 100  
 Omaha, NE 68154  
 tel 402.895.4700  
 fax 402.895.3599  
 www.eacg.com



**Engineering Answers**

Zachary A. Jilek, CPESC, CISEC  
 Environmental Services Dept. Manager

E & A CONSULTING GROUP, INC.  
 ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

**E&A - P1999.175.042**

Inspector: Patrick Sechser		Stage
Project Name:	<b>Val Vista</b>	3
For Week Ending:	<b>7/11/2015</b>	
Project Location:	<b>108th &amp; Giles Road - Papillion, NE (Sarpy County)</b>	<b>68128</b>

Grading:	100%			
Sanitary Sewer:	100%			
Storm Sewer:	100%			
Paving:	100%			
Seeding:	100%			
Utilities:	100%			
Overall Development:	68%			

RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	
				<b>Week 1</b>
Sunday:	0.28"			
Monday	0.61"	6/15/2015	Cloudy 76/64	
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.14"			
Friday	0.00"			
Saturday	0.00"			
				<b>Week 2</b>
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.80"	6/24/2015	90/65 Light Rain	
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
				<b>Week 3</b>
Sunday:	0.00"			
Monday	0.00"			
Tuesday	0.04"			
Wednesday	0.23"			
Thursday	0.14"			
Friday	0.04"			
Saturday	0.00"			
				<b>Week 4</b>
Sunday:	0.13"			
Monday	0.15"			
Tuesday	0.03"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.02"			
				<b>Week 5</b>
Sunday:	N/A	N/A		
Monday	N/A	N/A		
Tuesday	N/A	N/A		
Wednesday	N/A	N/A		
Thursday	N/A	N/A		
Friday	N/A	N/A		
Saturday	N/A	N/A		

<b>Complaints:</b>	None

**Construction Sequencing:**

**Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?**  
 Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005,

**Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :**  
 Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005,

**What temporary or permanent stabilization measures listed in this section are being implemented?**  
 Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

**SUMMARY QUESTIONS:**

**Are approved entrances and adjacent streets being maintained adequately?**  
 Yes

**Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?**  
 Yes


**CHECKLIST QUESTIONS:**

**Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?**  
 Yes

**Is dust associated with the construction activity adequately controlled on the site?**  
 Yes

**Comments:**  
 Comments:  
 Site is inactive.

**Findings / Corrective Actions (Date):**  
 Findings / Corrective Actions (Date):  
 1.) No maintenance is required in the BMP section.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance
SB 7	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No
<b>Current Condition:</b>	Good Condition- 36% full- Outlet Pipe maintenance completed 5/2007 Commercial Seeding.				
STR	Street Cleaning	N41d00m00s W96d00m00s	In Place	Active	No
<b>Current Condition:</b>	Good Condition- No major signs of track off.				
<b>Inspector Signature:</b>				<b>Reviewed By:</b>	