E & A Consulting Group, Inc.
10909 Mill Valley Road, Suite 100
Omaha, NE 68154
tel 402.895.4700
fax 402.895.3599
www.eacg.com



Zacharv A. Jilek, CPESC, CISEC

Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager Engineering Answers								
Inspector: Branson Starns		&A - P1999.175).U4Z		Stage			
Project Name:		Val Vista NER101066 4/9/2016						
For Week Ending:	1004.0			,				
Project Location:	108th 8	Giles Road - Pap	illion, NE (Sarpy County	')	68128			
Grading:	100%							
Sanitary Sewer:	100%							
Storm Sewer:	100%							
Paving:	100%							
Seeding:	100%							
Utilities:	100%							
Overall Development:	68%							
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions		Mark			
Sunday:	0.00"				Week 1			
Monday	0.00 0.03" Rain	<u> </u>						
Tuesday	0.08" Rain							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
Sunday	0.00"				Week 2			
Sunday: Monday	0.00"	1		+				
Tuesday	0.00"							
Wednesday	0.10" Rain	3/23/2016	Tstorms 60/35					
Thursday	0.00"	0.20.20.0	Totolinio corec					
Friday	0.00"							
Saturday	0.44" Rain							
					Week 3			
Sunday:	0.00"							
Monday Tuesday	0.00"							
Wednesday	0.00 Rain							
Thursday	0.03" Rain							
Friday	0.03" Rain							
Saturday	0.00"							
					Week 4			
Sunday:	0.00"							
Monday	0.00"							
Tuesday Wednesday	0.00" 0.03" Rain							
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
					Week 5			
Sunday:	N/A	N/A			·			
Monday	N/A	N/A		1				
Tuesday	N/A	N/A						
Wednesday Thursday	N/A N/A	N/A N/A		+				
Friday	N/A N/A	N/A N/A						
Saturday	N/A	N/A						
	<u> </u>			· '				
Complaints:	None							
		1						
Construction Sequencing:	· · · · · · · · · · · · · · · · · · ·			_ · !				
Which portion(s) (i.e. drainage basins) Entire site; residential site grading and south commercial property gr	completed and site seeded prio	r to 2005, north cor						
Which portion(s) (i.e. drainage basins)	of the site do not have grading conth	work or ground distri-	rhance scheduled in the next	14 days? :				
Entire site; residential site grading and south commercial property gr	completed and site seeded prio	r to 2005, north cor			seeded Summer 2005,			
What temporary or permanent stabiliza	ation measures listed in this section a	re heing implemented	<u> </u>	1				
Paving, dense vegetation and land								
- army, dense vegetation and land	accaping instance prior to 2005.	Taving continuercia	1 property (1/2001)	1				

SUMMARY QUESTION	NS:					
Are approved entrances ar	d adjacent streets being maintained	d adequately?				
Yes						
Are receiving waters adjace	ent to the project free of any signifi	cant signs of erosion or se	diment that would be assoc	iated with the constru	ction activity?	
Yes						
CHECKLIST QUESTION	ONS:					
Are waste materials (concr	ete, construction material, hazardoi	us, etc.) being managed pro	operly?			
Yes						
Is dust associated with the	construction activity adequately co	ontrolled on the site?		•		
Yes						
Comments:						
Comments:						
Site is inactive.						
Findings / Corrective	Actions (Date):					
Findings / Corrective						
	required in the BMP section.					
i.) No maintenance is i	equired in the BMP section.					
			Projecte	d Install		

			Projected Install				
Unique Name	Type	Location	Date	Status	Maintenance		
		N41d00m00s					
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- 36% full- (Good Condition- 36% full- Outlet Pipe maintenance completed 5/2007 Commercial Seeding.					
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition- No major :	signs of track off.		_			
Inspector Signature:	Branson Stevens			Reviewed By:	But Sul		