E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

**Engineering Answers** 

Environmental Services Dept. Manager  E&A - P1999.175.042								
	1	E&A - P1999.17	5.042		Ctogo			
Inspector: Matthew Vanicek		Stage						
		Val Vista NER101066						
Project Name:								
For Week Ending:								
Project Location:	108ti	68128						
Cradina	100%	1		1				
Grading: Sanitary Sewer:	100%							
Storm Sewer:	100%							
Paving:	100%							
Seeding:	100%							
Utilities: Overall Development:	100%							
Overali Development:	00%	0						
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time				
					Week 1			
Sunday:	0.00"							
Monday	0.00"							
Tuesday	0.06"							
Wednesday	0.30"							
Thursday	0.38"			1				
Friday	0.00"							
Saturday	0.00"				Wook 2			
Sunday:	0.00"				Week 2			
Monday	0.00"							
Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.00"							
Friday	0.10"							
Saturday	0.30"							
·					Week 3			
Sunday:	0.00"							
Monday	0.00"							
Tuesday	0.00"							
Wednesday	0.03"	0.4/0.0/00	01. 1.05/00	0.45.44				
Thursday	0.02" 0.21"	04/02/20	Cloudy 65/28	8:45 AM				
Friday Saturday	0.01"							
Saturday	0.01				Week 4			
Sunday:	0.00"				Week 4			
Monday	0.00"			+				
Tuesday	0.00"							
Wednesday	0.00"			1				
Thursday	0.00"							
Friday	0.00"							
Saturday	0.00"							
					Week 5			
Sunday:	N/A	N/A						
Monday	N/A	N/A						
Tuesday	N/A	N/A						
Wednesday	N/A	N/A						
Thursday	N/A	N/A						
Friday	N/A N/A	N/A		+				
Saturday	N/A	N/A						
	None							
Complaints:	TTO TO							
,								

Construction Sequencing:

ins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity? Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to

Yes

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Create Corrective Action?

N/A

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

N/A

Comments:

Comments:

Site is inactive as of the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

1.) No maintenance is needed at this time.

Unique Name	Type	Location	Projected Install Date	Status	Maintenance		
		N41d00m00s					
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 36% full - Outlet Pipe maintenance completed 5/2007 Commercial Seeding.						
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - No major signs of track off.						
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No		
Current Condition:	Pending - A SWPPP Sign will be reinstalled when construction resumes on the site.						

Hette Van Inspector Signature:

Reviewed By:

Set Su