E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept. M	anager		E 9 A D 4000 475	042	Liigineerin	,		
Inches Admin Markh	1	t	E&A - P1999.175	.042	Т	Stage		
Inspector: Matthew Vanicek								
		Val Vista NER101066						
Project Name:								
		68128						
For Week Ending:								
Project Location:		108th & Giles Road - Papillion, NE (Sarpy County)						
0		000/ I						
Grading: Sanitary Sewer:		00%						
Storm Sewer:		00%						
Paving:		00%						
Seeding:		00%						
Utilities:		00%						
Overall Development:		68%						
O TOTALI DO TOTO PINOTIC.		0070						
RAIN FALL AMOUNTS	Amount in tenths	- I	Date inspected	Weather Conditions	Inspection Time			
						Week		
Sunday:	0.00"							
Monday	0.00"	\neg						
Tuesday	0.11"							
Wednesday	0.00"							
Thursday	0.15"							
Friday	0.00"							
Saturday	0.61"							
						Week		
Sunday:	0.00"							
Monday	0.00"		5/18/2020	61/55 Cloudy	8:00 AM			
Tuesday	0.00"							
Wednesday	0.00"							
Thursday	0.06"							
Friday	0.24"							
Saturday	0.00"							
						Week		
Sunday:	0.72"							
Monday	0.27"		5/25/2020	69/63 Overcast	12:45 PM			
Tuesday	1.29"							
Wednesday	0.03"		5/27/2020	73/63 Overcast	9:45 AM			
Thursday	0.00"							
Friday	0.00"							
Saturday	0.68"							
	2001					Week 4		
Sunday:	0.08"		A11:	4	+ +			
Monday	0.02"		6/1/2020	94/71 Sunny	11:45 AM			
Tuesday	0.00"				+ +			
Wednesday	0.10"	\rightarrow			+ +			
Thursday Friday	0.01" 0.00"	-+			+			
Saturday	0.00"	-			+ +			
Juliuluay	0.00					Week !		
Sunday:	0.00"							
Monday	0.00"				+			
Tuesday	0.79"	-			+			
Wednesday	0.21"		6/10/2020	77/58 Sunny	2:00 PM			
Thursday	0.00"				1 1 1 1 1 1			
Friday	0.00"							
Saturday	0.00"							
	10.00			1	1			
	None							
Complaints:	INOTIC							
- Complaints.								
	<u> </u>	Т		1	T T			
Construction Sequencing:								

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.

nt stabilization measures listed in this section are being im

Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)

Checklist Questions:

Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

Create Corrective Action?

N/A

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to

Create Corrective Action?

N/A

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?
Yes

Create Corrective Action?

N/A

Create Corrective Action?

N/A

Comments:

Comments:

Site is inactive as of the last inspection.

Findings / Corrective Actions (Date): Findings / Corrective Actions (Date):

1.) No maintenance is needed at this time.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
		N41d00m00s					
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 36% full - Outlet Pipe maintenance completed 5/2007 Commercial Seeding.						
		N41d00m00s					
STR	Street Cleaning	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - No major signs of track off.						
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No		
Current Condition:	Pending - A SWPPP Sign will be reinstalled when construction resumes on the site.						

Plette Van Inspector Signature:

Reviewed By:

But See