E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Inspector: Shaun McGuire			Stage			
		Val Vista NER101066				
Project Name:			2023			
For Week Ending:		68128				
Project Location:	108th					
Grading:	100%					
Sanitary Sewer:	100%					
Storm Sewer:	100%					
Paving:	100%					
Seeding:	100%					
Jtilities:	100%					
Overall Development:	68%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time		
					Wee	
Sunday:	0.00"					
Monday	0.01"					
luesday	0.00"					
Wednesday	0.63"	4/40/0000	0	40-05 DM		
Thursday	0.00"	1/19/2023	Overcast 32/26	12:35 PM		
Friday	0.00" 0.00"					
Saturday	0.00				Wee	
Sunday:	0.00"				Wee	
Aonday	0.00"					
luesday	0.00"					
Vednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday:	0.00"					
Nonday	0.00"					
luesday	0.00"					
Vednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
					Wee	
Sunday:	0.00"					
Monday:	0.00" 0.00"					
Гuesday: Vednesday:	0.00"			+		
Thursday:	0.00"			+ +		
Friday:	0.00"			+ +		
Saturday:	0.00"					
					Wee	
Sunday:	N/A					
Monday	N/A					
Tuesday	N/A					
Vednesday	N/A					
hursday	N/A			+		
Friday Saturday	N/A N/A			+ +		
sata day			1	1		
	None					
Complaints:						
Construction Sequencing:	I		I	1 1		
	) of the site have had a temporary or pe	ermanent cessation of	grading, earthwork, or ground o	disturbance in the last 14	days?	

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.										
As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.										
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :										
Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and										
south commercial property grading completed and site seeded Summer 2006.										
As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.										
What temporary or permanent stabilization measures listed in this section are being implemented?										
Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)										
Charlelist Questioner										
Checklist Questions: Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?										
Yes										
Create Corrective Action?										
N/A										
Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.										
Yes										
Create Corrective Action?										
N/A										
Are waste materials (concrete, constru	ction material, hazardous, et	c.) being managed prop	erlv?							
Yes		· / · · · · · · · · · · ·								
Create Corrective Action?										
N/A										
Are construction entremote and editecent streats being maintained adequately?										
Are construction entrances and adjacent streets being maintained adequately? Yes										
Create Corrective Action?										
N/A										
Is dust associated with the construction activity adequately controlled on the site? Yes										
Create Corrective Action?										
N/A										
Comments:										
Comments:	-									
Site is inactive as of the last inspection										
Findings / Corrective Actions (Date) Findings / Corrective Actions (Date)										
1.) No maintenance is needed at this t										
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance					
-		N41d00m00s								
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No					
Current Condition:	Good Condition - 36% full -	Outlet Pipe maintenand N41d00m00s	ce completed 5/2007 Com	mercial Seeding.						
STR	Street Cleaning	W96d00m00s	In Place	Active	No					
Current Condition:	Good Condition - No major									
SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No					
Current Condition:	Pending - A SWPPP Sign v	will be reinstalled when	construction resumes on the	ne site.						
Certification Statement: I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information										
submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible										
for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and										
	complete. I am aware that there are significant penalties for submitting false information including the possibility of fines									
	and imprisonment for know	ing violations.								
	G/ N/C, -				Coto Sur					
Inspector Signature:	Sm Magin			Reviewed By:	and and					