E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager

Engineering Answers

Environmental Services Dept.		E&A - P1999	9.175.042			
Inspector: Shaun McGuire					Stage	
		Va	al Vista		3	
		NER101066				
Project Name:						
For Week Ending:		11/11/2023				
Project Location:	1	108th & Giles Road - Papillion, NE (Sarpy County)				
Grading:	1	00%				
Sanitary Sewer:		00%				
Storm Sewer:		00%				
Paving:		00%				
Seeding:		00%				
Utilities:		00%				
Overall Development:		68%				
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Inspection Time	Storm Event Duration	
	Amount in tentins	Date Inspected	Weather Conditions	Inspection nine	Week 1	
Sunday:	0.01"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.01"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
Sunday:	0.00"				Week 2	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.02"					
Thursday	0.00"					
Friday	0.08"					
Saturday	0.00"					
					Week 3	
Sunday:	0.00"					
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"				Week 4	
Sunday:	0.00"				Week 4	
Monday:	0.00"					
Tuesday:	0.00"					
Wednesday:	0.00"	11/8/2023	Sunny 66/41	9:35 AM		
Thursday:	0.00"					
Friday:	0.00"					
Saturday:	0.00"					
Sunday:	N/A				Week 5	
Monday	N/A N/A					
Tuesday	N/A					
Wednesday	N/A					
Thursday	N/A					
Friday	N/A					
Saturday	N/A					
	None					
Complaints:						
Complaints:						
Construction Sequencing:						
Which portion(s) (i.e. drainage basins)	of the site have had a temporary of	or permanent cessation of	f grading, earthwork, or ground d	isturbance in the last 14	days?	

Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.									
As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.									
Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :									
Entire site; residential site grading completed and site seeded prior to 2005, north commercial property grading completed and site seeded Summer 2005, and south commercial property grading completed and site seeded Summer 2006.									
As of inspection on 3/25/09 grading was active on lot 241. As of inspection on 4/7/09 grading was completed on this section of lot 241.									
What temporary or permanent stabilization measures listed in this section are being implemented?									
Paving, dense vegetation and landscaping installed prior to 2005. Paving commercial property (7/2007)									
Checklist Questions:									
Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?									
Yes									
Create Corrective Action?									
N/A									
Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measures are adequate or needed to prevent erosion.									
Yes									
Create Corrective Action?									
N/A									
Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?									
Yes									
Create Corrective Action?									
N/A									
Are construction entrances and adjacer	nt streets heing maintained ac	lequately?							
Are construction entrances and adjacent streets being maintained adequately? Yes									
Create Corrective Action?									
N/A									
Is dust associated with the construction Yes	activity adequately controlle	d on the site?							
Create Corrective Action?									
N/A									
Comments:									
Comments:									
Site is inactive as of the last inspection									
Findings / Corrective Actions (Date)									
Findings / Corrective Actions (Date) 1.) No maintenance is needed at this t									
	inte.								
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance				
	71	N41d00m00s							
SB 7	Sediment Basin	W96d00m00s	In Place	Active	No				
Current Condition:	Good Condition - 36% full -		ce completed 5/2007 Com	mercial Seeding.					
STR Current Condition	Street Cleaning Good Condition - No major	N41d00m00s W96d00m00s	In Place	Active	No				
Current Condition: SWPPP Sign	Sign	S. 108th Street	11/7/2018	Pending	No				
Current Condition:	Pending - A SWPPP Sign v								
	Jan								
Certification Statement: I certify, under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information									
submitted. Based on my inquiry of the person or persons who manage the system or those persons directly responsible for									
	gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information including the possibility of fines								
	complete. I am aware that t and imprisonment for know	0 1	alties for submitting false i	nformation including	the possibility of fines				
	Som Mayin				But Sul				
Inspector Signature:				Reviewed By:					