	E&A - 20	01.059.000		
Inspector:John Ciaccio				Stage
Project Name:	W	alnut Creek Hills	·	3
For Week Ending:				
One dieses				
Grading: Sanitary Sewer:	100			
Storm Sewer:	100			
Paving:	100			
Seeding:	100	%		
Utilities:	100			
Overall Development:	85	%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected		Week
Sunday:	0.00"			Week 1
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			Week 2
Sunday:	0.01"			
Monday	0.07"			
Tuesday	0.00"			
Wednesday	0.01"			
Thursday	0.00"	03/20/08		
Friday	0.00"	+	-	
Saturday	0.00			Week 3
Sunday:	0.00"			Week o
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday Saturday	0.02" 0.00"	+		
Jacul day	0.00			Week 4 / 5
Sunday:	0.00"; 0.00"			
Monday	1.28 "; 0.00"	3/31/2008; None		
Tuesday	0.00"; 0.00"			
Wednesday	0.00"; 0.01 "	N 4/40/00		
Thursday	0.52"; 1.00"	None; 4/10/08		
Friday Saturday	0.00"; 0.07 " 0.00"; 0.00"	4/4/2008; 4/11/08 4/5/2008; None		
Jacul day	10.00 , 0.00	T/J/ZUUU, NUITE	I .	l
Complaints:	None			
	1			
Construction Sequencing:				
Which portion(s) (i.e. drainage basins) of 14 days?		permanent cessation of grad	ing, earthwork, or ground d	listurbance in the last
Entire site; grading completed and	site seeded prior to 2005.			
Which portion(s) (i.e. drainage basins) of	the site do not have grading, ear	hwork, or ground disturbance	e scheduled in the next 14	days?:
Entire site; grading completed and	site seeded prior to 2005.			
What to make the second	a annual Baga (Control of the Control of the Contro	and below levels over 10		
Paying dones vegetation and lands				
Paving, dense vegetation and lands	scaping installed prior to 200	υ.		
Comments:				
Comments:				
Home construction is minimal on si				
Findings / Corrective Actions (Da				
Findings / Corrective Actions (Da 1) No problems at the time of inspe	•			

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance Scheduled
		N41d00m00s			
CE 1	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Entrance paved.				
		N41d00m00s			
CE 2	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Entrance paved.				

Description of Maintenance/Activity:
Repairs Needed/Planned:

tor Signature:	In Ciario		Reviewed By:	Zodnany K. Jil	k		
	Signs of track off present in Tim Moore cleaned streets						
Current Condition:	Good Condition						
STR	Streets	N41d00m00s W96d00m00s	In Place	Active	Ye		
Current Condition:	Removed	1		1			
SF3	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed; area vegetated.			1			
SF 2	Silt Fence	W96d00m00s		Active			
		N41d00m00s					
Current Condition:	Removed; area vegetated.						
SF 1	Silt Fence	N41d00m00s W96d00m00s		Active			
Current Condition:	Removed	N/44-10000-					
SB 5	Sediment Basin	W96d00m00s		Removed			
	<u> </u>	N41d00m00s	•				
Current Condition:	Good Condition - 30% Full						
SB 4	Sediment Basin	N41d00m00s W96d00m00s	In Place	Active	No		
Current Condition:	Removed December 2005		o drainage area dev	/elopment.			
SB 3	Sediment Basin	W96d00m00s		Removed			
		N41d00m00s					
Current Condition:	Removed						
SB 2	Sediment Basin	W96d00m00s		Removed			
Current Condition.	Good Condition - 30 % 1 dil	N41d00m00s					
Current Condition:	Good Condition - 30% Full		III Flace	Active	INC		
SB 1	Sediment Basin	W96d00m00s	In Place	Active	No		