E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC Environmental Services Dept. Manager E & A CONSULTING GROUP, INC.

ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES

Environmental Services Dept.	Manager	ENG	INEERING • PLANNING • ENVIRONME	ENTAL & FIELD SERVICES		
	E&	A - P2001.059.0	00			
Inspector: Alex Emerson						
		Walnut Creek Hills				
Project Name:		NER110521 9/13/2014				
For Week Ending:						
Project Location:	96th and	96th and Gold Coast Road- Papillion, NE (Sarpy County)				
-				•		
Grading:	1009					
Sanitary Sewer:	1009					
Storm Sewer:	1009					
Paving:	1009					
Seeding:	1009					
Utilities:	1009					
Overall Development:	859	%				
RAIN FALL AMOUNTS	Amount in inches	Date inspected	Weather Conditions			
				Week 1		
Sunday:	0.23"					
Monday	0.03"					
Tuesday	0.02"					
Wednesday	0.00"					
Thursday	0.00"					
Friday	0.00"					
Saturday	0.00"					
				Week 2		
Sunday:	0.00"					
Monday	0.04"					
Tuesday	0.00"					
Wednesday	0.00"	08/20/14	92/77 Sunny			
Thursday	0.04"					
Friday	0.26"					
Saturday	1.53"	8/23/2014	91/70 Sunny			
				Week 3		
Sunday:	0.00"					
Monday	0.00"					
Tuesday	1.36"					
Wednesday	1.58"	00/00/4 4	00/70 01			
Thursday	1.92"	08/28/14	82/70 Cloudy			
Friday	0.29"	+				
Saturday	0.00"			Week 4		
Sunday:	0.23"			vveek 4		
Monday Monday	0.00"	+				
Tuesday	0.00"	+				
Wednesday	0.00"	+				
Thursday	0.00"					
Friday	0.16"		+			
Saturday	0.00"	+	+			
				Week 5		
Sunday:	0.00"			Hock o		
Monday	0.03"					
Tuesday	1.26"					
Wednesday	0.00"	09/10/14	78/67 Cloudy			
Thursday	0.05"	30/10/17	70/07 Cloudy			
Friday	0.45"	09/12/14	53/42 Cloudy			
Saturday	0.00"	00/12/17	00,42 010ddy			

Complaints:	Inone						
Construction Sequencing:				<u> </u>			
Which portion(s) (i.e. drainage basins) of the	site have had a temporary or perr	manent cessation of grading	g, earthwork, or ground dis	sturbance in the last 1	4 days?		
Entire site; grading completed and site	e seeded prior to 2005.						
Which portion(s) (i.e. drainage basins) of the		ork, or ground disturbance s	scheduled in the next 14 da	ays?:			
Entire site; grading completed and site	e seeded prior to 2005.						
Miles (see a		h - l l l					
What temporary or permanent stabilization n		being implemented?					
Paving, dense vegetation and landsca	aping installed phor to 2005.						
Comments:							
Comments: Site is currently idle.							
Findings / Corrective Actions (Date							
Findings / Corrective Actions (Date) 1) No required maintenance in the BM							
			Projected Install		Maintenance		
Unique Name	Туре	Location	Date	Status	Scheduled		
CF 4	Construction Entrance	N41d00m00s		Domovod			
CE 1 Current Condition:	Construction Entrance Entrance paved.	W96d00m00s		Removed			
Current Condition.	Littiance paved.	N41d00m00s		1			
CE 2	Construction Entrance	W96d00m00s		Removed			
Current Condition:	Entrance paved.						
00.4	0 "	N41d00m00s	. 5.				
SB 1 Current Condition:	Sediment Basin Good Condition - 41% Full	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - 41% Full	N41d00m00s		1			
SB 2	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed		•		4		
		N41d00m00s					
SB 3	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed December 2005 by McArdle Grading due to drainage area development. N41d00m00s						
SB 4	Sediment Basin	W96d00m00s		Removed			
Current Condition:	This is a Permanent Basin/Pond that is under the supervision of the City of Papillion, therefore we are						
	removing it from the report as of inspection on 2/18/13.						
		N41d00m00s					
SB 5	Sediment Basin	W96d00m00s		Removed			
Current Condition:	Removed	N41d00m00s	T	Π	Т		
SF 1	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed; area vegetated.	***************************************			.1		
		N41d00m00s					
SF 2	Silt Fence	W96d00m00s		Removed			
Current Condition:	Removed; area vegetated.	N144 d00 m 00 m	Τ	Т	T		
SF 3	Silt Fence	N41d00m00s W96d00m00s		Removed			
Current Condition:	Removed	***************************************	!	1101110400	1		
		N41d00m00s					
STR	Streets	W96d00m00s	In Place	Active	No		
Current Condition:	Good Condition - No major s		0/40/2222	A - + '	T N		
SWPPP Sign Current Condition:	Signs Good Condition	3 Signs	8/19/2008	Active	No		
Current Condition:	-90th and Fenwick, 90th and	Gold Coast, 96th and	Gold Coast				

25

Zachany L. Gilek

Inspector Signature:

Zachany K. Jilde Reviewed By: