E & A Consulting Group, Inc. 330 North 117th Street Omaha, NE 68154-2509 tel 402.895.4700 fax 402.895.3599 www.eacg.com

Saturday

N/A



Zachary A. Jilek, CPESC, CISEC

E & A CONSULTING GROUP, INC.

## **Environmental Services Dept. Manager** ENGINEERING • PLANNING • ENVIRONMENTAL & FIELD SERVICES E&A - P2001.059.000 Stage Inspector: Alex Emerson **Walnut Creek Hills** NER110521 Project Name: 10/11/2014 For Week Ending: 96th and Gold Coast Road- Papillion, NE (Sarpy County) Project Location: 68046 Grading: 100% Sanitary Sewer: 100% 100% Storm Sewer: Paving: 100% Seeding: 100% Utilities: 100% Overall Development: 85% Amount in inches RAIN FALL AMOUNTS Date inspected Weather Conditions Week 1 Sunday: 0.00" Monday 0.00'Tuesday 0.00 Wednesday 0.00' Thursday 0.00" Friday 0.00" Saturday 0.12" Week 2 Sunday: 0.00" Monday 0.00" 0.05" Tuesday Wednesday 0.00 Thursday 0.00 Friday 0.00' Saturday 0.00" Week 0.00" Sunday: Monday 0.00" Tuesday 1.58" 10/01/14 Wednesday 1.94" 75/61 Cloudy 0.06" Thursday Friday 0.00' Saturday 0.00" Week 4 0.00" Sunday: Monday 0.00 Tuesday 0.00' Wednesday 0.00' Thursday 0.00' Friday 0.00" Saturday 0.00" Week ! Sunday: N/A N/A Monday N/A N/A N/A Tuesday N/A N/A N/A Wednesday N/A N/A N/A Thursday N/A N/A N/A N/A N/A N/A Friday

N/A

N/A

Complaints:	INone				
Construction Sequencing:				l	1
Which portion(s) (i.e. drainage basins) of the	e site have had a temporary or peri	manent cessation of grading	g, earthwork, or ground dis	sturbance in the last 1	4 days?
Entire site; grading completed and site	e seeded prior to 2005.				
Which portion(s) (i.e. drainage basins) of the		ork, or ground disturbance s	scheduled in the next 14 d	ays?:	
Entire site; grading completed and site	e seeded prior to 2005.				
Milest terror and the West terror	Paradia dia anti-	t - la a l			
What temporary or permanent stabilization r		being implemented?			
Paving, dense vegetation and landsca	aping installed phor to 2005.				
Comments:					
Comments: Site is currently idle.					
Findings / Corrective Actions (Date					
Findings / Corrective Actions (Date 1) No required maintenance in the BN	•				
			Projected Install		Maintenance
Unique Name	Туре	Location	Date	Status	Scheduled
OF 4	Construction Entrance	N41d00m00s		Damayad	
CE 1 Current Condition:	Construction Entrance Entrance paved.	W96d00m00s		Removed	1
Current Condition.	Littiance paveu.	N41d00m00s			
CE 2	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Entrance paved.			•	•
		N41d00m00s			
SB 1	Sediment Basin	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - 41% Full	N41d00m00s	T	I	I
SB 2	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed	1100000111000			
		N41d00m00s			
SB 3	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed December 2005 b		to drainage area deve	elopment.	1
SB 4	Sediment Basin	N41d00m00s W96d00m00s		Removed	
Current Condition:			Lunervision of the City o		re we are
Gurrom Gorialioni	This is a Permanent Basin/Pond that is under the supervision of the City of Papillion, therefore we are removing it from the report as of inspection on 2/18/13.				
	·	N41d00m00s			
SB 5	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed	1144 100 00	T	1	
SF 1	Silt Fence	N41d00m00s W96d00m00s		Romovad	
Current Condition:	Removed; area vegetated.	vv 96d00moos		Removed	
Current Condition.	rtemoved, area vegetated.	N41d00m00s			
SF 2	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed; area vegetated.				
05.0	011. 5	N41d00m00s			
SF 3	Silt Fence Removed	W96d00m00s		Removed	
Current Condition:	IVEHIOVEA	N41d00m00s			
STR	Streets	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition - No major s				•
SWPPP Sign	Signs	3 Signs	8/19/2008	Active	No
Current Condition:	Good Condition				
	-90th and Fenwick, 90th and	I Gold Coast, 96th and	Gold Coast		

25

Zachany L. Gilek

Inspector Signature:

Zachany K. Jilde Reviewed By: