	E&A - P20	003.019.000			
Inspector: John Ciaccio		mmit Ridge	Stage		
Project Name:		3			
For Week Ending:	'	7/12/2008			
Grading:	100				
Sanitary Sewer:	100				
Storm Sewer:	100				
Paving:	100				
Seeding:	100				
Jtilities:	100				
Overall Development:	97	%			
RAIN FALL AMOUNTS	Amount in inches	Date inspected			
			Wee		
Sunday:	0.12"				
Monday	0.00"				
Гuesday	0.00"				
Wednesday	0.00"				
Thursday	1.19"				
Friday	0.08"	06/20/08			
Saturday	0.19"	06/21/08			
			Wee		
Sunday:	0.00"				
Monday	0.00"				
Tuesday	1.07"				
Vednesday	0.00"	6/25/08			
Thursday Thursday	0.48"				
Friday	0.57"	6/27/08			
Saturday	0.02"	6/28/08			
		5, 25, 35	Wee		
Sunday:	0.00"				
Monday	0.00"	1			
Tuesday	0.00"				
Wednesday	0.43"	07/02/08			
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
,			Wee		
Sunday:	0.01"				
Monday	0.18"				
Tuesday	0.19"	07/08/08			
Vednesday	0.00"	07/09/08			
Thursday	0.00"				
riday	0.00"				
Saturday	0.07"				
Complaints:	None				
Construction Sequencing	g:				
		nporary or permanent cessation of gra	ading, earthwork, or grou		
Construction Sequencing Which portion(s) (i.e. drainage		nporary or permanent cessation of gra	ading, earthwork, d		

disturbance in the last 14 days?

Entire site, grading completed and site seeded prior to 2005.

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days? :

Entire site, grading completed and site seeded prior to 2005.

What temporary or permanent stabilization measures listed in this section are being implemented?

Paving and dense vegetation

## Comments:

## Comments:

Home construction continues as the main activity on site at this time. Site has good vegetative cover.

## Findings / Corrective Actions (Date):

## Findings / Corrective Actions (Date):

1) No major problems at time of inspection.

			Projected		Maintenance
Unique Name	Туре	Location	Install Date	Status	Scheduled
a= .	<u> </u>	N41d00m00s			
CE 1	Construction Entrance	W96d00m00s		Removed	
Current Condition:	Paved Entrance.	N44 d00 == 00 =			
CE 2	Construction Entrance	N41d00m00s W96d00m00s		Removed	
Current Condition:	Paved Entrance.	W9600011100S		Removed	
Current Condition.	Faved Elitiance.	N41d00m00s			
SB A	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed - Area seeded 08		<u> </u>	rtomovou	
		N41d00m00s			
SB B	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed May 2006				
		N41d00m00s			
SB C	Sediment Basin	W96d00m00s		Removed	
Current Condition:	Removed				
		N41d00m00s			
SF 1	Silt Fence	W96d00m00s	In Place	Active	No
Current Condition:	Good Condition				
SF 2	Silt Fence	N41d00m00s W96d00m00s		Domovod	
Current Condition:				Removed	
Current Condition:	Removed due to lot development N41d00m00s				
SF 3	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed Removed				
Curront Condition		N41d00m00s			
SF 4	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed		•		•
		N41d00m00s			
SF 5	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed				
	A =	N41d00m00s		_	
SF 6	Silt Fence	W96d00m00s		Removed	
Current Condition:	Removed				
CE 7	Silt Fence	N41d00m00s W96d00m00s		Domovod	
SF 7 Current Condition:	Removed	พพรดนบบทาบบร		Removed	
Current Condition:	Removed				

SF 8	Silt Fence	N41d00m00s W96d00m00s	Removed
Current Condition:	Removed 7/2007.		
Inspector's Signature:	John Ciario		Reviewed By: Zachary K. Jild
	/	<u> </u>	