Inspector:John Ciaccio	Lun	2001.059.000		Stage
Project Name:		Walnut Creek Hi	lls	3
For Week Ending:		1/12/2008		
TO WEEK Ending.	I	1712/2000		L
Grading:		00%		
Sanitary Sewer:		00%		
Storm Sewer:		00%		
Paving:		00%		
Seeding: Utilities:		00% 00%		
Overall Development:		85%		
RAIN FALL AMOUNTS	Amount in inches	Date inspected		
				Week
Sunday:	0.00"			
Monday Tuesday	0.20"			
Tuesday Wednesday	0.21" 0.00"		_	
wednesday Thursday	0.00"			
Friday	0.04"	12/14/08		+
Friday Saturday	0.10"	12/14/00		
Jacuruay	0.10			Week
Sunday:	0.00"			vveek
Monday	0.00"		+	+
Tuesday	0.00"			
Wednesday	0.00"		+	+
Thursday	0.00"			
Friday	0.00"			
Saturday	0.00"			
outui uuy	0.00			Week
Sunday:	0.00"			Week
Monday	0.00"			
Tuesday	0.00"			
Wednesday	0.00"			
Thursday	0.00"			
Friday	0.01"	12/28/07		
Saturday	0.00"			
				Week 4 /
Sunday:	0.00"; 0.00"			
Monday	0.00"; 0.03"			
Tuesday	0.00"; 0.00"			
Wednesday	0.00"; 0.00"			
Thursday	0.00" ; 0.01 "			
Friday	0.00"; 0.00"			
Saturday	0.00"; 0.00"			
Complaints:	None			
Complaints.				
Construction Sequencing:				
Which portion(s) (i.e. drainage basir	ns) of the site have had a tempora	ry or permanent cessation o	of grading, earthwork, or o	round disturbance in th
last 14 days?				
Entire site; grading completed a	and site seeded prior to 2005.			
Which portion(s) (i.e. drainage basir	ns) of the site do not have grading	, earthwork, or ground distu	Irbance scheduled in the I	next 14 days? :
Entire site; grading completed a	and site seeded prior to 2005.			
Albet temperature	limiting management that district the	ation are being bounded.		
What temporary or permanent stabil			ar	
Paving, dense vegetation and la				
Paving, dense vegetation and la				
Comments:				
Comments:	noite			
Comments: Comments: Home construction is minimal or				
Comments:	(Date):			

	Unique Name	Туре	Location	Projected Install Date	Status		Description of Maintenance/Activity:
	CE 1	Construction Entrance	N41d00m00s W96d00m00s		Removed		Repairs Needed/Planned:
	Current Condition:	Entrance paved.	W30d00iii003		Removed	1	Repairs Needed/Flaimed.
			N41d00m00s				1
	CE 2	Construction Entrance	W96d00m00s		Removed		
C	Current Condition:	Entrance paved.					
			N41d00m00s				
	SB 1	Sediment Basin	W96d00m00s	In Place	Active	No	
C	Current Condition:	Good Condition - 30% Full					
	SB 2	Sediment Basin	N41d00m00s W96d00m00s		Removed		

SB 3	Current Condition:	Removed	1144 100 00	1	1	
Current Condition: Removed December 2005 by McArdle Grading due to drainage area development. SB 4 Sediment Basin N41d00m00s W96d00m00s In Place Active No Current Condition: Good Condition - 30% Full - Permanent Basin/Pond N41d00m00s W96d00m00s Removed SB 5 Sediment Basin W96d00m00s W96d00m00s Removed Current Condition: Removed N41d00m00s W96d00m00s Active Current Condition: Removed; area vegetated. N41d00m00s W96d00m00s Active Current Condition: Removed; area vegetated. N41d00m00s W96d00m00s Removed Current Condition: Removed; area vegetated. N41d00m00s W96d00m00s Removed Current Condition: Removed N41d00m00s W96d00m00s Removed Current Condition: Removed N41d00m00s W96d00m00s Removed	SD 3	Sodiment Basin	N41d00m00s		Pomovod	
SB 4				to drainage area day		
SB 4 Sediment Basin W96d00m00s In Place Active No Current Condition: Good Condition - 30% Full - Permanent Basin/Pond N41d00m00s Removed SB 5 Sediment Basin W96d00m00s Removed Current Condition: Removed N41d00m00s Active SF 1 Silt Fence W96d00m00s Active Current Condition: Removed; area vegetated. N41d00m00s Active SF 2 Silt Fence W96d00m00s Active Current Condition: Removed; area vegetated. N41d00m00s Removed SF 3 Silt Fence W96d00m00s Removed Current Condition: Removed N41d00m00s Removed STR Streets W96d00m00s In Place Active No	Current Condition.	Removed December 2005		lo uramage area dev	reiopment.	
Current Condition: Good Condition - 30% Full - Permanent Basin/Pond SB 5 Sediment Basin N41d00m00s W96d00m00s Removed Current Condition: Removed N41d00m00s W96d00m00s Active SF 1 Silt Fence N41d00m00s W96d00m00s Active Current Condition: Removed; area vegetated. N41d00m00s W96d00m00s Active Current Condition: Removed; area vegetated. N41d00m00s W96d00m00s Removed SF 3 Silt Fence W96d00m00s Removed Current Condition: Removed STR Streets N41d00m00s W96d00m00s In Place Active No	SR /	Sediment Basin		In Place	Active	No
N41d00m00s					Active	INU
SB 5 Sediment Basin W96d00m00s Removed Current Condition: Removed SF 1 Silt Fence W96d00m00s Active Current Condition: Removed; area vegetated. SF 2 Silt Fence W96d00m00s Active Current Condition: Removed; area vegetated. SF 3 Silt Fence W96d00m00s Removed Current Condition: Removed STR Streets N41d00m00s In Place Active No	Current Condition.	Good Condition - 30 % Full		1		
Current Condition: Removed SF 1 Silt Fence W96d00m00s Active Current Condition: Removed; area vegetated. N41d00m00s Active SF 2 Silt Fence W96d00m00s Active Current Condition: Removed; area vegetated. SF 3 Silt Fence W96d00m00s Removed Current Condition: Removed STR Streets W96d00m00s In Place Active	SR 5	Sediment Basin			Removed	
SF 1			***30000111003	1	rtemoved	
SF 1 Silt Fence W96d00m00s Active Current Condition: Removed; area vegetated. SF 2 Silt Fence W96d00m00s Active Current Condition: Removed; area vegetated. SF 3 Silt Fence W96d00m00s Removed Current Condition: Removed STR Streets W96d00m00s In Place Active No	Current Condition.	Removed	N41d00m00s			
Current Condition: Removed; area vegetated. N41d00m00s W96d00m00s Active Current Condition: Removed; area vegetated. N41d00m00s W96d00m00s Removed SF 3 Silt Fence W96d00m00s Removed Current Condition: Removed STR Streets W96d00m00s In Place Active No	SF 1	Silt Fence			Active	
N41d00m00s					1	
Current Condition: Removed; area vegetated. SF 3 Silt Fence N41d00m00s Removed Current Condition: Removed STR Streets N41d00m00s In Place Active No		<u> </u>				
SF 3 Silt Fence N41d00m00s W96d00m00s Removed Current Condition: Removed STR Streets N41d00m00s W96d00m00s In Place Active No	SF 2	Silt Fence	W96d00m00s		Active	
SF 3 Silt Fence W96d00m00s Removed Current Condition: Removed STR N41d00m00s In Place Active No	Current Condition:	Removed; area vegetated		•		
Current Condition: Removed STR N41d00m00s W96d00m00s In Place Active No			N41d00m00s			
N41d00m00s STR Streets W96d00m00s In Place Active No	SF 3	Silt Fence	W96d00m00s		Removed	
STR Streets W96d00m00s In Place Active No	Current Condition:	Removed	•	•		
	STR			In Place	Active	No
Current Condition: Good Condition - No major signs of track-off.	Current Condition:	Good Condition - No majo	r signs of track-off.			
octor Signature: John Ciacio Reviewed By: Zachany k. Jihk		/ / / - ~			Today & Al	k
rector Signature: John Crause Reviewed By: Zachwy K. Jihn	tor Signature:	in Ciacie		Reviewed By:	23000 C. yo	