E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC

Enaineerina Answers

Environmental Services Dept.		anager Engineering				
		E&A- P2021.00	55.002			
Inspector: Joe Manning						
		Westridge Estates CSW-202106214				
Project Name:						
For Week Ending:		68073				
Project Location:	Highway	3/25/2023 Highway 77 West of Eagle Drive - Yutan, NE (Saunders County)				
Troject Location.	Inghway	77 West of Lagic Bit	ve - ratan, NE (Gaanae	13 County)		
Grading:	99%					
Sanitary Sewer:	0%					
Storm Sewer:	0%					
Paving:	95%					
Seeding:	25%					
Utilities:	45%					
Overall Development:	10%					
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	Storm Event Duration	
RAIN I ALL AMOUNTS	7 thount in tenths	Date inspected	Weather Conditions	Time	Week	
Sunday:	0.00"				Week	
Monday	0.00"					
Tuesday	0.00"					
Wednesday	0.00"					
Thursday Thursday	0.01"	3/23/2023	Cloudy 42	2:35 PM		
Friday	0.00"					
Saturday	0.00"					
Complaints:	None					
0						
Construction Sequencing:						
Which portion(s) (i.e. drainage basin	s) of the site have had a tempora	ary or permanent cessation	on of grading, earthwork, or	ground disturbance in th	e last 14 days?	
Which portion(s) (i.e. drainage basin		ary or permanent cessation	on of grading, earthwork, or	ground disturbance in th	e last 14 days?	
Which portion(s) (i.e. drainage basin Stripping and grading began (5/	/17/2022).				e last 14 days?	
	/17/2022). is) of the site do not have grading				e last 14 days?	
Which portion(s) (i.e. drainage basin Stripping and grading began (5/ Which portion(s) (i.e. drainage basin	/17/2022). is) of the site do not have grading /17/2022).	g, earthwork, or ground c	isturbance scheduled in the		e last 14 days?	
Which portion(s) (i.e. drainage basin Stripping and grading began (5/ Which portion(s) (i.e. drainage basin Stripping and grading began (5/	/17/2022). (s) of the site do not have grading (17/2022). (ization measures listed in this se	g, earthwork, or ground o	isturbance scheduled in the	next 14 days?		
Which portion(s) (i.e. drainage basin Stripping and grading began (5/Which portion(s) (i.e. drainage basin Stripping and grading began (5/What temporary or permanent stabili Existing vegetation (5/17/2022). Checklist Questions:	(17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022).	g, earthwork, or ground of cection are being implement onstruction entrance (isturbance scheduled in the nted? 9/14/2022). Seeding alor	next 14 days? ng ROWs (11/16/202	2).	
Which portion(s) (i.e. drainage basin Stripping and grading began (5/Which portion(s) (i.e. drainage basin Stripping and grading began (5/What temporary or permanent stabili Existing vegetation (5/17/2022). Checklist Questions: Are receiving waters adjacent	(17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022).	g, earthwork, or ground of cection are being implement onstruction entrance (isturbance scheduled in the nted? 9/14/2022). Seeding alor	next 14 days? ng ROWs (11/16/202	2).	
Which portion(s) (i.e. drainage basin Stripping and grading began (5/ Which portion(s) (i.e. drainage basin Stripping and grading began (5/ What temporary or permanent stabili Existing vegetation (5/17/2022). Checklist Questions: Are receiving waters adjacent construction activity?	(17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022).	g, earthwork, or ground of cection are being implement onstruction entrance (isturbance scheduled in the nted? 9/14/2022). Seeding alor	next 14 days? ng ROWs (11/16/202	2).	
Which portion(s) (i.e. drainage basin Stripping and grading began (5/ Which portion(s) (i.e. drainage basin Stripping and grading began (5/ What temporary or permanent stabili Existing vegetation (5/17/2022). Checklist Questions:	(17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022).	g, earthwork, or ground of cection are being implement onstruction entrance (isturbance scheduled in the nted? 9/14/2022). Seeding alor	next 14 days? ng ROWs (11/16/202	2).	
Which portion(s) (i.e. drainage basin Stripping and grading began (5/ Which portion(s) (i.e. drainage basin Stripping and grading began (5/ What temporary or permanent stabili Existing vegetation (5/17/2022). Checklist Questions: Are receiving waters adjacent construction activity? Yes	(17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022). (17/2022).	g, earthwork, or ground of cection are being implement onstruction entrance (isturbance scheduled in the nted? 9/14/2022). Seeding alor	next 14 days? ng ROWs (11/16/202	2).	

Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Nο

Create Corrective Action?

No - See Findings Section.

Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

Create Corrective Action?

N/A

Are construction entrances and adjacent streets being maintained adequately?

Nο

Create Corrective Action?

No, see BMPs section.

Is dust associated with the construction activity adequately controlled on the site?

Yes

Create Corrective Action?

NI/A

Comments:

Comments:

Site was inactive during the last inspection.

Findings / Corrective Actions (Date):

Findings / Corrective Actions (Date):

- 1.) Some maintenance is required in the BMP section.
- 2.) Inactive portions of the site should be stabilized. Summit Development was informed to complete by 8/16/22. Not done as of last inspection. Summit Development was reminded on 9/14/22, 11/9/22. Summit Development seeded the ROWs prior to the inspection on 11/16/22. E&A inspector will monitor for vegetative establishment.
- 3.) Due to street cleaning, the good condition of all BMPs, and frozen site conditions, the site will be inspected as a Winter Stage site as of 1/11/23. E&A inspector will monitor and update stage as site activity and weather conditions dictate.

Unique Name	Туре	Location	Projected Install Date	Status	Maintenance		
CE 01	Construction Entrance	H16		Removed			
Current Condition:	Removed - Summit Development paved the construction entrance prior to the inspection on 8/9/22.						
D 01	Diversion	J11 to H9	6/7/2022	Pending	No		
Current Condition:	Pending - The diversion will be installed once grading in the area requires. E&A inspector will continue to monitor.						
D 02	Diversion	J11 to I13	6/7/2022	Pending	No		
Current Condition:	Pending - The diversion will be installed once grading in the area requires. E&A inspector will continue to monitor.						
D 03	Diversion	J10 to I7		Removed			
Current Condition:	Removed - The grader installed the diversion prior to the first inspection on 5/17/22. The diversion has been removed prior to the inspection on 7/19/22 due to grading activity.						
MS 01	Material Storage	On Site	6/7/2022	Pending	No		
Current Condition:	Pending - The material storage will be installed as necessary.						
PT 01	Portable Toilet	On Site		Removed			
Current Condition:	Removed - Summit Development removed the portable toilet prior to the inspection on 9/28/22.						
SF 01	Silt Fence	H6 to G8		Removed			
Current Condition:	Removed - Due to site inactivity and straw wattle recommendations, silt fence will not be recommended as of 11/09/22.						
SF 02	Silt Fence	I13 to G16		Removed			
Current Condition:	Removed - Due to site inactivity and straw wattle recommendations, silt fence will not be recommended as of 11/09/22.						

STR	Streets	ADJ and Internal Streets	5/17/2022	Active	Yes		
Current Condition:	Fair Condition -	Streets			1.55		
	Tan Condition						
	Streets need to be cleaned.						
			ete by 2/28/23. Not done a		ion.		
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	6/7/2022	Active	No		
Current Condition:	Good Condition - E&A	Good Condition - E&A inspector installed the SWPPP sign during the inspection on 6/6/22.					
W 01	Straw Wattles	H16	9/14/2022	Active	No		
Current Condition:	Good Condition - Sur	Good Condition - Summit Development installed the straw wattles prior to the inspection on 9/14/22.					
W 02	Straw Wattles	H16	9/14/2022	Active	No		
Current Condition:	Good Condition - Summit Development installed the straw wattles prior to the inspection on 9/14/22.						
W 03 - 05	Straw Wattles	East side of internal streets	11/16/2022	Active	No		
Current Condition:	Good Condition - Summit Development installed straw wattles along the east side of the street prior to the inspection on 11/16/22.						
WO 01	Concrete Washout	On site		Removed			
Current Condition:	Removed - Summit De	Removed - Summit Development removed the concrete washout prior to the inspection on 8/9/22.					
WO 02	Concrete Washout	On site		Removed			
Current Condition:	Removed - Summit De	Removed - Summit Development removed the concrete washout prior to the inspection on 9/14/22.					
WS 01	Waste Storage Area	On site		Removed			
Current Condition:	Removed - Summit Development removed the waste storage prior to the inspection on 8/22/22.						
		<u> </u>		·			
Certification Statement:	I certify, under penalty	of law, that this docume	ent and all attachments w	ere prepared under	mv		
	direction or supervision in accordance with a system designed to assure that qualified personnel						
	properly gathered and evaluated the information submitted. Based on my inquiry of the person or						
	persons who manage the system or those persons directly responsible for gathering the information,						
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I						
	am aware that there are significant penalties for submitting false information including the possibility						
	of fines and imprisonn	of fines and imprisonment for knowing violations.					
	Che Min				Get Se		
spector Signature:				Reviewed By:	0.00		