E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700 fax 402.895.3599 www.eacg.com



Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager

Engineering Answers

	Manager				inswers		
		E&A- P2021.0	65.002		Stage		
Inspector: Joe Manning							
		Westrid	ge Estates		1		
Project Name:		CSW-202106214					
<u> </u>							
For Week Ending:	1P-b	4/8/2023 Highway 77 West of Eagle Drive - Yutan, NE (Saunders County)					
Project Location:	Highway	77 West of Eagle Dri	ve - Yutan, NE (Saunde	ers County)			
Grading:	99%	1			1		
Sanitary Sewer:	0%						
Storm Sewer:	0%						
	95%						
Paving:							
Seeding:	25%						
Utilities:	45%						
Overall Development:	10%						
RAIN FALL AMOUNTS	Amount in tenths	ln		I +.	lo		
RAIN FALL AWOUNTS	Amount in tentis	Date inspected	Weather Conditions	Time	Storm Event Duration Week		
Sunday:	0.00"				Week		
Monday	0.00"						
Tuesday	0.00"						
Wednesday	0.00"						
Thursday	0.00"	4/6/2023	Sunny 59	2:10 PM			
Friday	0.00"						
Saturday	0.00"						
Complaints:	None						
Construction Sequencing:		mry or normanont cosseti	on of grading parthwork or	ground disturbance in the	no lact 14 days 2		
		ary or permanent cessati	on of grading, earthwork, or	ground disturbance in th	ne last 14 days?		
Construction Sequencing: Which portion(s) (i.e. drainage basins	s) of the site have had a tempora		on of grading, earthwork, or	ground disturbance in th	ne last 14 days?		
Construction Sequencing:	s) of the site have had a temporal 17/2022). Utility installation	n active (3/30/2023).			ne last 14 days?		
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) Which portion(s) (i.e. drainage basins	s) of the site have had a temporal 17/2022). Utility installatio s) of the site do not have grading	n active (3/30/2023).			ne last 14 days?		
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/	s) of the site have had a temporal 17/2022). Utility installatio s) of the site do not have grading 17/2022). Utility installatio	n active (3/30/2023). g, earthwork, or ground on active (3/30/2023).	listurbance scheduled in the		ne last 14 days?		
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) Which portion(s) (i.e. drainage basins Stripping and grading began (5/2)	s) of the site have had a temporal 17/2022). Utility installations) of the site do not have grading 17/2022). Utility installations action measures listed in this second	n active (3/30/2023). g, earthwork, or ground on active (3/30/2023). ection are being impleme	disturbance scheduled in the	e next 14 days?			
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) Which portion(s) (i.e. drainage basins Stripping and grading began (5/2)	s) of the site have had a temporal 17/2022). Utility installations) of the site do not have grading 17/2022). Utility installations action measures listed in this second	n active (3/30/2023). g, earthwork, or ground on active (3/30/2023). ection are being impleme	disturbance scheduled in the	e next 14 days?			
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) What temporary or permanent stabiliz Existing vegetation (5/17/2022). Checklist Questions:	17/2022). Utility installations) of the site do not have grading 17/2022). Utility installations (17/2022). Utility installations (17/2022). Utility installations (17/2022). Eation measures listed in this seasons (17/2022). Seeding/matting near the content of the same statement (17/2022).	n active (3/30/2023). g, earthwork, or ground on active (3/30/2023). ection are being implement on the construction entrance	nted? (9/14/2022). Seeding alo	e next 14 days? ing ROWs (11/16/202	2).		
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) What temporary or permanent stabiliz Existing vegetation (5/17/2022). Checklist Questions: Are receiving waters adjacent	17/2022). Utility installations) of the site do not have grading 17/2022). Utility installations (17/2022). Utility installations (17/2022). Utility installations (17/2022). Eation measures listed in this seasons (17/2022). Seeding/matting near the content of the same statement (17/2022).	n active (3/30/2023). g, earthwork, or ground on active (3/30/2023). ection are being implement on the construction entrance	nted? (9/14/2022). Seeding alo	e next 14 days? ing ROWs (11/16/202	2).		
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/2 Which portion(s) (i.e. drainage basins Stripping and grading began (5/2 What temporary or permanent stabiliz Existing vegetation (5/17/2022). Checklist Questions: Are receiving waters adjacent construction activity?	17/2022). Utility installations) of the site do not have grading 17/2022). Utility installations (17/2022). Utility installations (17/2022). Utility installations (17/2022). Eation measures listed in this seasons (17/2022). Seeding/matting near the content of the same statement (17/2022).	n active (3/30/2023). g, earthwork, or ground on active (3/30/2023). ection are being implement on the construction entrance	nted? (9/14/2022). Seeding alo	e next 14 days? ing ROWs (11/16/202	2).		
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) Which portion(s) (i.e. drainage basins Stripping and grading began (5/2) What temporary or permanent stabiliz Existing vegetation (5/17/2022).	17/2022). Utility installations) of the site do not have grading 17/2022). Utility installations (17/2022). Utility installations (17/2022). Utility installations (17/2022). Eation measures listed in this seasons (17/2022). Seeding/matting near the content of the same statement (17/2022).	n active (3/30/2023). g, earthwork, or ground on active (3/30/2023). ection are being implement on the construction entrance	nted? (9/14/2022). Seeding alo	e next 14 days? ing ROWs (11/16/202	2).		
Construction Sequencing: Which portion(s) (i.e. drainage basins Stripping and grading began (5/2 Which portion(s) (i.e. drainage basins Stripping and grading began (5/2 What temporary or permanent stabiliz Existing vegetation (5/17/2022). Checklist Questions: Are receiving waters adjacent construction activity? Yes	17/2022). Utility installations) of the site do not have grading 17/2022). Utility installations (17/2022). Utility installations (17/2022). Utility installations (17/2022). Eation measures listed in this seasons (17/2022). Seeding/matting near the content of the same statement (17/2022).	n active (3/30/2023). g, earthwork, or ground on active (3/30/2023). ection are being implement on the construction entrance	nted? (9/14/2022). Seeding alo	e next 14 days? ing ROWs (11/16/202	2).		

Have disturbed areas been seede	d or otherwise stabiliz	ed as required? List in	active portions of the pi	oject and if stabilize	zation measure are
adequate or needed to prevent er	osion.			-	
No					
Create Corrective Action?					
No - See Findings Section.					
Are waste materials (concrete, co	nstruction material, ha	azardous, etc.) being n	nanaged properly?		
Yes					
Create Corrective Action?					
N/A					
Are construction entrances and a	djacent streets being i	maintained adequately	?		
No		•			
Create Corrective Action?					
No, see BMPs section.					
Is dust associated with the constr	uction activity adequa	ately controlled on the	site?		
Yes					
Create Corrective Action?					
N/A					
Comments:					
Comments:					
Site was inactive during the last ins	pection.				
Findings / Corrective Actions (Dat	te):				
Findings / Corrective Actions (Date					
1.) Some maintenance is required in					
2.) Inactive portions of the site should be					
monitor for vegetative establishment		evelopment seeded the	ROWS prior to the inspec	.IOII OII 11/10/22. Ex	A inspector will
Thermal for vegetative establishment	•				
	1				
Unique Name	Туре	Location	Projected Install Date	Status	Maintenance
	Construction	H16		Removed	
CE 01	Entrance				
Current Condition:	Removed - Summit Do	evelopment paved the c	onstruction entrance prior	to the inspection on	8/9/22.
D 01	Diversion	J11 to H9	6/7/2022	Pending	No
Current Condition:	Pending - The diversion	on will be installed once	grading in the area require	es. E&A inspector w	ill continue to monitor.
D 02	Diversion	J11 to I13	6/7/2022	Pending	No
Current Condition:	Pending - The diversion	on will be installed once	grading in the area require	es. E&A inspector w	ill continue to monitor.
D 03	Diversion	J10 to I7		Removed	
Current Condition:			prior to the first inspection	on 5/17/22. The div	ersion has been
	removed prior to the ir	nspection on 7/19/22 du	e to grading activity.		
MS 01	Material Storage	On Site	6/7/2022	Pending	No
Current Condition:	Pending - The materia	al storage will be installe	d as necessary.		
PT 01	Portable Toilet	On Site		Removed	
Current Condition:		evelopment removed the	portable toilet prior to the		/22.
SF 01	Silt Fence	H6 to G8		Removed	
Current Condition:		e inactivity and straw wa	ttle recommendations, silt	fence will not be re-	commended as of
	11/09/22.	1			<u> </u>
SF 02	Silt Fence	I13 to G16		Removed	
Current Condition:		e inactivity and straw wa	ttle recommendations, silt	fence will not be re-	commended as of
	11/09/22.				

ADJ and Internal Streets

5/17/2022

Active

Yes

Streets

STR

Current Condition:	Fair Condition -	Fair Condition -					
	Streets need to be cleaned.						
	Summit Development was informed to complete by 2/28/23. Not done as of the last inspection.						
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	6/7/2022	Active	No		
Current Condition:	Good Condition - E&A inspector installed the SWPPP sign during the inspection on 6/6/22.						
W 01	Straw Wattles	H16	9/14/2022	Active	No		
Current Condition:	Good Condition - Sum	Good Condition - Summit Development installed the straw wattles prior to the inspection on 9/14/22.					
W 02	Straw Wattles	H16	9/14/2022	Active	No		
Current Condition:	Good Condition - Sum	Good Condition - Summit Development installed the straw wattles prior to the inspection on 9/14/22.					
W 03 - 05	Straw Wattles	East side of internal streets	11/16/2022	Active	No		
Current Condition:	Good Condition - Sum	Good Condition - Summit Development installed straw wattles along the east side of the street prior to the					
	inspection on 11/16/22	2.					
WO 01	Concrete Washout	On site		Removed			
Current Condition:	Removed - Summit De	Removed - Summit Development removed the concrete washout prior to the inspection on 8/9/22.					
WO 02	Concrete Washout	On site		Removed			
Current Condition:	Removed - Summit De	Removed - Summit Development removed the concrete washout prior to the inspection on 9/14/22.					
WS 01	Waste Storage Area	On site		Removed			
Current Condition:	Removed - Summit Development removed the waste storage prior to the inspection on 8/22/22.						
Certification Statement:	I certify, under penalty	I certify, under penalty of law, that this document and all attachments were prepared under my					
	direction or supervision in accordance with a system designed to assure that qualified personnel						
		properly gathered and evaluated the information submitted. Based on my inquiry of the person or					
	persons who manage the system or those persons directly responsible for gathering the information,						
	the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I						
	am aware that there are significant penalties for submitting false information including the possibility						
-	of fines and imprisonn	nent for knowing violation	ns.	1			
	the Min				But Su		
nspector Signature:				Reviewed By:			