E & A Consulting Group, Inc. 10909 Mill Valley Road, Suite 100 Omaha, NE 68154 tel 402.895.4700

fax 402.895.3599 www.eacg.com

Zachary A. Jilek, CPESC, CISEC
Environmental Services Dept. Manager



**Engineering Answers** 

Environmental Services Dept.	. Manager				
		E&A- P2021.	065.002		
Inspector: Josh Ellington					Stage
		Westridge Estates			
Project Name:	CSW-202106214				3
For Week Ending:	3/9/2024				68073
Project Location:	Highwa				
		, , , , , , , , , , , , , , , , , , , ,	, ,	•,	
Grading:	99	9%			
Sanitary Sewer:	C	0%			
Storm Sewer:	C	0%			
Paving:	95	5%			
Seeding:	25	5%			
Utilities:	45	5%			
Overall Development:	10	1%			
	•	•	•		•
RAIN FALL AMOUNTS	Amount in tenths	Date inspected	Weather Conditions	Time	
					Week 1
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"				
Friday	0.00"				
Saturday	0.00"				
					Week 2
Sunday:	0.00"				
Monday:	0.00"				
Tuesday:	0.00"				
Wednesday:	0.00"				_
Thursday:	0.00"				_
Friday:	0.00"				
Saturday:	0.00"				Week 3
Sunday:	0.00"				vveek 3
Monday	0.00"				
Tuesday	0.00"				+
Wednesday	0.00"				
Thursday	0.00"				+
Friday	0.00"				1
Saturday	0.00"				
					Week 4
Sunday:	0.00"				
Monday	0.00"				
Tuesday	0.00"				
Wednesday	0.00"				
Thursday	0.00"	6/0/000	6: 1.5=	4	
Friday	0.14"	3/8/2024	Cloudy 37	1:50 PM	

Saturday	0.00"		
			Week 5
Sunday	N/A		
Monday	N/A		
Tuesday	N/A		
Wednesday	N/A		
Thursday	N/A		
Friday	N/A		
Saturday	N/A		

## **Construction Sequencing:**

Which portion(s) (i.e. drainage basins) of the site have had a temporary or permanent cessation of grading, earthwork, or ground disturbance in the last 14 days?

Stripping and grading began (5/17/2022). Utility installation active (3/30/2023). All construction ceased on site (1/10/2024).

Which portion(s) (i.e. drainage basins) of the site do not have grading, earthwork, or ground disturbance scheduled in the next 14 days?

Stripping and grading began (5/17/2022). Utility installation active (3/30/2023). All construction ceased on site (1/10/2024).

What temporary or permanent stabilization measures listed in this section are being implemented?

Existing vegetation (5/17/2022). Seeding/matting near the construction entrance (9/14/2022). Seeding along ROWs (11/16/2022).

## **Checklist Questions:**

1.) Are receiving waters adjacent to the project free of any significant signs of erosion or sediment that would be associated with the construction activity?

Yes

**Create Corrective Action?** 

N/A

2.) Have disturbed areas been seeded or otherwise stabilized as required? List inactive portions of the project and if stabilization measure are adequate or needed to prevent erosion.

Yes

**Create Corrective Action?** 

N/A

3.) Are waste materials (concrete, construction material, hazardous, etc.) being managed properly?

Yes

**Create Corrective Action?** 

N/A

4.) Are construction entrances and adjacent streets being maintained adequately?

Yes

Create Corrective Action?

N/A

5.) Is dust associated with the construction activity adequately controlled on the site?

Yes

**Create Corrective Action?** 

N/A

Comments:

Comments:

Site was inactive during the last inspection.

As of the 8/30/23 inspection; the site is well-vegetated and is inactive. This site will now be inspected as a Stage 3.

Findings / Corrective Actions (Date):

Unione Name	Turne	Lagation	Drainated Install Data	Ctatus	Maintanana
Unique Name	Type  Construction Entrance	Location H16	Projected Install Date	Status Removed	Maintenanc
CE 01					2/0/00
Current Condition:			nstruction entrance prior t		
D 01	Diversion	J11 to H9	6/7/2022	Pending	No
Current Condition:	Pending - The diversion	ા will be installed once (	grading in the area require	s. E&A inspector will	I continue to mor
D 02	Diversion	J11 to I13	6/7/2022	Pending	No
Current Condition:	Pending - The diversion	n will be installed once (	grading in the area require	s. E&A inspector will	I continue to mor
D 03	Diversion	J10 to I7		Removed	
Current Condition:	Removed - The grader	installed the diversion p	prior to the first inspection	on 5/17/22. The dive	rsion has been
	removed prior to the ins	spection on 7/19/22 due	to grading activity.		
MS 01	Material Storage	On Site	6/7/2022	Pending	No
Current Condition:	Pending - The material	storage will be installed	l as necessary.		
PT 01	Portable Toilet	On Site		Removed	
Current Condition:	Removed - Summit Dev	elopment removed the	portable toilet prior to the	inspection on 9/28/2	22.
SF 01	Silt Fence	H6 to G8		Removed	
Current Condition:	Removed - Due to site 11/09/22.	inactivity and straw wat	tle recommendations, silt t	ence will not be reco	ommended as of
SF 02	Silt Fence	I13 to G16		Removed	
Current Condition:	Removed - Due to site 11/09/22.	inactivity and straw wat	tle recommendations, silt t	ence will not be reco	ommended as of
STR	Streets	ADJ and Internal Streets	5/17/2022	Active	No
Current Condition:	Good Condition - The s	treets were cleaned pri	or to the 7/17/23 inspection	n.	
SWPPP Sign 01	SWPPP Signs	Adjacent to CE 1	6/7/2022	Active	No
Current Condition:	Good Condition - E&A i	nspector installed the S	SWPPP sign during the ins	pection on 6/6/22.	
W 01	Straw Wattles	H16	9/14/2022	Active	No
Current Condition:	Good Condition - Sumn	nit Development installe	ed the straw wattles prior to	the inspection on 9	9/14/22.
W 02	Straw Wattles	H16	9/14/2022	Active	No
Current Condition:	Good Condition - Sumn	•	ed the straw wattles prior to	the inspection on 9	9/14/22.
W 03 - 05	Straw Wattles	East side of internal streets	11/16/2022	Pending	No
Current Condition:		lopment removed the s	wattles along the east sic traw wattles prior to the 7/ stallation.		
WO 01	Concrete Washout	On site		Removed	
Current Condition:	Removed - Summit Dev	velopment removed the	concrete washout prior to	the inspection on 8/	9/22.
WO 02	Concrete Washout	On site		Removed	
Current Condition:	Removed - Summit Dev	velopment removed the	concrete washout prior to	the inspection on 9/	14/22.
WS 01	Waste Storage Area	On site		Removed	
Current Condition:		velopment removed the	waste storage prior to the	inspection on 8/22/2	22.
Certification Statement:	direction or supervision properly gathered and e persons who manage the the information submitted	in accordance with a sevaluated the information system or those persed is, to the best of my	ent and all attachments we ystem designed to assure on submitted. Based on my sons directly responsible for knowledge and belief, true or submitting false informat	that qualified persor inquiry of the perso or gathering the infor , accurate, and com	nnel n or mation, plete. I

	( fack y	1	South Ave
Inspector Signature:		Reviewed By:	